

SLN5981U.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Toyota Wish. 1798cc

Dense

JTDG620W60J006793

Rear Bumper Dented 581.10 ✓

Rear Bumper Clips. n 30(SN) ✓

Rear Bumper Side Holder x 02 ⁿ 58.4 x 2 = 116.80 ✓

Rear Bumper Impact Bracket x 02. ^{LH Dented} 68.50
68.5 x 2 = 137
58.90

Rear Bumper Reflector x 02 ^{LH} 58.9 x 2 = 117.80

Reverse Sensor Dented 280(SN). 200(SN)

Rear End Panel Outer Dented 581.40 ✓

Rear End Panel Inner Rys 199.50 +

Rear End Panel Top Garnish, Dented 253.20 ✓

Rear End Panel Sealant. ⁿ 60(SN) ✓

Tailgate Dented 1209.40 ✓

Tailgate Lock ⁿ 315.70 +

SLN59814

Tailgate Weatherstripe	At	299.10	✓
Tailgate Lower Trim Board	NP MR	485.50	X
Tailgate Lower Trim Board Clips	NP MR	30(SN)	X
Tailgate Lamp LH	could	277.60	✓
Tailgate G(S) Moulding.	2 MR	132.40	✓
Tailgate G(S) Sealant.	1 MR	60(SN)	✓
Toyota Logo.	2 MR	70.20	✓
Valve Matic Emblem.	1 MR	47.20	✓
Taillamp LH.	NP MR	395.50	X.
Floor Panel Top Board	NP MR	456.60	X
Rear LH Fender Lower Trim Board	NP MR	679.40.	X
Rear LH Fender Lower Trim Board Clips.	NP MR	30(SN)	X

SLN 5981U.

Panel Beating.

Spony Painting.

Wiring.

To. Remove reverse sensor

To remove rear camera.

To remove ~~to~~ video recorder.

To remove upholstery.

To transfer tailgate fittings.

To remove tailgate g/s

To spray tuff coat

~~1200~~ 800

~~1200~~ 800

~~500~~ 300

~~1000~~ 600

~~1000~~ 600

~~1000~~ 600

~~1500~~ 800

~~1500~~ 800

~~1800~~ 1200

~~1500~~ 600.

List: 3695.80

Wn 25%: 2771.85-

S.N: 350

Labour: 2050

total: 5271.85

4/5: 4.2k

06 Days.

4.2k