



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKW 1437R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER	DENTED / DEFORMED	1,083.30	1,083.30
1	FRONT BUMPER REINFORCEMENT	DENTED	466.80	466.80
1	FRONT BUMPER REINFORCEMENT PROTECTION	DISTORTED	87.90	87.90
1	SET FRONT BUMPER CLIPS	NECESSARY	50.00	50.00
2	FRONT BUMPER LOWER COVERS @\$29.40	MISSING	58.80	58.80
2	FRONT BUMPER SIDE RETAINERS @\$19.70	NOT NECESSARY	39.40	-
2	FRONT BUMPER FOG LAMPS @\$250.00	NOT NECESSARY	500.00	-
1	FRONT GRILLE LOGO	NECESSARY	46.50	46.50
1	FRONT GRILLE	CRACKED	610.70	610.70
1	FRONT GRILLE TOP	DENTED	351.80	351.80
1	FRONT GRILLE CHROME N/S	CRACKED	185.60	185.60
1	FRONT GRILLE CHROME O/S	NOT NECESSARY	185.60	-
1	SET FRONT GRILLE CLIPS	NECESSARY	30.00	30.00
1	BONNET	DENTED / BUCKLED	1,204.30	1,204.30
1	BONNET INNER RUBBER	NECESSARY	99.10	99.10
1	BONNET LOCK	SERVICEABLE	198.70	-
1	FRONT SUPPORT PANEL	TO REPAIR SEE LABOUR	469.70	-
1	HEADLAMP N/S	CRACKED	2,237.80	2,237.80
	LESS 20% DISCOUNT		-	-1,302.52
			7,906.00	5,210.08
<u>SPECIAL NETT ITEMS</u>				
1	FRONT BUMPER LICENCE PLATE (SN)	CRACKED	20.00	15.00
1	BOL BONNET SEALANT (SN)	NECESSARY	35.00	35.00
			55.00	50.00
<u>LABOUR</u>				
	TO CHECK WIRING.		50.00	30.00
	TO SPRAY RUST PROOFING.		50.00	30.00
	TO REFILL AIR CON GAS.	NOT NECESSARY	120.00	-

Report Ref No. CS/TP20013134/Utf3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR FOR PANEL BEATING & REPLACED PARTS. INCLUSIVE OF THE REPAIR OF FRONT SUPPORT PANEL.		680.00	500.00
	TO PUTTY & SPRAY PAINTING.		1,080.00	680.00
			1,980.00	1,240.00
GRAND TOTAL			9,941.00	6,500.08
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				5,200.00

Report Ref No. CS/TP20013134/Utf3e2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.