

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref: S0M02V6Z Date: 28th Dec 2020

Our Ref: CS3/ASM20010893/R1sf3e2-1

## M/s Axa Insurance Pte Ltd

8 Shenton Way #24-01 Axa Tower Singapore 068811 (The Motor Claims Department)

Attn: Oh Vale

Dear Sir / Madam.

## EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SMR 6655Y INSURED VEHICLE: FBK 5332C ACCIDENT DATE: 07/10/2020

We thank you for your instruction on 30/11/2020.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SMR 6655Y from M/s Impact Analysis Consultant.
- b) Singapore Accident Statement of Vehicles SMR 6655Y and FBK 5332C.
- c) Police Report of Vehicles FBK 5332C.
- d) Final Repair Bill of SMR 6655Y from M/s Triple-T Automobile.
- e) Colour damaged vehicle photographs of SMR 6655Y.

Pre-Repair Inspection Date : 20/10/2020 at M/s Garage 13 Pte Ltd, 8 Kaki Bukit Ave 4 #03-46 Premier, Singapore 415875.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number : SMR 6655Y

Make & Model : Honda Civic 1.8L A

Year of Registration : 2006

Chassis Number : JHMFD16306S208690

Engine Capacity : 1799 cc

- 2. We recommend that the repairs of the entire damage require about <u>5 (Five)</u> working days to complete.
- 3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.