

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/EGI20013137/ACF3Q2

Date: 28/01/2021

REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd. Policy No:

Claimant
Vehicle No : SMD4645M **Insured Vehicle No :** GBB8988M

Date of Loss: 27/11/2020 Nature of Claim: TP Claim No: CDMCG20001773

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No: | SMD4645M | | |
| Make & Model: | HYUNDAI ELANTRA, 1.6 AD GLS (A) | Engine No: | G4FGJU205876 |
| Reg. Date: | 21/08/2018 (Man. Year: 2018) | Chassis No: | KMHD841CMJU703816 |
| Colour: | Blue | Odometer: | 43725 km |
| Engine Capacity: | 1591 cc | | |
| Market Value/New Car Price: | N/A | | |
| Sum Insured (\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

| | | | |
|-------------------|------------|------------------|------------|
| Front Tyre Size: | 195/65R15 | Rear Tyre Size: | 195/65R15 |
| Front Left Side: | Nexen 6 mm | Rear Left Side: | Nexen 6 mm |
| Front Right Side: | Nexen 6 mm | Rear Right Side: | Nexen 6 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|---|-------------------|-------------------|-------------------|---------------|
| Parts | 6,123.44 | 4,776.80 | 1,346.64 | 21.99 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 2,180.00 | 1,640.00 | 540.00 | 24.77 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (\$) | 8,303.44 | 6,416.80 | 1,886.64 | 22.72 |
| Approved Total (Overridden) (\$) | | 5,100.00 | | |
| (S\$) | 8,303.44 | 5,100.00 | 3,203.44 | 38.58 |
| + GST 7.00/7.00% (S\$) | 581.24 | 357.00 | 224.24 | 38.58 |
| Nett Amount (S\$) | 8,884.68 | 5,457.00 | 3,427.68 | 38.58 |

INSPECTION

Date of Assignment: 30/11/2020

Date Inspected: 30/11/2020 Inspected At:

Ryder Auto Pte Ltd (HQ)
2 Kaki Bukit Ave 2, #02-19 AutoHub
@ Kaki Bukit
Singapore 417921

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

| | | |
|----------------------|--|--|
| Part Source: | MRM-SG | Version: 1.0 (Last Synchronised: 27 Jan 2021) |
| Parts: | 143 | HYUNDAI ELANTRA 1.6 AD GLS (A) (Catalogue:Merimen Singapore 1.0) |
| Labour: | Repairer's | (Price-denominated Standard List) |
| Print Code: | (Unsubmitted, no print-code for SMD4645M) | |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page | |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *. | |

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|--------------------------------------|---------------|-------------|--------------|
| 1 | 1 | | *REAR BUMPER | Deformed | 780.00 FL | *470.00 FL |
| 2 | 1 | | *REAR BUMPER ENFORCEMENT | Bent | 420.00 FL | *295.00 FL |
| 3 | 1 | | *REAR BUMPER BUZZER | Cracked | 140.00 FL | *140.00 FL |
| 4 | 1 | | *REAR BUMPER LOWER DIFFUSER | Distorted | 260.00 FL | *260.00 FL |
| 5 | 1 | | *REAR BUMPER O/S & N/S REFLECTOR | N/s Cut | 150.00 FL | *75.00 FL |
| 6 | 2 | | *REAR BUMPER O/S & N/S RETAINER | Not Necessary | 202.80 FL | *- FL |
| 7 | 1 | | *REAR BOOT COVER | Dented | 1,890.00 FL | *1,785.00 FL |
| 8 | 1 | | *REAR BOOT COVER WEATHERSTRIP | Cut | 135.00 FL | *135.00 FL |
| 9 | 1 | | *REAR BOOT COVER EMBLEM | Necessary | 106.40 FL | *45.00 FL |
| 10 | 1 | | *REAR BOOT COVER ELENTRA EMBLEM | Necessary | 79.20 FL | *48.00 FL |
| 11 | 1 | | *REAR BOOT COVER S EMBLEM | Necessary | 78.40 FL | *56.00 FL |
| 12 | 1 | | *REAR BOOT COVER LOCK (UPPER) | Damaged | 150.00 FL | *150.00 FL |
| 13 | 2 | | *REAR BOOT COVER O/S & N/S REFLECTOR | Cracked | 870.00 FL | *792.00 FL |
| 14 | 1 | | *REAR O/S & N/STAIL-LAMP | N/s Cut | 960.00 FL | *480.00 FL |
| 15 | 1 | | *REAR END PANE | Dented | 435.00 FL | *435.00 FL |
| 16 | 1 | | *REAR END PANE INNER TRIM | Deformed | 105.00 FL | *105.00 FL |
| 17 | 1 | | *REAR SPARE WHEEL BOARD COVER | Deformed | 300.00 FL | *300.00 FL |
| 18 | 1 | | *REAR N/S UNDER COVER | Torn | 90.00 FL | *90.00 FL |
| 19 | 10 | | *REAR BUMPER CLIPS | Necessary | 30.00 FS | *30.00 FS |
| 20 | 6 | | *REAR BUMPER LOWER DIFFUSER CLIPS | Necessary | 18.00 FS | *18.00 FS |
| 21 | 2 | | *REAR BUMPER REVERSE SENSOR | Damaged | 280.00 FS | *200.00 FS |
| 22 | 1 | | *REAR REG NO PLATE | Not Necessary | 45.00 FS | *- FS |
| 23 | 1 | | *REAR REG NO PLATE BRACKET | Not Necessary | 29.00 FS | *- FS |

F=Franchise part. S=SpcNett. L=ListItemDisc.

| | | |
|--|-----------------|-----------------|
| Sub Total (\$\$) | 7,553.80 | 5,909.00 |
| - List Item Discount on L Items 20.00/20.00% (\$\$) | 1,430.36 | 1,132.20 |
| Total Parts (\$\$) | 6,123.44 | 4,776.80 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------------------|---|----------|-----------------|-----------------|
| <u>Labour Items</u> | | | | |
| 1 | TO DISMANTLE,STRAIGHTEN & WELDING | New | 1,200.00 | 800.00 |
| 2 | TO SPRAY PAINTING | New | 800.00 | 700.00 |
| 3 | TO REMOVE & REPLACE REAR REVERSE SENSOR | New | 50.00 | 50.00 |
| 4 | TO CHECK WIRING | New | 50.00 | 30.00 |
| 5 | TO RE-SEAL ANTI-RUST | New | 80.00 | 60.00 |
| Gross Labour Cost (\$\$) | | | 2,180.00 | 1,640.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >