

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	SOMPO INSURAN	CE SINGAPORE PL		Ref:	CS3/SMO20013138/Uvf3e2	
	50 RAFFLES PLAC SINGAPORE LAND	CE #03-03 O TOWERSINGAPORE 048623		Date:	12/07/2021	
				Code:	SMO	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SMT 3790Z	Veh. Inspected	ł	GBF 7918B	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	CMTD2003260/IJH	Excess (\$)		0.00	
	Assign From	GRACE TEO	Assign Date		30/11/2020	
2.	Vehicle Particulars & Condition					
	Make & Model	TOYOTA HIACE (M)	c.c		2982	
	Engine No.	HIDDEN	Year of Reg.		2017	
	Chassis No.	JTFHT02P000215096	Colour		SILVER	
	Odometer	212777 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		NIL	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	195 R15	BRIDGESTONE		6 mm	
	L/H Front Tyre	195 R15	BRIDGESTONE		6 mm	
	R/H Rear Tyre	195 R15	BRIDGESTONE		6 mm	
	L/H Rear Tyre	195 R15	BRIDGESTONE		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION.					
5.	General Information					
	Accident Date	06/11/2020	Inspect Date /	Time	30/06/2021 (09:40 AM)	
	Survey held at ENG HUP SENG MOTOR					
		BLK 1 PANDAN LOOP #01-02 SINGAPORE 128219				
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$1,500-\$2,000					
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days					

Report Ref No. CS3/SMO20013138/Uvf3e2

Inspected By

CHUA KANG SENG Licensed Appraiser K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser