

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CS/AIG20013140/ESF3E2

Date: 23/12/2020

REFERENCE

Insured/Claimant:	KUEK HOCK KENG	Policy No:	1900005472		
Date of Loss:	29/11/2020	Nature of Claim:	OD	Claim No:	7842248311SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMH5763C	Engine No:	3A92UHN8065
Make & Model:	MITSUBISHI ATTRAGE, 1.2 CVT (A)	Chassis No:	MMBSTA13AKH001041
Reg. Date:	28/01/2019 (Man. Year: 2018)	Odometer:	80094 km
Colour:	Grey		
Engine Capacity:	1193 cc		
Market Value/New Car Price:	S\$54,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/55 R15	Rear Tyre Size:	195/55 R15
Front Left Side:	Bridgestone 4 mm	Rear Left Side:	Bridgestone 4 mm
Front Right Side:	Bridgestone 4 mm	Rear Right Side:	Bridgestone 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,217.00	1,335.89	881.11	39.74
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,060.00	2,260.00	800.00	26.14
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,277.00	3,595.89	1,681.11	31.86
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	4,677.00	2,995.89	1,681.11	35.94
+ GST 7.00/7.00% (S\$)	327.39	209.71	117.68	35.94
Nett Amount (S\$)	5,004.39	3,205.60	1,798.79	35.94

INSPECTION

Date of Assignment:	30/11/2020	
Date Inspected:	30/11/2020 Inspected At:	Cycle & Carriage Automotive Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	4.0 days	

Adjuster: CHEN TSUE YEE

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but

any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*C & C LOGO	Necessary	40.00 FS	*40.00 FS
2	1		*SUNDRY	Necessary	20.00 FS	*20.00 FS
3	1		*FACE, RR BUMPER	Deformed	748.00 F	*748.00 FL
4	1		*BRACKET, RR BUMPER, RH	Broken	28.00 F	*28.00 FL
5	1		*BRACKET, RR BUMPER, LH	Not Necessary	28.00 F	*- FL
6	1		*PANEL, TRUNK LID	Dented	791.00 F	*791.00 FL
7	1		*HINGE, TRUNK LID, LH	Not Necessary	203.00 F	*- FL
8	1		*HINGE, TRUNK LID, RH	Not Necessary	203.00 F	*- FL
9	1		*MARK, ATTRAGE	Necessary	21.00 F	*21.00 FL
10	1		*MARK, THREE-DIA	Necessary	69.00 F	*69.00 FL
11	1		*TRIM, RR END	Not Necessary	66.00 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	2,217.00	1,717.00
- List Item Discount on L Items 0.00/23.00% (\$)	0.00	381.11
Total Parts (\$)	2,217.00	1,335.89

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW REAR BUMPER, BOOTLID, REPAIR REAR AIRDAM, REAR END PANEL	New	1,350.00	900.00
2	REMOVE & INSTALL PARKING SENSOR	New	60.00	60.00
3	SPRAY PAINT FOR REAR AIRDAM, REAR END PANEL, REAR BUMPER BOOTLID	New	1,400.00	1,050.00
4	CHECK WIRING & ELECTRICAL SYSTEM	New	30.00	30.00
5	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
6	REMOVE & INSTALL REAR AIRDAM	New	100.00	100.00
Gross Labour Cost (\$\$)			3,060.00	2,260.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >