



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLW 6398A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER (WCP)	DEFORMED	650.00	650.00
10	FR BUMPER CLIP (WCP)	NECESSARY	30.00	30.00
1	FR BUMPER SIDE RETAINER,LH (WCP)	SERVICEABLE	26.00	-
1	FR BUMPER SIDE RETAINER,RH (WCP)	SERVICEABLE	26.00	-
1	FR BUMPER UPPER BRACKET,LH (WCP)	SERVICEABLE	30.00	-
1	FR BUMPER UPPER BRACKET,RH (WCP)	SERVICEABLE	30.00	-
1	FR BUMPER SPONGE (WCP)	SERVICEABLE	80.00	-
1	FR BUMPER REINFORCEMENT (WCP)	SERVICEABLE	250.00	-
1	FRONT GRILLE CHROME (WCP)	CRACKED	680.00	680.00
1	LOGO-FR (WCP)	CRACKED	65.00	65.00
1	LEFT HEADLAMP (WCP)	CRACKED	950.00	950.00
1	LEFT HEADLAMP CHROME MOULDING (WCP)	SERVICEABLE	40.00	-
1	RIGHT HEADLAMP (WCP)	SERVICEABLE	950.00	-
1	RIGHT HEADLAMP CHROME MOULDING (WCP)	SERVICEABLE	40.00	-
1	FRONT SUPPORT PANEL (WCP)	TO REPAIR SEE LABOUR	450.00	-
1	BONNET (WCP)	BENT	750.00	750.00
15	BONNET INSULATOR CLIP (WCP)	NECESSARY	45.00	45.00
1	BONNET LOCK (WCP)	SERVICEABLE	120.00	-
1	BONNET FR SEAL,RH (WCP)	NECESSARY	25.00	25.00
1	BONNET FR SEAL,LH (WCP)	NECESSARY	25.00	25.00
1	CTR SUPPORT BRACKET (WCP)(ADDITIONAL)	CRACKED	35.00	35.00
1	UPPER BEAM FR BUMPER (WCP)(ADDITIONAL)	BENT	70.00	70.00
1	UPPER AIR GUIDE (WCP)(ADDITIONAL)	CRACKED	35.00	35.00
1	SET SENSOR BRACKET (WCP)(ADDITIONAL)	NECESSARY	60.00	60.00
	COST PLUS 10%		546.20	342.00
			6,008.20	3,762.00
<u>SPECIAL NETT ITEMS</u>				
1	FRT NO PLATE (SN)	DEFORMED	45.00	45.00
1	RADIATOR COOLANT (SN)	NOT NECESSARY	60.00	-

Report Ref No. CS/AWA20013141/R1vf3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	AIR CON GAS & OIL (SN)	NOT NECESSARY	100.00	-
			205.00	45.00
	LABOUR			
	TO REMOVE,REPLACE,RE ALIGN:FR BUMPER,BONNET,SUPPORT PANEL AND ACCIDENT AFFECTED AREA.INCLUSIVE OF THE REPAIR OF FRONT SUPPORT PANEL.		1,200.00	500.00
	TO PUTTY,RE SPRAY PAINT:FR BUMPER,BONNET.		800.00	400.00
	TO CHECK WIRE AND FOCUS HEADLAMP.		60.00	30.00
			2,060.00	930.00
GRAND TOTAL			8,273.20	4,737.00

RECOMMENDED COST OF REPAIRS			4,737.00
LESS EXCESS			-500.00
NETT LIABILITY			4,237.00

Report Ref No. CS/AWA20013141/R1vf3e2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.