

## COMFORTDELGRO ENGINEERING PTE LTD

45 Pandan Road S (609286)

Tel: 68676919 Fax: 62626950

Appendix A

**Spare Parts**

Vehicle No. : **SLW6398A** Submit By : **Wong Chee Wei**  
 Make & Model : **PASSAT VARIANT R-LINE 2.0 TSI HUD** Year Manufacture : **2017**  
 Chassis No. : **WVWZZZ3CZHE201421** Engine No. : **CHH209768**

**OD****S/Order**

S/No	Part Description	Qty	Cost Price		Nett Price	List Price	S- Nett Price	Disposition By Surveyor
			original	OEM				
1	FRONT BUMPER <i>de /</i>	1	\$650.00					
2	FR BUMPER CLIP <i>re /</i>	10	\$30.00					
3	FR BUMPER SIDE RETAINER,LH <i>X</i>	1	\$26.00					
4	FR BUMPER SIDE RETAINER,RH <i>X</i>	1	\$26.00					
5	FR BUMPER UPPER BRACKET,LH <i>?</i>	1	\$30.00					
6	FR BUMPER UPPER BRACKET ,RH <i>?</i>	1	\$30.00					
7	FR BUMPER SPONGE <i>?</i>	1	\$80.00					
8	FR BUMPER REINFORCEMENT <i>?</i>	1	\$250.00					
9	FRONT GRILLE CHROME <i>cr /</i>	1	\$680.00					
10	LOGO - FR <i>cr /</i>	1	\$65.00					
11	LEFT HEADLAMP <i>? cr /</i>	1	\$950.00					
12	LEFT HEADLAMP CHROME MOULGING <i>?</i>	1	\$40.00					
13	RIGHT HEADLAMP <i>?</i>	1	\$950.00					
14	RIGHT HEADLAMP CHROME MOULDING <i>?</i>	1	\$40.00					
15	FRONT SUPPORT PANEL <i>?</i>	1	\$450.00					
16	BONNET <i>bt -</i>	1	\$750.00					
17	BONNET INSULATOR CLIP <i>re /</i>	15	\$45.00					
18	BONNET LOCK <i>X</i>	1	\$120.00					
19	BONNET FR SEAL,RH <i>re /</i>	1	\$25.00					
20	BONNET FR SEAL ,LH <i>re /</i>	1	\$25.00					
21	FRONT NO.PLATE <i>de /</i>	1					\$45.00	
22	RADIATOR COOLANT <i>?</i>	1					\$60.00	
23	AIR CON GAS & OIL <i>?</i>	1					\$100.00	
24		1						
25		1						
26		1						
27		1						
28		1						
29		1						
30		1						

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

45 Pandan Road S (609386)

## Appendix B

Vehicle No. : **SLW6398A**

Submit By : **Wong Chee Wei**

Make & Model : VOLKSWAGEN

Year of Manufacture : 2017

400 + 100 + 500
400
30

*Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.*