

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CS/AIG20013144/EVF3E2

Date: 24/12/2020

REFERENCE

Insured/Claimant:	LIM LI JUAN SHERILYN	Policy No:	2070140760		
Date of Loss:	27/11/2020	Nature of Claim:	OD	Claim No:	1629557858SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMV4479G		
Make & Model:	KIA CERATO, 1.6 (A)	Engine No:	G4FGKH740249
Reg. Date:	30/09/2020 (Man. Year: 2019)	Chassis No:	KNAF5416ML5064339
Colour:	Silver	Odometer:	1133 km
Engine Capacity:	1591 cc		
Market Value/New Car Price:	S\$85,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/50 R16	Rear Tyre Size:	205/50 R16
Front Left Side:	Michelin 5 mm	Rear Left Side:	Michelin 5 mm
Front Right Side:	Michelin 5 mm	Rear Right Side:	Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,783.60	2,631.20	1,152.40	30.46
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,170.00	3,920.00	1,250.00	24.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	8,953.60	6,551.20	2,402.40	26.83
+ GST 7.00/7.00% (S\$)	626.75	458.58	168.17	26.83
Nett Amount (S\$)	9,580.35	7,009.78	2,570.57	26.83

INSPECTION

Date of Assignment:	30/11/2020		
Date Inspected:	30/11/2020	Inspected At:	Cycle & Carriage KIA Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	6.0 days		

Adjuster: CHEN TSUE YEE

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*C&C EMBLEM	Necessary	40.00 FS	*40.00 FS
2	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
3	1		*PANEL ASSY-TRUNK LID	Dented	1,297.00 FL	*1,297.00 FL
4	1		*HINGE ASSY-TRUNK LID, LH	Not Necessary	97.00 FL	*- FL
5	1		*HINGE ASSY-TRUNK LID, RH	Not Necessary	97.00 FL	*- FL
6	1		*PANEL ASSY-BACK	Dented	324.00 FL	*324.00 FL
7	1		*TRIM ASSY-RR TRANSVERSE	Cut	41.00 FL	*41.00 FL
8	1		*COVER-RR BUMPER	Dented	651.00 FL	*651.00 FL
9	1		*COVER-RR BUMPER LWR (5 pcs)	Broken	1,205.00 FL	*241.00 FL
10	1		*COVER-RR BUMPER FOG LAMP, LH	Cut	19.00 FL	*19.00 FL
11	1		*LAMP ASSY-SIDE T/SIGNAL, LH	Not Necessary	181.00 FL	*- FL
12	1		*BRACKET-RR BEAM UPR MTG, LH	Not Necessary	9.00 FL	*- FL
13	1		*BRACKET-RR BEAM UPR MTG, RH	Not Necessary	9.00 FL	*- FL
14	1		*BRACKET-RR BEAM LWR, CTR	Broken	6.00 FL	*6.00 FL
15	1		*BRACKET-RR BEAM LWR MTG	Broken	6.00 FL	*6.00 FL
16	1		*BEAM-RR BUMPER	Broken	318.00 FL	*318.00 FL
17	1		*ANTENNA ASSY-SMARTKEY	Not Necessary	46.00 FL	*- FL
18	1		*STAY-RR BUMPER LH	Bent	65.00 FL	*65.00 FL
19	1		*STAY-RR BUMPER RH	Bent	65.00 FL	*65.00 FL
20	1		*BRACKET ASSY-RR BPR SIDE UPR, L	Broken	25.00 FL	*25.00 FL
21	1		*BRACKET ASSY-RR BPR SIDE UPR, R	Broken	31.00 FL	*31.00 FL
22	1		*EMBLEM-CERATO	Necessary	28.00 FL	*28.00 FL
23	1		*EMBLEM-GT LINE	Necessary	45.00 FL	*45.00 FL
24	1		*LOGO ASSY-KIA SUB	Necessary	32.00 FL	*32.00 FL
25	10		*CLIPS (SUPPLEMENTARY)	Necessary	20.00 FL	*20.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,707.00	3,274.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	923.40	642.80
Total Parts (\$\$)	3,783.60	2,631.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPLACE REAR BUMPER, BOOT, END PANEL & AFFECTED AREA. REPAIR ON SPARE TYRE PANEL	New	2,000.00	1,200.00
2	PAINT WORK ON REAR BUMPER, BOOT, END PANEL & SPARE TYRE PANEL	New	1,400.00	1,050.00
3	REMOVE & INSTALL REAR PARKING ASSIST	New	120.00	100.00
4	REMOVE & INSTALL REAR BOOT COMPARTMENT ON FACILITATE REPAIR	New	120.00	120.00
5	TO TRANSFER REAR BOOT ATTACHMENTS TO NEW PANEL	New	120.00	120.00
6	TO APPLY SEALANT ON AFFECTED AREA	New	80.00	40.00
7	PERFORM RUST PREVENTION	New	80.00	40.00
8	CHECK WIRING & CHASSIS ELECTRICAL SYSTEM	New	30.00	30.00
9	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
10	REPAIR RH REAR FENDER,& LH REAR FENDER (SUPPLEMENTARY)	New	400.00	400.00
11	RESPRAY RH REAR FENDER,& LH REAR FENDER (SUPPLEMENTARY)	New	700.00	700.00
Gross Labour Cost (\$\$)			5,170.00	3,920.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >