

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG20013146/DSF3E2

Date: 11/01/2021

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSNW00091022000

Claimant Vehicle
No : SY5883D

Insured Vehicle
No : GBK5795A

Date of Loss: 27/11/2020

Nature of Claim: TP

Claim
No: SNM20D204624/C02/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SY5883D

Make & Model: NISSAN QASHQAI, 1.2 DIG-T CVT ABS 2WD 5DR (A)

Engine No: HRA2211199A

Reg. Date: 02/12/2015 (Man. Year: 2015)

Chassis No: SJNFEAJ11U1533447

Colour: Brown

Odometer: 108683 km

Engine Capacity: 1197 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R17

Rear Tyre Size: 215/60 R17

Front Left Side: Bridgestone 5 mm

Rear Left Side: Bridgestone 5 mm

Front Right Side: Bridgestone 5 mm

Rear Right Side: Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	33,948.47	15,301.09	18,647.38	54.93
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,650.00	2,850.00	4,800.00	62.75
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	41,598.47	18,151.09	23,447.38	56.37
Approved Total (Overridden) (\$\$)		14,500.00		
(\$\$)	41,598.47	14,500.00	27,098.47	65.14
+ GST 7.00/7.00% (\$\$)	2,911.89	1,015.00	1,896.89	65.14
Nett Amount (\$\$)	44,510.36	15,515.00	28,995.36	65.14

INSPECTION

Date of Assignment: 30/11/2020

Date Inspected: 30/11/2020 Inspected At:

JWG International Pte Ltd (HQ)
Blk 10, Ang Mo Kio Ind Park 2A,, #03-08 AMK
AutoPoint
Singapore 568047

Estimated Period of Repair: 10.0 days

Adjuster: BRYAN TANI

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 11 Jan 2021)
Parts:	M1-SUV	NISSAN QASHQAI 1.2 DIG-T CVT ABS 2WD 5DR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SY5883D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*BONNET	Dented	1,261.40 FL	*961.40 FL
2	1	*BONNET INSULATOR	Bent / Crumpled	290.40 FL	*290.40 FL
3	1	*BONNET LOCK	Bent	199.80 FL	*199.80 FL
4	2	*BONNET HINGE LH / RH	Bent	156.40 FL	*156.40 FL
5	1	*BONNET STRIKER LOCK	Bent	93.20 FL	*93.20 FL
6	1	*BONNET SEAL	Serviceable	98.00 FL	*- FL
7	1	*SET BONNET STOPPERS	Serviceable	59.90 FL	*- FL
8	2	*HEAD LAMP LH / RH	OsBroken/NsCracked/MtgCracked	1,918.00 FL	*1,224.40 FL
9	2	*HEAD LAMP LOWER BRACKET LH / RH	Not Necessary	283.20 FL	*- FL
10	2	*HEAD LAMP PANEL LH / RH	No such part	418.60 FL	*- FL
11	1	*HEAD LAMP WIRE HARNESS	Serviceable	1,854.00 FL	*- FL
12	1	*FRONT BUMPER	Cut / Dented	1,014.60 FL	*717.00 FL
13	1	*FRONT BUMPER SIDE RETAINER LH / RH	O/S Broken / N/S Not Necessary	121.80 FL	*60.90 FL
14	1	*FRONT BUMPER FOG LAMP LH / RH	O/S Broken / N/S Not Necessary	843.20 FL	*421.60 FL
15	1	*FRONT BUMPER FOG LAMP GARNISH LH / RH	O/S Dislodged/N/SNotNecessary	431.00 FL	*215.50 FL
16	2	*FRONT BUMPER FOG LAMP HOLDER LH / RH	No such part	390.40 FL	*- FL
17	1	*FRONT BUMPER FOG LAMP WIRE HARNESS	Serviceable	1,838.90 FL	*- FL
18	1	*FRONT BUMPER TOW HOOK COVER	Not Necessary	40.30 FL	*- FL
19	1	*FRONT BUMPER GRILLE	Cracked / Broken	598.30 FL	*598.30 FL
20	1	*FRONT REINFORCEMENT BAR UPPER	Dented / Bent	875.40 FL	*675.40 FL
21	1	*FRONT REINFORCEMENT BAR LOWER	Not Necessary	537.70 FL	*- FL
22	1	*HORN	Cut / Broken	153.00 FL	*153.00 FL
23	1	*FRONT SUPPORT PANEL	Bent / Dented	917.50 FL	*792.50 FL
24	1	*INTER COOLER ASSY	Bent / Punctured	2,121.60 FL	*1,850.30 FL
25	1	*WIPER WASHER TANK	Mtg Broken	348.40 FL	*348.40 FL
26	1	*WIPER WASHER TANK MOTOR	Not Necessary	148.10 FL	*- FL
27	1	*WIPER WASHER TANK HOSE	Not Necessary	138.90 FL	*- FL
28	1	*A/C CONDENSOR ASSY	Bent	1,498.80 FL	*1,498.80 FL
29	1	*A/C CONDENSER FAN COMPLETE	Not Necessary	621.70 FL	*- FL
30	1	*A/C CONDENSOR LOW PRESSURE PIPE	Not Necessary	425.90 FL	*- FL
31	1	*A/C CONDENSOR HIGH PRESSURE PIPE	Not Necessary	337.40 FL	*- FL
32	1	*A/C CONDENSOR DISCHARGE PIPE	Not Necessary	337.40 FL	*- FL
33	1	*RADIATOR ASSY	Punctured / Mtg Broken	1,387.40 FL	*1,387.40 FL
34	1	*RADIATOR TOP HOSE	Not Necessary	103.60 FL	*- FL
35	1	*RADIATOR BOTTOM HOSE	Not Necessary	185.30 FL	*- FL
36	1	*RADIATOR FAN MOTOR	Not Necessary	332.80 FL	*- FL
37	1	*RADIATOR FAN BLADE	Not Necessary	195.90 FL	*- FL
38	1	*RADIATOR FAN COWLING	Not Necessary	395.20 FL	*- FL
39	2	*FRONT FENDER LH / RH	Dented	1,645.40 FL	*1,245.40 FL
40	2	*FRONT FENDER ARC GARNISH LH / RH	Bent / Broken	966.00 FL	*966.00 FL
41	1	*FRONT FENDER INNER SHIELD LH / RH	O/S Torn / N/S Not Necessary	307.00 FL	*153.50 FL
42	1	*FRONT WHEEL HOUSING RH	Dented	1,094.40 FL	*812.30 FL

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*FRONT WHEEL BEARING & HUB ASSY RH	Not Necessary	432.30 FL	*- FL
44	1		*FRONT ABSORBER RH	Not Necessary	647.50 FL	*- FL
45	1		*FRONT LOWER ARM RH	Distorted	440.50 FL	*349.60 FL
46	1		*FRONT KNUCKLE ARM RH	Distorted	683.20 FL	*583.20 FL
47	1		*FRONT STABILIZER BAR	Not Necessary	503.30 FL	*- FL
48	1		*FRONT STABILIZER LINK RH	Not Necessary	140.80 FL	*- FL
49	1		*FRONT TIE ROD RH	Not Necessary	192.00 FL	*- FL
50	1		*FRONT TIE ROD END RH	Not Necessary	121.00 FL	*- FL
51	1		*FRONT DOOR RH	Repair	1,104.80 FL	*- FL
52	1		*FRONT DOOR BLACK PLASTIC RH	Not Necessary	175.40 FL	*- FL
53	1		*FRONT DOOR WINDOW MOULDING RH	Not Necessary	120.70 FL	*- FL
54	1		*FRONT DOOR CHROME MOULDING RH	Not Necessary	188.90 FL	*- FL
55	1		*A PILLAR RH	Not Necessary	1,530.30 FL	*- FL
56	1		*FRONT WINDSCREEN	Not Necessary	1,244.60 FL	*- FL
57	1		*FRONT WINDSCREEN MOULDING	Not Necessary	234.60 FL	*- FL
58	1		*FRONT WINDSCREEN LOWER GARNISH	Not Necessary	244.90 FL	*- FL
59	1		*RADIATOR RESERVE TANK	Broken	310.70 FL	*268.10 FL
60	1		*BONNET INNER TRIM CLIPS	Necessary	50.00 FS	*15.00 FS
61	1		*HEAD LAMP CLIPS	Not Necessary	50.00 FS	*- FS
62	1		*FRONT GRILLE CLIPS	Necessary	50.00 FS	*15.00 FS
63	1		*FRONT BUMPER CLIPS	Necessary	50.00 FS	*20.00 FS
64	1		*FRONT BUMPER GRILLE CLIPS	Repeated	50.00 FS	*- FS
65	1		*FRONT BUMPER UNDER COVER CLIPS	Not Necessary	50.00 FS	*- FS
66	1		*COOLANT	Necessary (Leaked)	100.00 FS	*40.00 FS
67	1		*FRONT WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
68	1		*FRONT WINDSCREEN DAMPING SEAL	Not Necessary	30.00 FS	*- FS
69	1		*FRONT WHEEL HOUSING SEALANT	Necessary	80.00 FS	*40.00 FS
70	1		*FRONT FENDER INNER SHIELD CLIPS	O/S Necessary	50.00 FS	*15.00 FS
71	1		*FRONT NO. PLATE & CASING	Bent	100.00 FS	*45.00 FS
72	1		*AIR INTAKE DUCT	Broken	495.80 FL	*161.20 FL
73	1		*A/C CONDENSOR SIDE GARNISH LH / RH	O/S Broken / N/S Not Necessary	571.40 FL	*208.00 FL
74	1		*A/C CONDENSOR TOP GARNISH	Broken	529.40 FL	*398.10 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	37,638.30	16,980.10
- List Item Discount on L Items 10.00/10.00% (\$\$)	3,689.83	1,679.01
Total Parts (\$\$)	33,948.47	15,301.09

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ALL INTERIOR UPHOLSTERY ITEMS TO FACILITATE REPAIRS	New	300.00	0.00
2	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	New	2,400.00	1,200.00
3	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	New	2,400.00	1,000.00
4	TO TUFF COAT DAMAGED AREAS	New	300.00	40.00
5	TO RNR A/C CONDENSOR & REFILL GAS TO FACILITATE REPAIRS	New	200.00	120.00
6	TO RNR RADIATOR ASSY & REFILL COOLANT TO FACILITATE REPAIRS	New	200.00	50.00
7	TO RNR FRONT INTER-COOLER TO FACILITATE REPAIRS	New	200.00	50.00
8	TO RNR FRONT UNDERCARRIAGE TO FACILITATE REPAIRS	New	400.00	150.00
9	TO CONDUCT COMPUTERIZE 4 WHEEL ALIGNMENT	New	150.00	60.00
10	TO RNR FRONT WINDSCREEN TO FACILITATE REPAIRS	New	500.00	0.00
11	TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS	New	300.00	30.00
12	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS, RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	New	300.00	150.00
Gross Labour Cost (\$\$)			7,650.00	2,850.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >