

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CTI20013147/KQF3Q2

**Date:** 20/01/2021

### REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00107032001
<b>Claimant Vehicle No :</b>	SMQ8961E	<b>Insured Vehicle No :</b>	SME852C
Date of Loss:	27/11/2020	Nature of Claim:	TP
		Claim No:	SNM20D204639/C02/THAMYL

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SMQ8961E</b>		
Make & Model:	OPEL ASTRA, H 1.6 (MTA)	Engine No:	A2183329JR5X0247
Reg. Date:	09/12/2019 (Man. Year: 2019)	Chassis No:	W0VBD8EG9K8031419
Colour:	Metallic Brown	Odometer:	95354 km
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Continental 3 mm	Rear Left Side:	Continental 3 mm
Front Right Side:	Continental 3 mm	Rear Right Side:	Continental 3 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,749.60	1,071.36	678.24	38.77
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,400.00	420.00	980.00	70.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>3,149.60</b>	<b>1,491.36</b>	<b>1,658.24</b>	<b>52.65</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>1,200.00</b>		
<b>(\$\$)</b>	3,149.60	1,200.00	1,949.60	61.90
<b>+ GST 7.00/7.00% (\$\$)</b>	220.47	84.00	136.47	61.90
<b>Nett Amount (\$\$)</b>	<b>3,370.07</b>	<b>1,284.00</b>	<b>2,086.07</b>	<b>61.90</b>

### INSPECTION

Date of Assignment:	02/01/2021	
Date Inspected:	11/01/2021	Inspected At:
		MUNICH AUTOCARE PTE LTD 60 JALAN LAM HUAT #07-43 CARROS CENTER SINGAPORE 737869
Estimated Period of Repair:	2.0 days	

**Adjuster:** KENNETH KONG**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 19 Jan 2021)
<b>Parts:</b>	144	OPEL ASTRA H 1.6 (MTA) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SMQ8961E)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		<b>*39113368 REAR BUMPER</b>	Buckled/Dented	1,190.40 FL	*1,190.40 FL
2	1		<b>*13426391 BRACKET CENTRE</b>	Serviceable	48.00 FL	*- FL
3	1		<b>*39193222 REAR END PANEL</b>	Repair	648.00 FL	*- FL
4	1		<b>*90766405 REFLECTOR LH</b>	Serviceable	28.80 FL	*- FL
5	1		<b>*90766404 REFLECTOR RH</b>	Serviceable	28.80 FL	*- FL

F=Franchise part. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>1,944.00</b>	<b>1,190.40</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	194.40	119.04
<b>Total Parts (\$\$)</b>	<b>1,749.60</b>	<b>1,071.36</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	LABOUR FOR REPLACE REAR END PANEL AND PANEL BEATING AFFECTED AREAS }	New	400.00	200.00
2	LABOUR FOR REMOVE & TRANSFER PARTS TO NEW BUMPER }	New	200.00	0.00
3	LABOUR FOR SPRAY PAINT REAR BUMPER }	New	400.00	220.00
4	LABOUR FOR SPRAY PAINT REAR END PANEL }	New	400.00	0.00
<b>Gross Labour Cost (\$)</b>			<b>1,400.00</b>	<b>420.00</b>

Report was unsubmitted during this print-out.

**< END OF ESTIMATES >**