

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CTI20013153/QTF3E2

**Date:** 01/02/2021

### REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00089982000  
**Claimant Vehicle No :** SJH2373A **Insured Vehicle No :** SGQ4583K  
Date of Loss: 27/11/2020 Nature of Claim: TP Claim No: SNM20D204640/C02

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJH2373A**  
Make & Model: VOLKSWAGEN TOURAN, 1.4 TSI (A) Engine No: BLG039624  
Reg. Date: 30/07/2008 (Man. Year: 2008) Chassis No: WVGZZZ1TZ8W155441  
Colour: Black Odometer: 177452 km  
Engine Capacity: 1390 cc  
Market Value/New Car Price: N/A  
Sum Insured (\$\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16  
Front Left Side: Falken 6 mm Rear Left Side: Falken 6 mm  
Front Right Side: Falken 6 mm Rear Right Side: Falken 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	7,296.00	2,210.40	5,085.60	69.70
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,240.00	1,270.00	1,970.00	60.80
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>10,536.00</b>	<b>3,480.40</b>	<b>7,055.60</b>	<b>66.97</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>2,800.00</b>		
<b>Nett Amount (\$\$)</b>	<b>10,536.00</b>	<b>2,800.00</b>	<b>7,736.00</b>	<b>73.42</b>

### INSPECTION

Date of Assignment: 14/01/2021  
Date Inspected: 01/12/2020 Inspected At: Kent Seng Car Service  
Blk 1017 Yishun Industrial Park A, #01-240  
Singapore 768759  
Estimated Period of Repair: 3.0 days

**Adjuster:** OI SUN PIN

**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 01 Feb 2021)	
<b>Parts:</b>	N/A	VOLKSWAGEN TOURAN 1.4 TSI (A) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SJH2373A)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Crumpled	1,250.00 F	*950.00 FL
2	1		*REAR BUMPER LOWER LIP COVER	Serviceable	650.00 F	*- FL
3	10		*REAR BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
4	2		*REAR BUMPER LEFT & RIGHT HAND SIDE RETAINER	Serviceable	84.00 F	*- FL
5	1		*REAR BUMPER CENTER SECURING STRIP (CHROME)	Necessary	198.00 F	*158.00 FL
6	2		*REAR BUMPER LEFT & RIGHT SIDE REFLECTOR	Serviceable	120.00 F	*- FL
7	1		*REAR BUMPER TOW COVER	Crumpled	28.00 F	*28.00 FL
8	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	300.00 F	*220.00 FL
9	1		*REAR END PANEL OUTER	Repair	325.00 F	*- FL
10	1		*REAR END PANEL GARNISH	Serviceable	195.00 F	*- FL
11	1		*TAILGATE	Serviceable	1,650.00 F	*- FL
12	1		*TAILGATE TSI EMBLEM	Serviceable	57.00 F	*- FL
13	1		*TAILGATE VOLKSWAGEN LOGO	Serviceable	115.00 F	*- FL
14	1		*TAILGATE TOURAN EMBLEM	Serviceable	68.00 F	*- FL
15	1		*TAILGATE TOP LOCK	Serviceable	155.00 F	*- FL
16	1		*TAILGATE LOWER CHROME	Serviceable	235.00 F	*- FL
17	1		*REAR WIND SCREEN MOULDING	Serviceable	138.00 F	*- FL
18	1		*REAR NUMBER PLATE WITH CASING	Serviceable	60.00 F	*- FL
19	1		*FRONT BUMPER	Crumpled	1,350.00 F	*1,050.00 FL
20	2		*FRONT BUMPER SIDE RETAINER	Serviceable	84.00 F	*- FL
21	2		*FRONT BUMPER SIDE MOULDING	Serviceable	184.00 F	*- FL

F=Franchise part. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>7,296.00</b>	<b>2,456.00</b>
<b>- List Item Discount on L Items 0.00/10.00% (\$\$)</b>	0.00	245.60
<b>Total Parts (\$\$)</b>	<b>7,296.00</b>	<b>2,210.40</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR FOR CUTTING REAR END PANEL, KNOCKING, STRAIGHTEN, REALIGNING THE AFFECT AREA, DISMANTLE AND REPLACE FRONT AND REAR DAMAGE PARTS	New	1,500.00	600.00
2	LABOUR TO RESPRAY REAR TAILGATE COVER (INNER & OUTER) PORTION, REAR END PANEL, REAR BUMPER & FRONT BUMPER	New	1,200.00	600.00
3	RUST-PROOFING ON THE FRONT ACCIDENT AFFECTED	New	200.00	40.00
4	TO TESTING, CHECKING, DISMANTLE AND REPLACE REAR REVERSE SENSOR	New	80.00	30.00
5	TO APPLY SILICON ONTO REAR WIND SCREEN	New	80.00	0.00
6	LABOUR TO DISMANTLE & REFIX REAR WIND SCREEN	New	180.00	0.00
<b>Gross Labour Cost (S\$)</b>			<b>3,240.00</b>	<b>1,270.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >