

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20013154/AQF3Q2

Date: 18/02/2021

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMHCSNW00005292001

**Claimant
Vehicle No :** SME6822A

**Insured Vehicle
No :** SCE6900B

Date of Loss: 25/11/2020

Nature of Claim: TP

Claim
No: SNM20D204599

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SME6822A**

Make & Model: HYUNDAI ELANTRA, 1.6 AD GLS (A)

Engine No: G4FGJU250222

Reg. Date: 11/10/2018 (Man. Year: 2018)

Chassis No: KMHD841CMJU740154

Colour: Red

Odometer: 39044 km

Engine Capacity: 1591 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size: 195/65 R15

Front Left Side: Nexen 6 mm

Rear Left Side: Nexen 6 mm

Front Right Side: Nexen 6 mm

Rear Right Side: Nexen 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,737.84	4,538.72	3,199.12	41.34
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,760.00	2,110.00	1,650.00	43.88
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,497.84	6,648.72	4,849.12	42.17
Approved Total (Overridden) (S\$)		5,300.00		
Nett Amount (S\$)	11,497.84	5,300.00	6,197.84	53.90

INSPECTION

Date of Assignment: 07/12/2020

Date Inspected: 01/12/2020 Inspected At:

Ms Car Auto Pte Ltd (HQ)
8 KAKI BUKIT AVE 4 #01-07
PREMIER @ KAKI BUKIT
Singapore 415875

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 10 Feb 2021)
Parts:	143	HYUNDAI ELANTRA 1.6 AD GLS (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SME6822A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT	Dented	1,178.00 FL	*1,178.00 FL
2	1		*REAR BOOT LOCK	Damaged	188.00 FL	*188.00 FL
3	1		*REAR BOOT W/STRIP	Cut	112.00 FL	*112.00 FL
4	1		*REAR BOOT LOGO	Necessary	73.00 FL	*73.00 FL
5	1		*REAR BOOT EMBLEM-ELANTRA	Necessary	58.00 FL	*58.00 FL
6	1		*REAR BOOT EMBLEM-S	Necessary	67.50 FL	*67.50 FL
7	1		*REAR BOOT HANDLE	Not Necessary	137.50 FL	*- FL
8	2		*REAR BOOT REFLECTOR L+R	Not Necessary	386.00 FL	*- FL
9	1		*REAR BOOT INSULATOR	Not Necessary	167.00 FL	*- FL
10	10		*REAR BOOT INSULATOR CLIP	Not Necessary	50.00 FL	*- FL
11	2		*REAR BOOT HINGE L+R	Not Necessary	264.00 FL	*- FL
12	1		*REAR BUMPER	Deformed	634.00 FL	*634.00 FL
13	1		*REAR BUMPER SPONGE	Not Necessary	183.00 FL	*- FL
14	1		*REAR BUMPER REINFORCEMENT	Bent	595.00 FL	*295.00 FL
15	2		*REAR BUMPER REINFORCEMENT BRACKET L+R	Not Necessary	186.40 FL	*- FL
16	1		*REAR BUMPER REINFORCEMENT TOP BRACKET (3 Pcs)	Bent	86.00 FL	*86.00 FL
17	2		*REAR BUMPER REINFORCEMENT BOTTOM BRACKET	Damaged	76.00 FL	*76.00 FL
18	10		*REAR BUMPER CLIP	Necessary	50.00 FL	*30.00 FL
19	2		*TAIL LAMP L+R	Cracked	972.00 FL	*972.00 FL
20	2		*TAIL LAMP PANEL L+R	Repair	480.00 FL	*- FL
21	4		*TAIL LAMP CLIP L+R	Not Necessary	20.00 FL	*- FL
22	1		*REAR END PANEL	Dented	698.00 FL	*586.00 FL
23	1		*REAR END PANEL TOP GARNISH	Deformed	84.00 FL	*84.00 FL
24	1		*SPARE WHEEL PANEL	Repair	943.00 FL	*- FL
25	1		*SPARE WHEEL PANEL TOP BOARD	Deformed	274.00 FL	*274.00 FL
26	1		*BUMPER LOWER LIP	Deformed	353.80 FL	*353.80 FL
27	1		*REAR END PANEL ANTENNA SENSOR	Cracked	189.70 FL	*189.70 FL
28	2		*REAR BUMPER REFLECTOR	Cracked	91.40 FL	*91.40 FL
29	1		*REAR NUMBER PLATE	Not Necessary	50.00 FS	*- FS
30	2		*REVERSE SENSOR	Damaged	500.00 FS	*200.00 FS
31	1		*REAR END PANEL SEALANT	Necessary	80.00 FS	*60.00 FS
32	1		*SPARE WHEEL PANEL SEALANT	Not Necessary	80.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
33	1		*SPARE WHEEL PANEL INSULATOR	Not Necessary	150.00 FS	*-FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (S\$)					9,457.30	5,608.40
- List Item Discount on L Items 20.00/20.00% (S\$)					1,719.46	1,069.68
Total Parts (S\$)					7,737.84	4,538.72

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO R & R ACCIDENT DAMAGE PARTS,TO CUT/WELD,KNOCK AND REALIGN ACCIDENT AFFECTED AREA	New	1,500.00	900.00
2	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA	New	1,500.00	1,000.00
3	TO RUST PROOF ACCIDENT AFFECTED AREA	New	120.00	60.00
4	TO R & R REAR BOOT MECHANISM	New	100.00	60.00
5	TO R & R REAR LUGGAGE COMPARTMENT	New	100.00	60.00
6	TO R & R REVERSE SENSOR AND CHECK FUNCTION	New	80.00	30.00
7	TO R & R REAR UNDER CARRIAGE SYSTEM	New	280.00	0.00
8	TO CHECK WHEEL ALIGNMENT	New	80.00	0.00
Gross Labour Cost (S\$)			3,760.00	2,110.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >