

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CC3/AIG20013155/AVD3E2

**Date:** 28/05/2021

### REFERENCE

Insured/Claimant:	NOH BIN SALLEH	Policy No:	2070113511		
Date of Loss:	26/11/2020	Nature of Claim:	OD	Claim No:	1453319248SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLB1989M	Engine No:	CVK082853
Make & Model:	AUDI A4, 2.0 (A)	Chassis No:	WAUZZZF41KN014147
Reg. Date:	04/08/2020 (Man. Year: 2019)	Odometer:	6910 km
Colour:	Black		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$155,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	245/40R18	Rear Tyre Size:	245/40R18
Front Left Side:	Hankook 6 mm	Rear Left Side:	Hankook 6 mm
Front Right Side:	Hankook 6 mm	Rear Right Side:	Hankook 6 mm

*The above values represent the remaining tyre tread depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,208.00	4,046.24	13,161.76	76.49
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,702.00	2,302.00	3,400.00	59.63
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>22,910.00</b>	<b>6,348.24</b>	<b>16,561.76</b>	<b>72.29</b>
<b>- Excess (S\$)</b>	<b>550.00</b>	<b>550.00</b>	<b>0.00</b>	<b>0.00</b>
<b>(S\$)</b>	<b>22,360.00</b>	<b>5,798.24</b>	<b>16,561.76</b>	<b>74.07</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,565.20</b>	<b>405.88</b>	<b>1,159.32</b>	<b>74.07</b>
<b>Nett Amount (S\$)</b>	<b>23,925.20</b>	<b>6,204.12</b>	<b>17,721.08</b>	<b>74.07</b>

### INSPECTION

Date of Assignment:	01/12/2020		
Date Inspected:	30/11/2020	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	6.0 days		

**Adjuster:** ADRIAN LING

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,171.00 FS	*1,736.80 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	580.00 FS	*- FS
3	1		*FRONT BUMPER SECURING STRIP	Not Necessary	35.00 FS	*- FS
4	1		*FRONT BUMPER GRILLE-CENTRE	Not Necessary	194.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT-LOWER CENTRE	Not Necessary	208.00 FS	*- FS
6	1		*FRONT BUMPER AIR GUIDE-RH	Not Necessary	62.00 FS	*- FS
7	1		*RADIATOR GRILLE	Cracked	1,317.00 FS	*1,053.60 FS
8	1		*FRONT BUMPER AIR GUIDE GRILLE-RH	Not Necessary	134.00 FS	*- FS
9	1		*FRONT BUMPER CARRIER	Bent	795.00 FS	*635.60 FS
10	1		*FRONT BUMPER FOAM FILLER PIECE	Cracked	123.00 FS	*98.40 FS
11	1		*FRONT BUMPER GUIDE SECTION-RH	Not Necessary	37.00 FS	*- FS
12	1		*FRONT BUMPER TOP COVER	Not Necessary	126.00 FS	*- FS
13	1		*CAUTION SIGN STICKER	Not Necessary	14.00 FS	*- FS
14	1		*AIRCON STICKER	Not Necessary	8.00 FS	*- FS
15	1		*LOCK CARRIER BRACKET	Cracked	136.00 FS	*108.40 FS
16	2		*LOCK CARRIER BRACKET SUPPORT-LH/RH	Not Necessary	56.00 FS	*- FS
17	1		*HORN-RH LOW TONE	Not Necessary	124.00 FS	*- FS
18	1		*SPRING SHACKLE-RH	Not Necessary	29.00 FS	*- FS
19	2		*FRONT PARKING AID SENSOR-INNER/OUTER	Not Necessary	484.00 FS	*- FS
20	4		*FRONT PARKING AID SEAL RING	Not Necessary	14.00 FS	*- FS
21	1		*FRONT FENDER-RH	Not Necessary	758.00 FS	*- FS
22	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	200.00 FS	*- FS
23	1		*FRONT FENDER CLOSING ELEMENT-RH	Not Necessary	49.00 FS	*- FS
24	1		*FRONT FENDER BRACKET-RH	Not Necessary	35.00 FS	*- FS
25	1		*DEFORMATION ELEMENT BRACKET-RH	Not Necessary	49.00 FS	*- FS
26	1		*WHEEL HOUSING LINER-RH	Not Necessary	239.00 FS	*- FS
27	1		*WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	230.00 FS	*- FS
28	1		*WHEEL SPOILER-RH	Not Necessary	73.00 FS	*- FS
29	1		*WHEEL SPOILER TRIM-RH	Not Necessary	36.00 FS	*- FS
30	1		*STONE CHIP GUARD-RH	Not Necessary	50.00 FS	*- FS
31	1		*TOP FENDER LEDGE COVER-UPPER	Not Necessary	31.00 FS	*- FS
32	1		*TOP FENDER LEDGE COVER-LOWER	Not Necessary	23.00 FS	*- FS
33	1		*LED HEADLIGHT-RH	Not Necessary	7,693.00 FS	*- FS
34	1		*LIFT CYLINDER-RH	Not Necessary	208.00 FS	*- FS
35	1		*LIFT CYLINDER CORRUGATED PIPE	Not Necessary	92.00 FS	*- FS
36	1		*RADIATOR AIR GUIDE-OUTER	Not Necessary	28.00 FS	*- FS
37	1		*RADIATOR AIR GUIDE-INNER	Damaged	12.00 FS	*9.36 FS
38	1		*RADIATOR AIR GUIDE-UPPER	Not Necessary	16.00 FS	*- FS
39	1		*FRONT NO PLATE	Necessary	60.00 FS	*60.00 FS
40	1		*SUNDRIES	Necessary	250.00 FS	*1.12 FS
41	1		*FRONT BUMPER REINFORCEMENT BRACKET-RH (SUPPLEMENTARY)	Bent	225.00 FS	*180.00 FS
42	1		*BONNET IMPACT PROTECTION-CENTRE (SUPPLEMENTARY)	Damaged	27.00 FS	*21.52 FS
43	1		*RADIATOR COOLANT (SUPPLEMENTARY)	Necessary	177.00 FS	*141.44 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 17,208.00 4,046.24

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE,CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR,HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	280.00	280.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHT CONTROL UNIT AND POWER MODULE	New	350.00	0.00
3	TO DISMANTLE AND RENEW FRONT BUMPER,RHS FRONT FENDER AND RHS HEADLIGHT.RE-ORGANISE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	2,100.00	500.00
4	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER	New	2,000.00	550.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
6	TO DISLODGE AND REINSTALL FRONT LOCK CARRIER TO FACILIATE THE RENEWAL OF FRONT RHS BUMPER REINFORCEMENT BRACKET (SUPPLEMENTARY)	New	780.00	780.00
<b>Gross Labour Cost (\$\$)</b>			<b>5,702.00</b>	<b>2,302.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >