

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG20013156/APA3Q2

Date: 04/03/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2070103095

Claimant
Vehicle No : SLW1265H **Insured Vehicle No :** GBH5392U

Date of Loss: 27/11/2020 Nature of Claim: TP Claim No: 0092575593SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLW1265H		
Make & Model:	AUDI A4, 2.0 (A)	Engine No:	CVK049078
Reg. Date:	30/01/2018 (Man. Year: 2017)	Chassis No:	WAUZZZF49JA062713
Colour:	Blue	Odometer:	34867 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/40R18	Rear Tyre Size:	245/40R18
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,457.00	1,744.80	2,712.20	60.85
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,502.00	1,602.00	900.00	35.97
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	6,959.00	3,346.80	3,612.20	51.91
+ GST 7.00/7.00% (S\$)	487.13	234.28	252.85	51.91
Nett Amount (S\$)	7,446.13	3,581.08	3,865.05	51.91
+ Car Rental (3.0 x S\$150.00/day) (S\$)		450.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		4,033.08		

INSPECTION

Date of Assignment: 02/12/2020

Date Inspected: 02/12/2020 Inspected At: Premium Automobiles Pte Ltd (HQ)
55 UBI ROAD 1
Singapore 408699

Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	2,181.00 FS	*1,744.80 FS
2	1		*REAR BUMPER FIXING PARTS	Not Necessary	72.00 FS	*- FS
3	1		*REAR BUMPER SECURING STRIP	Not Necessary	220.00 FS	*- FS
4	1		*REAR BUMPER SPOILER	Not Necessary	246.00 FS	*- FS
5	2		*REAR LIGHT REFLECTOR -LH/RH	Not Necessary	82.00 FS	*- FS
6	1		*REAR BUMPER CARRIER	Not Necessary	886.00 FS	*- FS
7	2		*REAR BUMPER CARRIER SEAL	Not Necessary	28.00 FS	*- FS
8	2		*REAR BUMPER GUIDE SECTION -LH/RH	Not Necessary	44.00 FS	*- FS
9	2		*REAR PARKING AID SENSOR -INNER /OUTER	Not Necessary	484.00 FS	*- FS
10	4		*REAR PARKING AID SEAL RING	Not Necessary	14.00 FS	*- FS
11	1		*SUNDRIES	Not Necessary	200.00 FS	*- FS
F=Franchise part. S=SpcNett.						
Total Parts (\$\$)					4,457.00	1,744.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR .CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE	New	360.00	360.00
2	TO DISMANTLE AND RENEW REAR BUMPER .RE-ORGANISE CRASH MANAGEMENT COMPONENTS .REINSTALL ALL PARTS REMOVED	New	1,050.00	500.00
3	TO RESPRAY REAR BUMPER	New	900.00	550.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			2,502.00	1,602.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >