

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG20013160/GQD3E2

Date: 28/12/2020

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070113511		
Claimant Vehicle No :	SMR7015M	Insured Vehicle No :	SLB1989M		
Date of Loss:	26/11/2020	Nature of Claim:	TP	Claim No:	1453319248SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMR7015M	Engine No:	CDH123270
Make & Model:	AUDI A4, 1.8 T (A)	Chassis No:	WAUZZZ8K7BA110514
Reg. Date:	28/04/2011 (Man. Year: 2011)	Odometer:	75564 km
Colour:	Black		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/50 R17	Rear Tyre Size:	225/50 R17
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	01/12/2020		
Date Inspected:	01/12/2020	Inspected At:	Mje Motor 7 Sin Ming Industrial Estate Sector C, #01-94 Singapore 575642
Estimated Period of Repair:	5.0 days		

Adjuster: XING GUO QIANG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	0.00 F	*- F
2	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
3	1		*REVERSE SENSOR	Damaged	0.00 F	*- F
4	1		*REAR END PANEL	Repair	0.00 F	*- F
5	1		*REAR LH TAILLAMP	Scratched	0.00 F	*- F
6	1		*BOOTLID	Dented	0.00 F	*- F
7	3		*BOOTLID EMBLEM	Necessary	0.00 F	*- F
8	1		*BOOTLID LAMP LH	Scratched	0.00 F	*- F
9	1		*REAR EXHAUST PIPE	Repair	0.00 F	*- F
10	1		*REAR EXHAUST CHROME PIPE	Cut	0.00 F	*- F
F=Franchise part.				Total Parts (\$\$)	0.00	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >