

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CS/AIG20013162/EQD3E2

Date: 15/12/2020

REFERENCE

Insured/Claimant:	TOH ENG YEE	Policy No:	2100383481		
Date of Loss:	30/11/2020	Nature of Claim:	OD	Claim No:	9343274065SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKP2045T		
Make & Model:	KIA FORTE K3, 1.6 (A)	Engine No:	G4FGEH735063
Reg. Date:	25/08/2014 (Man. Year: 2014)	Chassis No:	KNAFZ411MF5316722
Colour:	Grey	Odometer:	83192 km
Engine Capacity:	1591 cc		
Market Value/New Car Price:	S\$38,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/50 R15	Rear Tyre Size:	195/50 R15
Front Left Side:	Dunlop 5 mm	Rear Left Side:	Dunlop 5 mm
Front Right Side:	Dunlop 5 mm	Rear Right Side:	Dunlop 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,103.60	2,497.60	606.00	19.53
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,710.00	1,710.00	0.00	0.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,813.60	4,207.60	606.00	12.59
+ GST 7.00/7.00% (S\$)	336.95	294.53	42.42	12.59
Nett Amount (S\$)	5,150.55	4,502.13	648.42	12.59

INSPECTION

Date of Assignment:	01/12/2020		
Date Inspected:	01/12/2020	Inspected At:	Cycle & Carriage KIA Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	4.0 days		

Adjuster: CHEN TSUE YEE

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LAMP ASSY-HEAD, RH	Broken	1,870.00 FL	*1,870.00 FL
2	1		*PANEL -FENDER, RH	Dented	435.00 FL	*435.00 FL
3	1		*BRACKET-FR BUMPER SIDE MTG, RH	Broken	13.00 FL	*13.00 FL
4	1		*COVER-FR BUMPER	Deformed	728.00 FL	*728.00 FL
5	1		*ABSORBER -FRONT BUMPER ENERGY	Not Necessary	97.00 FL	*- FL
6	1		*RAIL ASSY-FR BUMPER	Not Necessary	410.00 FL	*- FL
7	1		*BRACKET-FR BUMPER UPR SIDE MTG	Not Necessary	26.00 FL	*- FL
8	1		*ULTRASONIC SENSOR ASSY - FBWS	Not Necessary	187.00 FL	*- FL
9	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
10	1		*LOGO ASSY-KIA SUB	Necessary	51.00 FL	*51.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,867.00	3,117.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	763.40	619.40
Total Parts (\$\$)	3,103.60	2,497.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW ACCIDENT DAMAGED PARTS ON FRONT BUMPER FACE, RH FRONT FENDER, RH HEADLAMP.	New	800.00	800.00
2	REMOVE AND INSTALL PARKING ASSIST.	New	60.00	60.00
3	PAINT WORK SPRAY RH FRONT FENDER, FRONT BUMPER AND AFFECTED PORTION.	New	700.00	700.00
4	CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM.	New	30.00	30.00
5	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
Gross Labour Cost (\$\$)			1,710.00	1,710.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >