

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20013164/APS3Q2

Date: 18/02/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900092763

Claimant
Vehicle No : SGF6696M **Insured Vehicle No :** SML5970A

Date of Loss: 26/11/2020 Nature of Claim: TP Claim No: 4621858998SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGF6696M		
Make & Model:	HONDA VEZEL, 1.5 X (A)	Engine No:	L15B4027266
Reg. Date:	21/03/2016 (Man. Year: 2015)	Chassis No:	RU11107262
Colour:	White	Odometer:	360143 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,910.30	3,435.36	4,474.94	56.57
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,580.00	2,100.00	1,480.00	41.34
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,490.30	5,535.36	5,954.94	51.83
Approved Total (Overridden) (S\$)		4,400.00		
Nett Amount (S\$)	11,490.30	4,400.00	7,090.30	61.71
+ Loss of Use (6.0 x S\$60.00/day) (S\$)		360.00		
Nett Liability (S\$)		4,760.00		

INSPECTION

Date of Assignment: 30/11/2020

Date Inspected: 30/11/2020 Inspected At:

Leang Automotive (HQ)
BLK 1 KAKI BUKIT AVE 6 #02-12
AUTOBAY@ KAKI BUKIT
Singapore 417883

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	459.40 F	*459.40 FL
2	2		*REAR BUMPER SIDE HOLDER	Necessary	47.00 F	*47.00 FL
3	2		*REAR BUMPER REFLECTOR	Cracked	282.20 F	*282.20 FL
4	1		*REAR END PANEL	Dented	585.00 F	*585.00 FL
5	1		*REAR END PANEL TOP GARNISH	Deformed	98.40 F	*98.40 FL
6	1		*REAR END PANEL ANTENNA SENSOR	Not Necessary	90.80 F	*- FL
7	1		*REAR END PANEL BUZZER	Damaged	85.20 F	*85.20 FL
8	2		*TAILLAMP	Not Necessary	949.20 F	*- FL
9	2		*TAILLAMP LOWER APRON	Repair	390.00 F	*- FL
10	1		*TAILGATE	Distorted	1,100.00 F	*1,100.00 FL
11	1		*TAILGATE LOCK	Damaged	182.50 F	*182.50 FL
12	1		*TAILGATE WEATHERSTRIPE	Cut	165.40 F	*165.40 FL
13	2		*TAILGATE REFLECTOR	Not Necessary	826.40 F	*- FL
14	1		*TAILGATE INNER TRIM BOARD	Cracked	285.60 F	*285.60 FL
15	1		*TAILGATE OUTER GARNISH	Not Necessary	395.20 F	*- FL
16	1		*TAILGATE GLASS MOULDING	Necessary	120.00 F	*120.00 FL
17	1		*HONDA LOGO	Not Necessary	30.40 F	*- FL
18	1		*VEZEL EMBLEM	Necessary	45.90 F	*45.90 FL
19	1		*SPARE TYRE PANEL TOP COVER	Not Necessary	306.20 F	*- FL
20	1		*SPARE TYRE PANEL UNDER COVER	Deformed	225.10 F	*225.10 FL
21	2		*REAR FENDER INNER TRIM BOARD	Not Necessary	610.40 F	*- FL
22	1		*REAR NUMBER PLATE	Bent	30.00 FS	*30.00 FS
23	1		*REAR NUMBER PLATE HOLDER	Deformed	30.00 FS	*30.00 FS
24	1		*REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
25	1		*REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
26	1		*REAR END PANEL TOP GARNISH CLIPS	Necessary	20.00 FS	*20.00 FS
27	1		*REAR END PANEL SEALANT	Necessary	60.00 FS	*60.00 FS
28	1		*TAILGATE INNER TRIM BOARD CLIPS	Necessary	30.00 FS	*30.00 FS
29	1		*TAILGATE GLASS SEALANT	Necessary	60.00 FS	*60.00 FS
30	1		*SPARE TYRE PANEL UNDER COVER CLIPS	Necessary	30.00 FS	*30.00 FS
31	1		*REAR FENDER INNER TRIM BOARD CLIPS	Not Necessary	60.00 FS	*- FS
					Sub Total (\$\$)	7,910.30 4,171.70
					- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00 736.34
					Total Parts (\$\$)	7,910.30 3,435.36

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	1,400.00	800.00
2	SPRAY PAINTING	New	1,200.00	800.00
3	WIRING	New	50.00	30.00
4	TO REMOVE REVERSE SENSOR	New	100.00	50.00
5	TO REMOVE REAR CAMERA	New	100.00	50.00
6	TO REMOVE VIDEO CRCORDER	New	100.00	50.00
7	TO REMOVE UPHOLSTERY	New	150.00	60.00
8	TO TRANSER TAILGATE FITTINGS	New	150.00	80.00
9	TO REMOVE TAILGATE GLASS	New	180.00	120.00
10	TO SPRAY TUFF COAT	New	150.00	60.00
Gross Labour Cost (\$\$)			3,580.00	2,100.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >