

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20013165/R1VF3E2

Date: 15/12/2020

### REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00090242000  
Claimant Vehicle No: SGJ7710C Insured Vehicle No: GBK6062A  
Date of Loss: 02/10/2020 Nature of Claim: TP Claim No: SNM20D203706C02/IRENE

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SGJ7710C  
Make & Model: HYUNDAI TUCSON, 2.0 (A) Engine No: G4GC5456719  
Reg. Date: 21/07/2006 (Man. Year: 2005) Chassis No: KMHJN81BR6U336003  
Colour: Black Odometer: 169623 km  
Engine Capacity: 1975 cc  
Market Value/New Car Price: N/A  
Sum Insured (\$\$): Market Value/New Car Price

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 215/65 R16 Rear Tyre Size: 215/65 R16  
Front Left Side: Falken 6 mm Rear Left Side: Falken 6 mm  
Front Right Side: Falken 6 mm Rear Right Side: Falken 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	949.80	592.00	357.80	37.67
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,120.00	510.00	610.00	54.46
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>2,069.80</b>	<b>1,102.00</b>	<b>967.80</b>	<b>46.76</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>900.00</b>		
	2,069.80	900.00	1,169.80	56.52
<b>+ GST 7.00/7.00% (\$\$)</b>	144.89	63.00	81.89	56.52
<b>Nett Amount (\$\$)</b>	<b>2,214.69</b>	<b>963.00</b>	<b>1,251.69</b>	<b>56.52</b>

### INSPECTION

Date of Assignment: 01/12/2020  
Date Inspected: 07/12/2020 Inspected At: Wah Hong Motors & Credit Pte Ltd (HQ)  
38 Toh Guan Road East, #01-57, Enterprise Hub  
Singapore 608581  
Estimated Period of Repair: 2.0 days

Adjuster: MOHD RASUL

Manager: VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 15 Dec 2020)
Parts:	M1-SUV	HYUNDAI TUCSON 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGJ7710C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER RH	Bent	619.00 FL	*330.00 FL
2	1		*FRONT HEADLAMP RH	Cracked	477.00 FL	*410.00 FL
3	1		*FRONT BUMPER SIDE RETAINER RH	Serviceable	10.00 FL	*- FL
4	1		*FRONT BUMPER (NPA)	Repair	0.00 FL	*- FL
5	1		*FRONT BUMPER CLIPS	Not Necessary	35.00 FS	*- FS
6	1		*FRONT FENDER SHIELD CLIPS	Not Necessary	30.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	1,171.00	740.00
- List Item Discount on L Items 20.00/20.00% (S\$)	221.20	148.00
Total Parts (S\$)	949.80	592.00

Report was unsubmitted during this print-out.

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS; PANEL BEAT & RESHAPE THE AFFECTED AREAS AND REPLACE THE DAMAGED PARTS AND COMPONENTS	New	600.00	250.00
2	TO SUPPLY PAINT MATERIALS, EXPANDABLE ITEMS & PUTTY, RESPRAY PAINT ON PARTS REPLACED & REPAIRED	New	400.00	200.00
3	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS	New	30.00	30.00
4	TO REMOVE AND REFIX WIRING SYSTEM AT ACCIDENT DAMAGED AREA AND CHECK FOR ALL ELECTRICAL PROPER FUNCTION	New	60.00	0.00
5	TO REMOVE, RE-FIX / REPLACE AND FOCUS HEADLAMP BEAM	New	30.00	30.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,120.00</b>	<b>510.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >