

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG20013166/QGS3Q2
Date: 18/05/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999993896
Claimant Vehicle No :	SHC4730P	Insured Vehicle No :	GBH3871S
Date of Loss:	23/11/2020	Nature of Claim:	TP
		Claim No:	9005145421SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC4730P		
Make & Model:	TOYOTA PRIUS TAXI, 1.8 (A)	Engine No:	2ZR6555936
Reg. Date:	15/01/2016 (Man. Year: 2015)	Chassis No:	JTDKN36U605766792
Colour:	Maroon	Odometer:	708961 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Neuton 6 mm	Rear Left Side:	Neuton 6 mm
Front Right Side:	Neuton 6 mm	Rear Right Side:	Neuton 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,735.34	2,925.30	10,810.04	78.70
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,855.00	1,590.00	3,265.00	67.25
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	18,590.34	4,515.30	14,075.04	75.71
Approved Total (Overridden) (S\$)		3,950.00		

Nett Amount (S\$)	18,590.34	3,950.00	14,640.34	78.75
+ Loss of Use (7.0 x S\$60.00/day) (S\$)		420.00		
+ Car Rental (7.0 x S\$97.00/day) (S\$)		679.00		
+ Doc/Search Fee (S\$)		7.00		
Nett Liability (S\$)		5,056.00		

INSPECTION

Date of Assignment: 24/11/2020

Date Inspected: 24/11/2020

Estimated Period of Repair: 6.0 days

Inspected At:

SMRT Automotive Services Pte Ltd (Woodlands)
 60 Woodlands Industrial Park E4
 Singapore 757705

Adjuster: OI SUN PIN**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*DUCT ASSY ,QUARTER (DISC 25%)	Crumpled	70.40 F	*52.80 F
2	1		*TAIL LAMP BRACKET ,RH (DISC 25%)	Broken	30.70 F	*23.03 F
3	1		*FENDER LINE RR/RH (DISC 25%)	Crumpled	141.30 F	*105.98 F
4	1		*QUARTER GLASS RR/RH (DISC 25%)	Necessary	846.50 F	*634.88 F
5	1		*FENDER RR/RH (DISC 25%)	Dented	766.80 F	*575.10 F
6	1		*BUMPER LIP COVER RR/RH (DISC 25%)	Crumpled	118.10 F	*88.58 F
7	1		*BUMPER SEAL ,RR RH (DISC 25%)	Broken	65.70 F	*49.28 F
8	1		*BUMPER SIDE RETAINER RR/RH (DISC 25%)	Broken	94.80 F	*71.10 F
9	1		*BUMPER CLIPS (DISC 25%) (10 PCS)	Necessary	21.00 F	*15.75 F
10	1		*BUMPER REAR (DISC 25%)	Crumpled	458.60 F	*343.95 F
11	1		*TROUGH ,BACK DOOR (DISC 25%)	Dented	110.90 F	*83.18 F
12	1		*PANEL ASSY ,DECK RH (DISC 25%)	Crumpled	307.00 F	*230.25 F
13	1		*TAIL LAMP RH (DISC 10%)	Crumpled	557.80 F	*502.02 F
14	1		*STICKER DECAL 65558888 (SN)	Necessary	21.60 F	*21.60 F
15	1		*SMRT LOGO (SN)	Necessary	7.80 F	*7.80 F
16	2		*PIXEL STICKER (SN)	Necessary	120.00 F	*120.00 F
17	1		*PAN,FRONT FLOOR ,RH	Serviceable	667.70 F	*- F
18	1		*COVER ,REAR FLOOR SIDE MEMBER RH	Serviceable	113.90 F	*- F
19	1		*WHEEL HUB REAR	Serviceable	489.40 F	*- F
20	1		*TYRE	Serviceable	126.74 F	*- F
21	1		*WHEEL DISC	Serviceable	1,484.20 F	*- F
22	1		*TROUGH ,BACK DOOR	Serviceable	110.90 F	*- F
23	1		*SILL MEMBER PLATE RR/RH	Serviceable	57.50 F	*- F
24	1		*SEALANT W/SCREEN	Serviceable	37.00 F	*- F
25	1		*STICKER DECAL 65558888	Serviceable	21.60 F	*- F
26	1		*SMRT LOGO	Serviceable	7.80 F	*- F
27	1		*NAME PLATE (TOYOTA)	Serviceable	51.90 F	*- F
28	1		*NAME PLATE (PRUIS)	Serviceable	60.80 F	*- F
29	1		*NAME PLATE (HYBRID)	Serviceable	51.90 F	*- F
30	1		*TAILGATE OUTSIDE GARNISH	Serviceable	504.90 F	*- F
31	2		*TAILGATE DOOR HINGE LH/RH	Serviceable	58.30 F	*- F
32	1		*TAILGATE ASY	Serviceable	1,007.90 F	*- F
33	1		*BATTERY TRAY	Serviceable	42.80 F	*- F
34	1		*BATTERY CLAMP	Serviceable	16.10 F	*- F
35	1		*TERMINAL JUNCTION	Serviceable	51.90 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*BATTERY	Serviceable	278.00 F	*- F
37	1		*PANEL SUB-ASSY ,QTR (RH)	Serviceable	588.40 F	*- F
38	1		*FLOOR PANEL RR/RH	Serviceable	209.90 F	*- F
39	1		*SPARE TYRE PANEL	Serviceable	667.70 F	*- F
40	1		*PANEL ASSY ,DECK RH	Serviceable	307.00 F	*- F
41	1		*BOARD ASSY ,RR RH	Serviceable	379.20 F	*- F
42	1		*SEALANT SIKAFLEX	Serviceable	37.00 F	*- F
43	1		*END PANEL COVER ,DECK TRIM RR	Serviceable	121.10 F	*- F
44	1		*END PANEL COVER ,DECK TRIM HOLE	Serviceable	46.10 F	*- F
45	1		*END PANEL	Serviceable	602.10 F	*- F
46	1		*UNDER COVER RR SHIELD	Serviceable	63.90 F	*- F
47	1		*UNDER COVER SUB-ASSY RR FLOOR	Serviceable	514.50 F	*- F
48	1		*BUMPER LIP REAR	Serviceable	228.90 F	*- F
49	1		*BUMPER LIP COVER RR/LH	Serviceable	72.20 F	*- F
50	1		*BUMPER SIDE RETAINER RR/LH	Serviceable	94.80 F	*- F
51	1		*SENSOR REVERSE	Serviceable	180.00 F	*- F
52	1		*ANTENNA ELECTRICAL LOWER REAR	Serviceable	157.40 F	*- F
53	1		*ARM SUB-ASSY ,RR BUMPER LH	Serviceable	139.60 F	*- F
54	1		*ARM SUB-ASSY ,RR BUMPER RH	Serviceable	139.60 F	*- F
55	1		*BUMPER REINFORCEMENT REAR	Serviceable	205.70 F	*- F
					Total Parts (\$\$)	13,735.34
						2,925.30

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING & BODY WORK	New	1,445.00	950.00
2	SPRAY PAINT	New	2,754.00	600.00
3	TO TEST AND REFIX REVERSE SENSOR SYSTEM	New	120.00	20.00
4	TO DO WHEEL ALIGNMENT /TYRE BALANCING	New	120.00	0.00
5	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	New	120.00	0.00
6	TO REPLACE SUNDRY PARTS	New	100.00	0.00
7	TO CHECK WIRING AND SYSTEM FUNCTION	New	80.00	20.00
8	TO WASH AND VACUUM	New	60.00	0.00
9	TOWING CHARGES	New	56.00	0.00
Gross Labour Cost (\$\$)			4,855.00	1,590.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >