

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI20013179/T1QF3N2**Date:** 26/08/2021**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSN30659719000

**Claimant Vehicle No :** GBE6056A **Insured Vehicle No :** SLN5902Z

Date of Loss: 26/11/2020 Nature of Claim: TP Claim No: SNM20D204646/C02/TAYHP

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **GBE6056A**

Make & Model: NISSAN NV200, 1.6 (A) Engine No: HR16048166D

Reg. Date: 25/01/2016 (Man. Year: 2015) Chassis No: VM20085591

Colour: Black Odometer: 131358 km

Engine Capacity: 1597 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

**CONDITION OF TYRES**

Front Tyre Size: 185/65 R15 Rear Tyre Size: 185/65 R15

Front Left Side: CST 6 mm Rear Left Side: CST 6 mm

Front Right Side: CST 6 mm Rear Right Side: CST 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	13,883.73	4,607.66	9,276.07	66.81
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,700.00	2,000.00	3,700.00	64.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>19,583.73</b>	<b>6,607.66</b>	<b>12,976.07</b>	<b>66.26</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>5,300.00</b>		
<b>(S\$)</b>	19,583.73	5,300.00	14,283.73	72.94
<b>+ GST 7.00/7.00% (S\$)</b>	1,370.86	371.00	999.86	72.94
<b>Nett Amount (S\$)</b>	<b>20,954.59</b>	<b>5,671.00</b>	<b>15,283.59</b>	<b>72.94</b>

**INSPECTION**

Date of Assignment: 01/12/2020

Date Inspected: 02/12/2020 Inspected At: AP Automotive Services Pte Ltd (HQ)  
Blk 9006 Tampines Street 93, #01-202  
Singapore 528840

Estimated Period of Repair: 6.0 days

**Adjuster:** MOHD TAUFIKH BIN HAMID**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

**REPAIR DETAILS****Reference**

<b>Part Source:</b>	(Last Synchronised: 25 Aug 2021)	
<b>Parts:</b>	N/A	NISSAN NV200 1.6 (A) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for GBE6056A)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Bent	1,736.89 FL	*1,736.89 FL
2	1		*TAILGATE WINDSCREEN MOULDING	Necessary	137.55 FL	*137.55 FL
3	1		*TAILGATE LOGO -NISSAN	Necessary	61.68 FL	*61.68 FL
4	1		*TAILGATE HANDLE GARNISH	Not Necessary	341.75 FL	*- FL
5	1		*TAILGATE HANDLE SWITCH	Not Necessary	162.68 FL	*- FL
6	2		*TAILGATE NUMBER PLATE LAMP L+R	Not Necessary	140.20 FL	*- FL
7	1		*TAILGATE LOCK	Bent	278.12 FL	*278.12 FL
8	1		*TAILGATE LOCK CATCH	Not Necessary	75.34 FL	*- FL
9	1		*TAILGATE INNER TRIM	Not Necessary	197.56 FL	*- FL
10	2		*TAILGATE HINGE SET	Not Necessary	167.60 FL	*- FL
11	2		*TAILGATE DAMPER SET	Not Necessary	394.70 FL	*- FL
12	1		*TAILGATE WEATHERSTRIP	Cut	102.75 FL	*63.70 FL
13	2		*TAIL LAMP L+R	Cracked	512.74 FL	*512.74 FL
14	2		*TAIL LAMP PANEL L+R	Not Necessary	385.58 FL	*- FL
15	1		*REAR BUMPER	Deformed	597.68 FL	*597.68 FL
16	2		*REAR BUMPER RETAINER L+R	Deformed	104.60 FL	*104.60 FL
17	1		*REAR BUMPER SPONGE	Deformed	92.76 FL	*92.76 FL
18	2		*REAR BUMPER BRACKET L+R	Not Necessary	130.20 FL	*- FL
19	1		*REAR BUMPER UNDER COVER	Not Necessary	231.20 FL	*- FL
20	2		*REAR FENDER COWLING L+R	Not Necessary	384.80 FL	*- FL
21	1		*END PANEL	Bent	218.75 FL	*218.75 FL
22	1		*END PANEL INNER PANEL	Bent	557.92 FL	*247.50 FL
23	1		*END PANEL TOP GARNISH	Deformed	78.45 FL	*78.45 FL
24	1		*FLOOR PANEL	Not Necessary	1,287.40 FL	*- FL
25	1		*EXHAUST PIPE	Not Necessary	835.79 FL	*- FL
26	1		*EXHAUST MOUNTING	Not Necessary	164.26 FL	*- FL
27	2		*EXHAUST HEAT SHIELD	Not Necessary	191.55 FL	*- FL
28	1		*TAILGATE WINDSCREEN SEALANT	Necessary	150.00 FS	*60.00 FS
29	1		*TAILGATE EMBLEM	Necessary	100.00 FS	*50.00 FS
30	1		*TAILGATE STICKER-SPEED	Necessary	80.00 FS	*20.00 FS
31	1		*TAILGATE STICKER-PAX	Necessary	80.00 FS	*20.00 FS
32	1		*REAR NUMBER PLATE	Not Necessary	100.00 FS	*- FS
33	4		*TAIL LAMP CLIPS	Not Necessary	40.00 FS	*- FS
34	2		*TAIL LAMP PANEL SEALANT	Not Necessary	240.00 FS	*- FS
35	10		*REAR BUMPER CLIPS	Necessary	100.00 FS	*30.00 FS
36	1		*REAR BUMPER REVERSE SENSOR SET	Not Working	300.00 FS	*200.00 FS
37	20		*REAR FENDER COWLING CLIPS	Not Necessary	200.00 FS	*- FS
38	1		*END PANEL SEALANT	Necessary	200.00 FS	*40.00 FS
39	1		*END PANEL INNER PANEL SEALANT	Necessary	200.00 FS	*40.00 FS
40	1		*FLOOR PANEL SEALANT	Not Necessary	300.00 FS	*- FS
41	1		*FLOOR PANEL TOP MAT	Torn	600.00 FS	*100.00 FS
42	1		*FLOOR PANEL TOP BOARD	Cracked	2,500.00 FS	*250.00 FS
43	1		*TAILGATE EMBLEM-NV200	Necessary	89.20 FL	*89.20 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>14,849.70</b>	<b>5,029.62</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	965.97	421.96

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
					<b>Total Parts (\$)</b>	<b>13,883.73</b>	<b>4,607.66</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	SPRAY PAINT ON AFFECTED AREAS	New	1,200.00	800.00
2	PANEL BEATING ON AFFECTED AREAS	New	1,400.00	800.00
3	TO RNR REAR EXHAUST	New	250.00	0.00
4	TO RNR REAR WINDSCREEN	New	350.00	120.00
5	TO CHECK WIRING AND TAILLAMP FUNCTION	New	150.00	30.00
6	TO UNLOAD AND UPHOLSTERY	New	400.00	80.00
7	TO CHECK WATER LEAK	New	150.00	40.00
8	TO RNR FUEL TANK	New	300.00	0.00
9	TO PERFORM DIAGNOSTIC AND CLEAR FAULTS	New	600.00	0.00
10	TO RNR REAR TAILGATE MECHANISM	New	350.00	60.00
11	TO RNR REAR REVERSE SENSOR AND CHECK FUNCTION	New	150.00	30.00
12	TO PERFORM RUST PROOFING	New	400.00	40.00
			<b>Gross Labour Cost (\$)</b>	<b>5,700.00</b>
				<b>2,000.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >