

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG20013180/GEA3Q2**Date:** 13/04/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070143292
Claimant Vehicle No :	XE4261B	Insured Vehicle No :	GBK6831Y
Date of Loss:	26/11/2020	Nature of Claim:	TP
		Claim No:	9470884947SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	XE4261B	Engine No:	D11440613
Make & Model:	VOLVO FMX370, 10.8 D 64R RSS SC (M)	Chassis No:	YV2X922D0JA826834
Reg. Date:	08/08/2018 (Man. Year: 2018)	Odometer:	0 km
Colour:	Red		
Engine Capacity:	10837 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	295/80 R22.5	Rear Tyre Size:	295/80 R22.5 (D)
Front Left Side:	TR912 6 mm	Rear Left Side:	TR912 6/6 mm
Front Right Side:	TR912 6 mm	Rear Right Side:	TR912 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	620.00	620.00	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,220.00	1,440.00	1,780.00	55.28
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,840.00	2,060.00	1,780.00	46.35
+ GST 7.00/7.00% (S\$)	268.80	144.20	124.60	46.35
Nett Amount (S\$)	4,108.80	2,204.20	1,904.60	46.35
+ Loss of Use (3.0 x S\$150.00/day) (S\$)		450.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		2,661.65		
Global Sum Settlement (S\$)		2,660.00		

INSPECTION

Date of Assignment:	01/12/2020		
Date Inspected:	14/12/2020	Inspected At:	SC Auto Industries (S) Pte Ltd (HQ) 51 Senoko Road, #03-01 Singapore 758133
Estimated Period of Repair:	2.0 days		

Adjuster: XING GUO QIANG**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LHS REAR MUDGUARD	Buckled	620.00 FS	*620.00 FS
			F=Franchise part. S=SpcNett.			
				Total Parts (\$\$)	620.00	620.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR FOR LHS PORTION	New	1,920.00	640.00
2	LABOUR FOR SPRAY PAINTING	New	1,300.00	800.00
Gross Labour Cost (S\$)			3,220.00	1,440.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >