### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd. Our File No:

AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Date: 25/01/2021

**REFERENCE** 

Insured/Claimant: NARENDRAN KRISHNAN Policy No: 1800145493

Date of Loss: 27/11/2020 Nature of Claim: OD Claim No: 3375466181SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SJS7088H

Make & Model: AUDI A3, 1.4 SEDAN TFSI (AMBIENTE) (A) Engine No: CZE846934

Reg. Date: 07/12/2018 (Man. Year: 2018) Chassis No: WAUZZZ8V7K1009015

Colour: White Odometer: 39850 km

Engine Capacity: 1395 cc
Market Value/New Car Price: \$\$94,000.00

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES** 

Front Tyre Size: 225/45R17 Rear Tyre Size: 225/45R17
Front Left Side: Yokohama 6 mm
Front Right Side: Yokohama 6 mm
Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		4,282.00	867.00	3,415.00	79.75
Miscellaneous Items		0.00	0.00	0.00	
Labour		3,872.00	2,072.00	1,800.00	46.49
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	8,154.00	2,939.00	5,215.00	63.96
	- Excess (S\$)	600.00	600.00	0.00	0.00
	(S\$)	7,554.00	2,339.00	5,215.00	69.04
	+ GST 7.00/7.00% (S\$)	528.78	163.73	365.05	69.04
	Nett Amount (S\$)	8,082.78	2,502.73	5,580.05	69.04

**INSPECTION** 

Date of Assignment: 02/12/2020

Premium Automobiles Pte Ltd (UBI)

CC3/AIG20013199/AVF3E2

Date Inspected: 01/12/2020 Inspected At: 55 Ubi Road 1 Singapore 408699

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING Manager: VERON CHEN

Please be informed that insured has withdrawn claim from Premium Automobile.

Report changed to "reporting only".

(REPAIR COST NOT CONCLUDE)
(EXCLUDE CHECK ITEMS \$\$200.00 NETT)

# **REPAIR DETAILS**

## **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	1,944.00 FS	*- FS
2	1		*REAR BUMPER FIXING PARTS	Not Necessary	191.00 FS	*- FS
3	1		*WHEEL HOUSING LINER ADAPTER-RH	Not Necessary	37.00 FS	*- FS
4	2		*REAR BUMPER GUIDE SECTION-LH/RH	Not Necessary	32.00 FS	*- FS
5	2		*REAR BUMPER LOCKING MECHANISM	Not Necessary	59.00 FS	*- FS
6	1		*REAR BUMPER SPOILER	Not Necessary	234.00 FS	*- FS
7	1		*REAR LIGHT REFLECTOR-RH	Not Necessary	41.00 FS	*- FS
8	1		*LED TAIL LIGHT-RH	Cracked	867.00 FS	*867.00 FS
9	1		*TAIL LIGHT TRIM-RH	Not Necessary	30.00 FS	*- FS
10	1		*REAR BUMPER GUIDE SECTION-RH	Not Necessary	66.00 FS	*- FS
11	1		*WHEEL HOUSING LINER-RH	Not Necessary	237.00 FS	*- FS
12	1		*WHEEL HOUSING LINER ATTACHMENT PART	Not Necessary	88.00 FS	*- FS
13	1		*REAR PARKING AID SENSOR-INNER/OUTER	Not Necessary	242.00 FS	*- FS
14	4		*REAR PARKING AID SEAL RING	Not Necessary	14.00 FS	*- FS
15	1		*SUNDRIES	*Check	200.00 FS	*- FS
F=Fra	anchise	part. S=SpcN	lett.	_		
				Total Parts (S\$)	4,282.00	867.00

Report was unsubmitted during this print-out.

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO REMOVE AND TRANSFER REAR PARKING AID.CHECK FUNCTI AND RENEW ACCORDING TO DAMAGE	<b>ON</b> New	280.00	280.00
2	TO DISMANTLE AND RENEW REAR BUMPER.TO REPAIR RHS REAFENDER.RE-ORGANISE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	AR New	1,400.00	500.00
3	TO RESPRAY REAR BUMPER AND RHS REAR FENDER	New	2,000.00	1,100.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
	Gross	Labour Cost (S\$)	3,872.00	2,072.00
	Report was unsubmitted during	this print-out.		

< END OF ESTIMATES >