

LKK Auto Consultants Pte Ltd

LKK Auto Consultants Pte L 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YN 7824Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT PANEL (WCP)	DENTED	750.00	750.00
10	FRONT PANEL CLIPS @\$5.00 (WCP)	NECESSARY	50.00	50.00
1	FRONT GRILLE (WCP)	BROKEN	550.00	550.00
10	FRONT GRILLE CLIPS @\$5.00 (WCP)	NECESSARY	50.00	50.00
1	FRONT CORNER PANEL (WCP)	CRUSHED	700.00	700.00
1	FRONT SIDE MIRROR BRACKET COVER (WCP)	BROKEN	60.00	60.00
1	FRONT SIDE MIRROR BRACKET ROUND COVER (WCP)	BROKEN	30.00	30.00
1	FRONT BUMPER (WCP)	CRUSHED	650.00	650.00
1	FRONT BUMPER BRACKET (WCP)	BENT	700.00	700.00
1	FRONT SIGNAL LAMP (WCP)	BROKEN	500.00	500.00
1	FRONT HEADLAMP (WCP)	BROKEN	1,500.00	1,500.00
1	FRONT PANEL (REWARD) STICKER (WCP)	NOT NECESSARY	35.00	-
1	FRONT CABIN TORSION BAR (WCP)	NOT NECESSARY	650.00	-
1	FRONT AIRCON PIPE (WCP)	NOT NECESSARY	560.00	-
	COST PLUS 15%		1,017.75	831.00
			7,802.75	6,371.00
	SPECIAL NETT ITEMS			
1	FRONT NUMBER PLATE (SN)	BENT	45.00	45.00
			45.00	45.00
	<u>LABOUR</u>			
	TO INSPECT FRONT LIGHTING WATER & LEAKAGE TEST.		40.00	30.00
	TO STRAIGHTEN FRONT BOTH CHASSIS MEMBER AND FRONT INNER PANEL & RENEW DAMAGED PARTS.		600.00	550.00
	TO SPRAY PAINT ON REPLACED, REPAIRED AREAS.		650.00	600.00
			1,290.00	1,180.00
	GRAND TOTAL		9,137.75	7,596.00

Report Ref No. CS/LPC20013200/Etf3e2



Page No.:2 of 2

RECOMMENDED COST OF REPAIRS		7,596.00
LESS EXCESS		-2,000.00
NETT LIABILITY		5,596.00

Report Ref No. CS/LPC20013200/Etf3e2



Automotive Assessor



ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser