

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933  
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way #07-16  
Singapore 079120

**Our File No:** CC3/AIG20013208/ETF3E2  
**Date:** 30/12/2020

### REFERENCE

Insured/Claimant: CHEW WEI AN Policy No: 1900121329  
Date of Loss: 01/12/2020 Nature of Claim: OD Claim No: 4277827376SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMM8794S**  
Make & Model: KIA CERATO, 1.6 (A) Engine No: G4FGKH741316  
Reg. Date: 18/07/2019 (Man. Year: 2018) Chassis No: KNAF3416MK5047096  
Colour: White Odometer: 27431 km  
Engine Capacity: 1591 cc  
Market Value/New Car Price: S\$74,000.00  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

### CONDITION OF TYRES

Front Tyre Size: 205/55R16 Rear Tyre Size: 205/55R16  
Front Left Side: Bridgestone 5 mm Rear Left Side: Bridgestone 5 mm  
Front Right Side: Bridgestone 5 mm Rear Right Side: Bridgestone 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	3,878.80	599.20	3,279.60	84.55
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,980.00	1,700.00	1,280.00	42.95
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>6,858.80</b>	<b>2,299.20</b>	<b>4,559.60</b>	<b>66.48</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>480.12</b>	<b>160.94</b>	<b>319.18</b>	<b>66.48</b>
<b>Nett Amount (S\$)</b>	<b>7,338.92</b>	<b>2,460.14</b>	<b>4,878.78</b>	<b>66.48</b>

### INSPECTION

Date of Assignment: 01/12/2020

Date Inspected: 01/12/2020 Inspected At:

Cycle & Carriage KIA Pte Ltd (Pandan Gardens)  
209 Pandan Gardens  
Singapore 609339

Estimated Period of Repair: 4.0 days

---

**Adjuster:** CHEN TSUE YEE

**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LAMP ASSY-HEAD,RH	Not Necessary	1,219.00 FL	*- FL
2	1		*PANEL-FENDER,RH	Dented	430.00 FL	*430.00 FL
3	1		*COVER-FR BUMPER	Repair	633.00 FL	*- FL
4	1		*GRILLE-FRONT BUMPER	Cut	262.00 FL	*262.00 FL
5	1		*AIR DUCT-FR BUMPER,RH	Not Necessary	14.00 FL	*- FL
6	1		*BRACKET-FR BUMPER UPR SIDE MTG	Not Necessary	22.00 FL	*- FL
7	1		*ORNAMENT-KIA NO.115	Necessary	32.00 FL	*32.00 FL
8	1		*KNUCKLE-FRONT AXLE,RH	Not Necessary	350.00 FL	*- FL
9	1		*HUB ASSY-FR WHEEL	Not Necessary	436.00 FL	*- FL
10	1		*GEAR ASSY-STEERING	Not Necessary	770.00 FL	*- FL
11	1		*STRUT ASSY-FR,RH	Not Necessary	280.00 FL	*- FL
12	1		*INSULATOR ASSY-STRUT	Not Necessary	85.00 FL	*- FL
13	1		*BEARING-STRUT	Not Necessary	86.00 FL	*- FL
14	1		*LINK-STABILIZER	Not Necessary	72.00 FL	*- FL
15	1		*GUARD ASSY-FRONT WHEEL,RH	Not Necessary	95.00 FL	*- FL
16	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>4,836.00</b>	<b>744.00</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	957.20	144.80
<b>Total Parts (\$\$)</b>	<b>3,878.80</b>	<b>599.20</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	REPLACE FRT RH FENDER,FRT BUMPER & AFFECTED AREA	New	1,200.00	400.00
2	PAINT WORK ON FRT BUMPER & FRT RH FENDER	New	700.00	700.00
3	PERFORM RUST PREVENTION	New	80.00	0.00
4	TO CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT	New	120.00	120.00
5	TO TRANSFER FRT RH RIM INCLUDING BALANCING	New	30.00	30.00
6	TO REPLACE FRT UNDERCARRIAGE	New	400.00	0.00
7	TO SUPPLY FRT RH SPORT RIM	New	300.00	300.00
8	CHECK WIRING & CHASSIS ELECTRICAL SYSTEM (SUPPLEMENTARY)	New	30.00	30.00
9	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST (SUPPLEMENTARY)	New	120.00	120.00
			<b>Gross Labour Cost (\$\$)</b>	<b>2,980.00</b>
				<b>1,700.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >