

ASS. REC. BY:

REF:

ERG

CS/EGI20013211/Kqd3

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. CDMPG20001783

Sum Insured: _____


Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

09

days

Res.: Yes or No

Lum Sum: _____

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: _____

S14C 55657

Yr Regn: _____

08, 14

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: _____

Meralt Latitude

c.c

1995

Colour: _____

M. White / Red

A/C: _____

Insured / Std / NI / NA

Sp. Reading: _____

645203

T/Radio: _____

Insured / Std / NI / NA

Eng/No: _____

C/No: _____

VF1A9L15AUC

278902

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: M / S / R / m / STD A / R / m or

Tyre Size: _____

F: _____

215/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Pailun

Front

Rear

R/Bal. _____

P

mm

R/Bal. _____

P

mm

L/Bal. _____

P

mm

L/Bal. _____

P

mm

D.O.A. _____

29/11/20

D.O.I. _____

1/12/2020

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

03/12/20@12.44pm revised to ERGO via Merimen.

25/01/21@2.36pm confirmed with Wai Yin 'Ls \$8950, 9 days (Red \$14556.17, 62%)

04/03/21@12pm Re-confirmed with Wai Yin LS \$8000, 9 days (Red \$15506.17, 66%)

Date/Time, File Pass to?

☐

: Prel. Report

1) 04/03 Typist

☐

: Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 9

Resurvey No. of Trip: _____

Add Fee: _____

Site Insp (\$ _____)

Interview (\$ _____)

Tech Invs (\$ _____)

Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

S - RS. \$ _____

Fees: _____

Others: _____

TOTAL

Report Format: _____

MER-TP

Lump Sum H.B. (\$ _____)

8000

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5565T**AAD2011-***Not Authorised*
L/Lump &

Vehicle No.:

Chassis No.:

Vehicle Make:

01 DEC 2020

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHC5565T

VF1ABL15AUC278902

RENAULT

LATITUDE

29.11.2020.**ER60****15/08/2014**

PART		LIST	
1	1 BUMPER COVER REAR	\$	<i>B₂</i> 561.70 <i>✓</i>
2	1 BUMPER LOWER REAR	\$	<i>B₂</i> 411.90 <i>✓</i>
3	1 BUMPER BRACKET CTR REAR	\$	<i>CM</i> 98.10 <i>✓</i>
4	1 BUMPER BRACKET SIDE RH REAR	\$	<i>S₂</i> 82.10 <i>X</i>
5	1 BUMPER RETAINER RH REAR	\$	<i>S₂</i> 59.80 <i>X</i>
7	1 BUMPER BRACKET SIDE LH REAR	\$	<i>Dir</i> 80.80 <i>✓</i>
8	1 BUMPER RETAINER LH REAR	\$	<i>CM</i> 54.20 <i>✓</i>
10	1 BUMPER BEAM REAR	\$	<i>B₂</i> 547.80 <i>✓</i>
11	1 BUMPER BEAM BRACKET LH REAR	\$	<i>B₂</i> 114.50 <i>✓</i>
12	1 BUMPER BEAM BRACKET RH REAR	\$	<i>B₂</i> 114.50 <i>✓</i>
13	1 BUMPER REFLECTOR LH	\$	<i>CM</i> 16.60 <i>✓</i>
14	1 BUMPER REFLECTOR RH	\$	<i>S₂</i> 16.60 <i>X</i>
15	1 OUTER PANEL REAR (End Panel)	\$	<i>B₂</i> 745.80 <i>✓</i>
16	1 OUTER PANEL REAR (End Panel)TRIM	\$	<i>Del</i> 404.56 <i>✓</i>
17	1 BOOT REAR	\$	<i>B₂</i> 1,677.20 <i>✓</i>
18	1 BOOT WEATHERSTRIP	\$	<i>Dir Mod</i> 178.20 <i>50 B₂</i>
19	1 BOOT REFLECTOR LAMP LH	\$	<i>CM</i> 277.70 <i>✓</i>
20	1 BOOT REFLECTOR LAMP RH	\$	<i>CM</i> 277.70 <i>✓</i>
21	1 BOOT HINGE LH	\$	<i>N</i> 254.20 <i>X</i>
22	1 BOOT HINGE RH	\$	<i>N</i> 254.20 <i>X</i>
23	1 BOOT LOCK	\$	<i>N</i> 246.60 <i>X</i>
24	1 BOOT LOCK CATCH	\$	<i>N</i> 41.70 <i>X</i>
25	1 BOOT FINISHER	\$	<i>S₂</i> 344.70 <i>X</i>
26	1 BOOT BADGE 'RENAULT'	\$	<i>N₂</i> 82.40 <i>✓</i>
27	1 BOOT BADGE	\$	<i>N₂</i> 95.80 <i>✓</i>
28	1 BOOT FINISHER	\$	<i>S₂</i> 344.70 <i>X</i>
29	1 TAILLAMP RH	\$	<i>Mjcm</i> 401.40 <i>✓</i>
30	1 TAILLAMP LH	\$	<i>cmf</i> 401.40 <i>✓</i>

Trans-cab Auto Services Pte Ltd

AAD2011-

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5565T

31	1 FENDER PANEL REAR LH	\$	<i>br</i> 1,933.20 ✓
32	1 WHEELARCH REAR LH	\$	<i>br</i> 275.40 X
33	1 SPARE TYRE BOARD	\$	<i>br</i> 680.90 X
34	1 SPARE WHEEL PANEL	\$	<i>n</i> 1,229.40 ✓
35	1 SPARE WHEEL PANEL BRACKET LH L70Y	\$	<i>n</i> 70.60 X
36	1 SPARE WHEEL PANEL BRACKET RH L70Y	\$	<i>n</i> 69.20 X

\$	8,186.86
10% \$	818.69
\$	<u>7,368.17</u>

Specical Nett

1	1SET PARKING AID	\$	<i>Short</i> 700.00 <i>400in</i>
2	1 BOOT FINISHER NUT L70Y	\$	<i>na</i> 60.00 X
3	1SET REAR BUMPER CLIP	\$	<i>na</i> 66.00 ✓
4	1SET BUMPER BRACKET CTR CLIP	\$	<i>na</i> 33.00 X
5	1SET BUMPER BRACKET SIDE CLIP RH RR	\$	<i>na</i> 10.00 X
6	1SET BUMPER RETAINER RH CLIP RR	\$	<i>na</i> 20.00 X
7	1SET BUMPER BRACKET SIDE CLIP LH RR	\$	<i>na</i> 10.00 X
8	1SET BUMPER RETAINER CLIP LH RR	\$	<i>na</i> 20.00 X
9	1SET BUMPER LOWER REAR RIVET	\$	<i>na</i> 22.00 X
10	1SET BUMPER LOWER REAR CLIP	\$	<i>na</i> 66.00 ✓
11	1SET WHEELARCH CLIP	\$	<i>na</i> 60.00 X
12	1SET FENDER CLIP	\$	<i>na</i> 35.00 X
13	1 EXHAUST MOUNTING REAR	\$	<i>br</i> 17.82 X
14	1 REAR NUMBER PLATE WITH HOLDER	\$	<i>na</i> 120.00 <i>45na</i>
15	1 REAR BOOT STICKER 'Trans-cab'	\$	<i>na</i> 80.00 <i>30na</i>
16	1 REAR BOOT STICKER '6555-3333'	\$	<i>na</i> 80.00 <i>30na</i>
17	2 WINDSCREEN SEALANT	\$	<i>na</i> 150.00 <i>40na</i>
18	1 WINDSCREEN MOULDING	\$	<i>na</i> 200.00 X
19	1 WINDSCREEN INNER SPONGE SEAL	\$	<i>na</i> 130.00 <i>30na</i>
TOTAL		\$	<u>1,399.82</u>
TOTAL PARTS		\$	<u>8,767.99</u>

LABOUR

Putty And Spray Painting Of The Affected Portion.	\$	3,000.00 <i>1100/</i>
---	----	-----------------------

Trans-cab Auto Services Pte Ltd

AAD2011-

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5565T

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	3,000.00	1400
To Remove And Refit Rear W/Screen Glass To Facilitate Bodywork Repair.	\$	300.00	120
To Rust-Proofing Of The Affected Areas.	\$	170.00	90
To reinstall rear bumper parking sensor.	\$	170.00	60
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	60
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	100
To check steering geometry and computer wheel alignment	\$	220.00	X
To Check Electrical Lighting Concerned.	\$	170.00	20

TOTAL \$ 7,370.00**Over All Total \$ 23,506.17****(LUMP SUM)
Repair Days****28 DAYS****9 days**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

For Official Use

Acknowledged by Repairer

Signature:

Date:

Prepared By : _____
(Accident Dept)