威利摩哆 WEI LEE MOTOR WORKS

BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32, SINGAPORE 575644.

TEL: 6456 9830 • FAX: 6458 0128 • EMAIL: weileemotorworks@gmail.com Business Regn No: 269436/00J

Not Nothanker

USay & 300ch Max

Resurry After Paint

Hance notify 8day,

30,NOV 2020

China Taiping Insurance (S) PL 105 Cecil Street #18-00 The Octagon S 069534

Attn: Motor claim dept-3rd party claim

Claiming against your insured vehicle no: GY6984G

Accident involving vehicle no: SGF7450Z/GY6984G

DOA: 27112020 AT Orahard Boulevard after Grange Road, before Orchard Turn

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
 To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- . Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Dear officer incharge

Re: Estimate cost of repair to SGF7450Z

To supply--

Description	Description Qty						Amount		
Rear bumper				1		nit	482.00	_	
Rear bumper enforcement/sponge						NIP	123.50	X	
Rear bumper retainer	, -, - 0	@69.80		2		cm	139.60		
End panel	diament of			1	Pro 1	By	580.60		
End panel top garnish	-iV-			1	1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1	ni	202.70		
Taillamp	Carrie	@409.90		2	The Mark Hand	em	819.80		
Taillamp lower panel	\$x	@57.302		2	90 m32, -	BI	114.60		
Rear fender,Lh	r			1	NOT NOT THE	Bur	918.00		
Rear bumper clip	17-6		U.		3 44 5 5 6 6	m	38.00		
Tailgate				1	किसी पित	21	618.50		
Tailgate outer handle	2			1		ap	232.50		
Tailgate reflector	<u> </u>	@171.60	NISSOR	2	olsen		343.20	し	
Tailgate- 1.6 emblem				1	1.72	nex			
Tailgate-Corolla emblem				1	7 78,2	m	46.60		
Tailgate-Altis emblem	3 (2)			1	7	us!	45.60		
Tailgate-TOYOTA logo	(d.)			1	4, 4, ,	ne.	158.30	*	
Tailgate hinge	20-	@72.20		2		K	144.40	50%	
Tailgate weather strip		10		1	Dist	61	184.70 580.0	101	
Parts	(V				Jan Grand	5	,126.50		
Parts less 25%	4.1.			11.1.1.2.2.2.		1,281.62			
	4.			1. 1. 1. 1.		3,844.88			
	f).					218.1			
	- F.				Party Jak	10 - 1	* 118.6		
	N.				10.70 (DV)		618.		

33.

Soudhit

				327,	
				3.1.	
				Δű.t	
1		***		5013511	
			1	458.3	
/		10	1	144.8	
/				180.6	
		1.	7		2100
Reverse	sensor	2		5.120.00	1001A/-
To romo	ve/reinstall rear w	vindscreen glass		180.00	2001AI- 1201-
To remo	ive/Tellistali Teal W	hit.		3,84%	1
To remo	ve damaged parts	n attachments	tange of the control of	028	
Cur n w	eld damaged pane	l,fender	Sansabar at L	35.1	
Repair/	reshape damaged :	spare tyre panel	that the	613.	
Repair/	reshape all dented	areas		237	
Straight	en rear chassis wh	ere necessary		7.6%	12001
Penlace	/align all parts into	position	a game and	1,400.00	120d. 100d.
				1,200.00	10001.
To spra	у раше	1	1 m m m m m 1		
		, in	f.,	6,844.88	
			m. 4.5. (2.1.4) (2.1.4) mag. (3.1.4)	111.	
		7.3		184.	
			destroyed	22%(4%	
				5,035.	
		scre		1.141.	
			a same and	2 04 s.	
		.n.		17.7.	
		40	7	3	
		75	1837	41.18.1	
		.5		1000	
		5.	- KA	1 100	
		ti	40470	1,400.	
		**		1,200.	
				P.4449.4	
		7.3		134.5	
		1000		187. 1970)* 5.775	
				1961	
		, j. r		5,7757	
		scre-		13850 1.5	
		1.77		1,3 10.	
		k fy:			
			gaman ni is	111	
		A.	ipm, man di	6.,18.7	
		\$		111	
				100	
				1,400	
				1,790	
		fre		6.5%	
				G.Sope 5	
		1414		7 141	
				$-\mathbf{j}_{\mathcal{D}L}$	
				2000	
		3		1, 11%	
		Serv		187	
		783		7.711	
		47.	1.50 .00 . 1		