



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

| Invoice Name & Address | Owner Name & Vehicle Info |
|--|--|
| AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000 | Cust No/Name /TAN TONG LING Reg No/Reg Date SMH626Z / 10/01/201 Date In/Mileage / 14481 Chassis No KNAF3416MK5023986 Engine No G4FGJH713013 Make/Model KIA/CERATO 1.6 A EX G333 Colour/Trim CR5 RUNWAY RED / WK SATURN BLACK |

| Account No | Terms | Date/Time Printed | CSE | Operator | WIP No |
|------------|--------|-------------------|-----|-------------------|--------|
| LAX00000 | Credit | 01/12/2020/ 15:51 | BLE | 261 / Edwin Caina | 25127 |

| Description of Goods / Services | Qty | Unit Price | Disc% | Amount |
|--|------|------------|-------|-------------|
| E PNT88000 RENEW FRT DOOR RH & WINGMIRROR ASSY RH | | | | 470 1250.00 |
| E PNT98000 RESpray FRT DOOR RH & WINGMIRROR RH | | | | 580 700.00 |
| E PNT88000 REMOVE & REFIT RH F DOOR COMPONENTS | | | | 120.00 |
| A 54900099 CHECK WIRING ELECTRICAL SYSTEM | | | | 30.00 |
| A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST | | | | 120.00 |
| M SUNDRY Sundries | | | | 20.00 |
| M MIRROR ASSY-OUTSIDE RR VIEW RH | 1.00 | 559.00 | 20.00 | 447.20 |
| M PANEL ASSY-FRONT DOOR, RH | 1.00 | 1277.00 | 20.00 | 1021.60 |
| M HINGE ASSY-FRT DOOR UPP, RH | 1.00 | 30.00 | 20.00 | 24.00 |
| M HINGE ASSY-FRT DOOR LWR, RH | 1.00 | 27.00 | 20.00 | 21.60 |
| M BLACK TAPE-FR DR RR, RH | 1.00 | 13.00 | 20.00 | 10.40 |
| M MOULDING ASSY-FRT DR FRAME, RH | 1.00 | 37.00 | 20.00 | 29.60 |
| M W/STRIP ASSY-FR DR BELT O/S RH | 1.00 | 64.00 | 20.00 | 51.20 |

SURVEYOR NAME: Stef (LKK)
SURVEYOR SIGNATURE: OD - Not All
DATE: 1/12/20, 4.10pm
REMARKS: 3 days

Confirm & accepted by
LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Nett 3,845.60
7% GST on 3845.60 269.19
Total Payable 4,114.79