

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20013226/GQD3Q2

Date: 18/02/2021

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd.	Policy No: DMPCSNA00143242004	
Claimant Vehicle No : SJM1315Z	Insured Vehicle No : SJG4846U	
Date of Loss: 29/11/2020	Nature of Claim: TP	Claim No: SNM20D204654/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJM1315Z		
Make & Model: BMW 316I, 1.6 (A)	Engine No: A667J746N13B16A	
Reg. Date: 22/08/2014 (Man. Year: 2014)	Chassis No: WBA3A16010NS37863	
Colour: White	Odometer: 140463 km	
Engine Capacity: 1598 cc		
Market Value/New Car Price: N/A		
Sum Insured (\$\$): Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45ZR18	Rear Tyre Size: 225/45ZR18
Front Left Side: KAPSEN 5 mm	Rear Left Side: KAPSEN 5 mm
Front Right Side: KAPSEN 5 mm	Rear Right Side: KAPSEN 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,013.71	4,593.51	1,420.20	23.62
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,230.00	1,040.00	190.00	15.45
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	7,243.71	5,633.51	1,610.20	22.23
+ GST 7.00/7.00% (\$\$)	507.06	394.35	112.71	22.23
Nett Amount (\$\$)	7,750.77	6,027.86	1,722.91	22.23

INSPECTION

Date of Assignment: 09/12/2020		
Date Inspected: 01/12/2020	Inspected At:	Sin Motor Repairs (HQ) BLK 176 Sin Ming Drive,, Sin Ming Auto Care #05-07 Singapore 575721
Estimated Period of Repair: 5.0 days		

Adjuster: XING GUO QIANG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 10 Feb 2021)
Parts:	143	BMW 316I 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJM1315Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,178.85 FL	*1,178.85 FL
2	1		*REAR BUMPER BRACKETS	Bent (1 Pc only)	112.00 FL	*55.75 FL
3	1		*REAR BUMPER REFLECTOR-LH	Missing	37.75 FL	*37.75 FL
4	1		*REAR REVERSE SENSOR	Damaged	236.85 FL	*236.85 FL
5	1		*REAR BUMPER REINFORCEMENT	Bent	423.22 FS	*100.00 FS
6	1		*FRONT BUMPER	Deformed	1,037.50 FL	*1,037.50 FL
7	1		*BONNET (NPA)	Repair	0.00 FL	*- FL
8	1		*EXHAUST PIPE	Repair	1,020.20 FL	*- FL
9	1		*HEAT SHIELD	Buckled	88.65 FL	*88.65 FL
10	1		*HEAD LAMP LH	Broken	2,130.35 FL	*2,130.35 FL
11	1		*REAR EXHAUST PIPE CHROME	Cut	180.00 FL	*90.00 FL
12	1		*REAR BUMPER INNER CENTRE BRACKET	Cracked	72.65 FL	*72.65 FL
13	1		*REVERSE SENSOR BRACKET	Necessary	55.74 FL	*20.00 FL
14	1		*FRONT NUMBER PLATE AND CASING	Bent	55.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,628.76	5,088.35
- List Item Discount on L Items 10.00/10.00% (\$\$)	615.05	494.84
Total Parts (\$\$)	6,013.71	4,593.51

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	ADJUSTMENT OF REAR ALIGNMENT	New	80.00	0.00
2	TO DETECT BUMPER SENSOR	New	100.00	40.00
3	KNOCKING,RE-INSTALLATION OF FRONT BONET/FRONT/REAR BUMPER,REAR REVERSE SENSOR	New	450.00	400.00
4	SPRAY PAINTING ON FRONT/REAR BUMPER/REVERSE SENSOR/TOUCH UP ON NECESSARY PARTS	New	600.00	600.00
Gross Labour Cost (\$)			1,230.00	1,040.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >