

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/III20013235/ABS3Q2
Date: 08/07/2021**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D19MCV0000121_01
Claimant Vehicle No :	SLA9800B	Insured Vehicle No :	GU857B
Date of Loss:	30/11/2020	Nature of Claim:	TP
		Claim No:	MCV2020D0002583

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLA9800B		
Make & Model:	TOYOTA CAMRY, 2.0 ABS AIRBAG (A)	Engine No:	1AZE129836
Reg. Date:	26/02/2009 (Man. Year: 2009)	Chassis No:	MR053BK4107042653
Colour:	White	Odometer:	149210 km
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,176.35	6,094.17	4,082.18	40.11
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,810.00	2,560.00	1,250.00	32.81
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,986.35	8,654.17	5,332.18	38.12
Approved Total (Overridden) (S\$)		6,900.00		

Nett Amount (S\$)	13,986.35	6,900.00	7,086.35	50.67
+ Loss of Use (10.0 x S\$120.00/day) (S\$)		1,200.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		8,107.45		
Global Sum Settlement (S\$)		8,000.00		

INSPECTION

Date of Assignment: 01/12/2020

Date Inspected: 01/12/2020

Estimated Period of Repair: 9.0 days

Inspected At:

Choo Motor Spray Painter (HQ)
 1 Kaki Bukit Avenue 6, #01-39 AutoBay @ Kaki Bukit
 Singapore 417883

Adjuster: ADRIAN LING**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 03 Jun 2021)
Parts:	143	TOYOTA CAMRY 2.0 ABS AIRBAG (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLA9800B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT	Distorted	1,012.30 FL	*1,012.30 FL
2	1		*REAR BOOT LOCK	Damaged	892.20 FL	*381.00 FL
3	1		*REAR BOOT CENTRE EMBLEM	Necessary	77.40 FL	*77.40 FL
4	1		*REAR BOOT EMBLEM (CAMRY)	Necessary	58.50 FL	*58.50 FL
5	1		*REAR BOOT EMBLEM (2.0)	Necessary	48.20 FL	*48.20 FL
6	1		*REAR BOOT CENTRE EMBLEM	Necessary	77.40 FL	*77.40 FL
7	2		*REAR BOOT REFLECTOR LAMP	N/S Cut / O/S Cracked	798.80 FL	*660.00 FL
8	1		*REAR BOOT RUBBER	Cut	207.30 FL	*207.30 FL
9	2		*REAR TAIL LAMP	N/S Cut / O/S Smashed	991.40 FL	*991.40 FL
10	1		*REAR TAIL LAMP LOWER BRACKET	O/S Cracked	50.40 FL	*25.20 FL
11	1		*REAR END PANEL	Distorted	647.30 FL	*647.30 FL
12	1		*REAR END PANEL TOP GARNISH	Deformed	421.30 FL	*383.00 FL
13	1		*REAR FENDER	O/S Buckled	2,460.40 FL	*1,230.20 FL
14	1		*REAR FENDER INNER GARNISH	O/S Deformed	868.60 FL	*388.00 FL
15	1		*REAR SPARE TYRE PANEL	Repair	1,023.60 FL	*- FL
16	1		*REAR SPARE TYRE PANEL TOP COVER BOARD	Torn	244.80 FL	*244.80 FL
17	1		*REAR BUMPER	Distorted	725.50 FL	*580.00 FL
18	1		*REAR BUMPER SIDE RETAINER	O/S Damaged	206.20 FL	*65.00 FL
19	1		*REAR BUMPER TOWING COVER	Not Necessary	26.50 FL	*- FL
20	1		*REAR BUMPER REINFORCEMENT	Bent	561.30 FL	*392.00 FL
21	1		*REAR BUMPER REFLECTOR	O/S Cracked	130.40 FL	*65.20 FL
22	1		*REAR EXHAUST SILENCER	Not Necessary	981.70 FL	*- FL
23	2		*REAR EXHAUST RUBBER	Not Necessary	121.60 FL	*- FL
24	1		*REAR EXHAUST CHROME TAIL PIPE	Cut	98.70 FL	*98.70 FL
25	12		*REAR FENDER INNER GARNISH CLIPS	Necessary	78.00 FS	*30.00 FS
26	3		*REAR END PANEL TOP GARNISH CLIPS	Necessary	19.50 FS	*19.50 FS
27	1		*REAR END PANEL SEALANT	Necessary	80.00 FS	*60.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
28	1		*REAR GLASS SEALANT	Necessary	100.00 FS	*60.00 FS
29	1		*SET REAR BUMPER REVERSE SENSOR	Damaged	350.00 FS	*200.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$)					13,359.30	8,002.40
- List Item Discount on L Items 25.00/25.00% (\$)					3,182.95	1,908.23
Total Parts (\$)					10,176.35	6,094.17

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING	New	180.00	30.00
2	TUFF KOTE	New	150.00	100.00
3	REMOVE AND REFIX UPHOLSTERY AND ROOF LINING	New	160.00	80.00
4	REMOVE AND REPLACE EXHAUST PIPE	New	160.00	0.00
5	REMOVE AND REPLACE REVERSE SENSOR	New	160.00	50.00
6	TO REMOVE AND REPLACE SPARE PART AND PANEL BEATING	New	1,500.00	1,200.00
7	TO SPRAY PAINTING AND ETC	New	1,500.00	1,100.00
Gross Labour Cost (S\$)			3,810.00	2,560.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >