

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CS/AIG20013242/EQD3E2
Date: 30/12/2020

REFERENCE

Insured/Claimant:	WONG SOOK LENG	Policy No:	1800085929	Claim No:	0495508771SG
Date of Loss:	29/11/2020	Nature of Claim:	OD		

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMC8687X	Engine No:	3A92UGY1382
Make & Model:	MITSUBISHI ATTRAGE, 1.2 CVT (A)	Chassis No:	MMBSTA13AJH002253
Reg. Date:	26/07/2018 (Man. Year: 2018)	Odometer:	47015 km
Colour:	Silver		
Engine Capacity:	1193 cc		
Market Value/New Car Price:	S\$50,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	185/55R15	Rear Tyre Size:	185/55R15
Front Left Side:	Yokohama 5 mm	Rear Left Side:	Yokohama 5 mm
Front Right Side:	Yokohama 5 mm	Rear Right Side:	Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,714.90	3,431.87	2,283.03	39.95
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,415.00	2,615.00	800.00	23.43
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,129.90	6,046.87	3,083.03	33.77
- Excess (S\$)	300.00	300.00	0.00	0.00
(S\$)	8,829.90	5,746.87	3,083.03	34.92
+ GST 7.00/7.00% (S\$)	618.09	402.28	215.81	34.92
Nett Amount (S\$)	9,447.99	6,149.15	3,298.84	34.92

INSPECTION

Date of Assignment: 02/12/2020

Date Inspected:	02/12/2020	Inspected At:	Cycle & Carriage Automotive Pte Ltd (Pandan Gardens)
Estimated Period of Repair:	3.0 days		209 Pandan Gardens
			Singapore 609339

Adjuster: CHEN TSUE YEE

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEADLAMP ASSY,LH	Not Necessary	660.00 FL	*- FL
2	1		*FACE,FR BUMPER	Broken	703.00 FL	*703.00 FL
3	1		*COVER,HEADLAMP SUPT PANEL	Not Necessary	62.00 FL	*- FL
4	1		*GRILLE,FR UNDER	Broken	165.00 FL	*165.00 FL
5	1		*BRACKET,FR BUMPER,LH	Not Necessary	13.00 FL	*- FL
6	1		*AIR DAM,SIDE,FR LH	Not Necessary	18.00 FL	*- FL
7	1		*GRILLE,RADIATOR	Broken	554.00 FL	*554.00 FL
8	1		*MARK,THREE-DIA	Necessary	69.00 FL	*69.00 FL
9	1		*REINFORCEMENT,FR BUMPER	Not Necessary	466.00 FL	*- FL
10	1		*UNPAINTED BODYKITS	Not Necessary	1,643.00 FN	*- FN
11	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
12	1		*PANEL ASSY, FR END (Supplementary)	Dented	1,055.00 FL	*1,055.00 FL
13	1		*RADIATOR ASSY (Supplementary)	Broken	967.00 FL	*967.00 FL
14	1		*CONDENSER ASSY, A/C REFRIGE (Supplementary)	Bent	758.00 FL	*758.00 FL
15	1		*PANEL, AIR GUIDE (Supplementary)	Broken	112.00 FL	*112.00 FL
16	1		*PANEL, AIR GUIDE, RH (Supplementary)	Broken	11.00 FL	*11.00 FL
17	1		*PANEL, AIR GUIDE, LH (Supplementary)	Broken	11.00 FL	*11.00 FL
18	1		*LLC 4L (Supplementary)	Necessary	26.00 FL	*26.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.

Sub Total (\$\$)	7,343.00	4,451.00
- List Item Discount on L Items 23.00/23.00% (\$\$)	1,299.50	1,019.13
- Nett Item Discount on N Items 20.00/20.00% (\$\$)	328.60	0.00
Total Parts (\$\$)	5,714.90	3,431.87

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPLACE FRT BUMPER,BODY KIT & AFFECTED AREA	New	900.00	450.00
2	TO SUPPLY FRT NUMBER PLATE WITH FRAME	New	50.00	50.00
3	PAINT WORK ON FRT BUMPER & BODY KIT	New	700.00	350.00
4	CHECK WIRING & CHASSIS ELECTRICAL SYSTEM	New	30.00	30.00
5	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
6	REPAIR ON BONNET (Supplementary)	New	225.00	225.00
7	RESPRAY ON BONNET (Supplementary)	New	350.00	350.00
8	REPLACE FRONT SUPPORT PANEL (Supplementary)	New	450.00	450.00
9	RESPRAY ON FRONT SUPPORT PANEL (Supplementary)	New	350.00	350.00
10	REMOVE & INSTALL RADIATOR, A/COND CONDENSER TO FACILITATE REPAIR (Supplementary)	New	120.00	120.00
11	PERFORM RUST PREVENTION ON AFFECTED AREAS. (Supplementary)	New	40.00	40.00
12	VACUUM & TOP UP A/COND GAS (Supplementary)	New	80.00	80.00
Gross Labour Cost (S\$)			3,415.00	2,615.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >