Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20013249/ATD3Q2

Date: 25/02/2021

REFERENCE

China Taiping Insurance Policy No: Handling Insurer:

(Singapore) Pte. Ltd.

DMPCSNW00005332000

Claimant Vehicle No:

SGF7231P

Insured Vehicle No:

SMN5436R

Date of Loss:

29/11/2020

Nature of TP

Claim:

Claim SNM20D204665/C02/LEWLC

No:

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGF7231P**

Make & Model: HONDA FIT, 1.3 (A) Engine No: L13B1454339 Reg. Date: 09/04/2019 (Man. Year: 2019) Chassis No: GK31345708 Colour: Odometer: 29354 km Blue

Engine Capacity: 1317 cc Market Value/New Car Price: N/A

Market Value/New Car Price Sum Insured (S\$):

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/55R15 Rear Tyre Size: 195/55R15 Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm Front Right Side: Rear Right Side: Yokohama 6 mm Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,503.76	1,722.56	781.20	31.20
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,230.00	730.00	500.00	40.65
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,733.76	2,452.56	1,281.20	34.31
Approved Total (Overridden) (S\$)		1,950.00		
(S\$)	3,733.76	1,950.00	1,783.76	47.77
+ GST 7.00/7.00% (S\$)	261.36	136.50	124.86	47.77
Nett Amount (S\$)	3,995.12	2,086.50	1,908.62	47.77

INSPECTION

Date of Assignment: 02/12/2020

J-mart Motor Pte Ltd (HQ) Date Inspected: 02/12/2020 Inspected At:

Blk 5 Defu Lane 10, #01-578

Singapore 539186

Estimated Period of Repair: 4.0 days

Manager: DENISE TAY KWEE CHENG Adjuster: ADRIAN LING

Adjuster Report Page 2 of 4

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 25 Feb 2021)

Parts: 144 HONDA FIT 1.3 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SGF7231P)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LH HEADLAMP	Cracked	836.20 FL	*836.20 FL
2	1		*FRT BUMPER	Deformed	636.90 FL	*532.00 FL
3	1		*FRT BUMPER LH RETAINER	Necessary	78.00 FL	*35.00 FL
4	1		*FRT LH FENDER	Repair	468.20 FL	*- FL
5	1		*FRT LH FENDER INNER SHIELD	Not Necessary	79.20 FL	*- FL
6	8		*FRT LH FENDER INNER SHIELD CLIPS	Not Necessary	31.20 FL	*- FL
7	1		*FRT LH TYRE	Cut	400.00 FS	*200.00 FS
8	1		*FRT LH RIM	Cut	400.00 FS	*400.00 FS
F=Fra	anchise	part. S=Spcl	Nett. L=ListItemDisc.	_		
				Sub Total (S\$)	2,929.70	2,003.20
- List Item Discount on L Items 20.00/20.00% (S\$)_				425.94	280.64	
				Total Parts (S\$)	2,503.76	1,722.56

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount			
Lab	Labour Items						
1	PANEL BEATING	New	600.00	300.00			
2	SPRAY PAINTING	New	600.00	400.00			
3	WIRING	New	30.00	30.00			
		Gross Labour Cost (S\$)	1,230.00	730.00			
	F	Report was unsubmitted during this print-out.					

< END OF ESTIMATES >