

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CS/AIG20013253/EQD3E2

Date: 23/12/2020

REFERENCE

Insured/Claimant:	PANG CHUAN HUNG	Policy No:	1900256421		
Date of Loss:	01/12/2020	Nature of Claim:	OD	Claim No:	7048119873SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMQ8861K		
Make & Model:	MITSUBISHI ATTRAGE, 1.2 CVT (A)	Engine No:	3A92UJB1635
Reg. Date:	09/12/2019 (Man. Year: 2019)	Chassis No:	MMBSTA13AKH003362
Colour:	Grey	Odometer:	13529 km
Engine Capacity:	1193 cc		
Market Value/New Car Price:	S\$55,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/55 R15	Rear Tyre Size:	185/55 R15
Front Left Side:	Bridgestone 5 mm	Rear Left Side:	Bridgestone 5 mm
Front Right Side:	Bridgestone 5 mm	Rear Right Side:	Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,321.51	2,291.51	30.00	1.29
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,600.00	2,210.00	1,390.00	38.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,921.51	4,501.51	1,420.00	23.98
+ GST 7.00/7.00% (S\$)	414.51	315.11	99.40	23.98
Nett Amount (S\$)	6,336.02	4,816.62	1,519.40	23.98

INSPECTION

Date of Assignment: 02/12/2020

Date Inspected: 03/12/2020 Inspected At:

Cycle & Carriage Automotive Pte Ltd (Pandan Gardens)
209 Pandan Gardens
Singapore 609339

Estimated Period of Repair: 3.0 days

Adjuster: CHEN TSUE YEE

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
2	1		*LAMP ASSY, COMB, RR LH	Broken	335.00 FL	*335.00 FL
3	1		*BRACKET, RR BUMPER, LH	Broken	28.00 FL	*28.00 FL
4	1		*FACE, RR BUMPER	Dented	748.00 FL	*748.00 FL
5	1		*UNPAINTED BODYKITS	Broken	1,643.00 FN	*1,643.00 FN
6	1		*BUZZER, KEYLESS OPERATIO, RR (Supplementary)	Broken	91.00 FL	*91.00 FL
7	1		*MUD GUARD, RR LH (Supplementary)	Broken	41.00 FL	*41.00 FL
F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.						
Sub Total (S\$)					2,936.00	2,906.00
- List Item Discount on L Items 23.00/23.00% (S\$)					285.89	285.89
- Nett Item Discount on N Items 20.00/20.00% (S\$)					328.60	328.60
Total Parts (S\$)					2,321.51	2,291.51

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPLACE REAR BUMPER, BODYKIT & AFFECTED AREA. REPAIR ON REAR LH FENDER	New	1,800.00	450.00
2	PAINT WORK ON REAR BUMPER, BODY KIT & REAR LH FENDER	New	1,050.00	1,050.00
3	REMOVE & INSTALL REAR PARKING ASSIST	New	120.00	120.00
4	PERFORM RUST PREVENTION	New	80.00	40.00
5	CHECK WIRING & CHASSIS ELECTRICAL SYSTEM	New	30.00	30.00
6	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
7	REPAIR REAR END PANEL LH SIDE (Supplementary)	New	225.00	225.00
8	RESPRAY REAR END PANEL LH SIDE (Supplementary)	New	175.00	175.00
Gross Labour Cost (S\$)			3,600.00	2,210.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >