

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CC3/AIG20013256/EQF3E2

Date: 12/04/2021

REFERENCE

Insured/Claimant:	LEE TECK WAI	Policy No:	2070128139		
Date of Loss:	30/11/2020	Nature of Claim:	OD	Claim No:	8828182633SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMV2946M		
Make & Model:	AUDI A4, 1.4 (A)	Engine No:	CVK086198
Reg. Date:	24/09/2020 (Man. Year: 2019)	Chassis No:	WAUZZZF46KA104403
Colour:	Red	Odometer:	2691 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$140,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Continental 5 mm	Rear Left Side:	Continental 5 mm
Front Right Side:	Continental 5 mm	Rear Right Side:	Continental 5 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	40,835.00	22,750.32	18,084.68	44.29
Miscellaneous Items	0.00	0.00	0.00	
Labour	16,244.00	8,182.00	8,062.00	49.63
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	57,079.00	30,932.32	26,146.68	45.81
- Excess (S\$)	3,000.00	3,000.00	0.00	0.00
(S\$)	54,079.00	27,932.32	26,146.68	48.35
+ GST 7.00/7.00% (S\$)	3,785.53	1,955.26	1,830.27	48.35
Nett Amount (S\$)	57,864.53	29,887.58	27,976.95	48.35

INSPECTION

Date of Assignment:	02/12/2020		
Date Inspected:	02/12/2020	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	12.0 days		

Adjuster: CHEN TSUE YEE

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Broken	2,171.00 FS	*1,736.80 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	580.00 FS	*- FS
3	2		*FRONT BUMPER SECURING STRIP	Not Necessary	70.00 FS	*- FS
4	1		*FRONT BUMPER GRILLE - CENTRE	Not Necessary	194.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Not Necessary	208.00 FS	*- FS
6	1		*RADIATOR GRILLE	Broken	1,317.00 FS	*1,053.60 FS
7	1		*FRONT BUMPER AIR GUIDE GRILLE - LH / RH	O/S Broken	268.00 FS	*106.80 FS
8	2		*FRONT PARKING AID SENSOR - INNER / OUTER	Not Necessary	484.00 FS	*- FS
9	4		*FRONT PARKING AID SEAL RING	Not Necessary	14.00 FS	*- FS
10	1		*SET FRONT BUMPER WIRING	Not Necessary	505.00 FS	*- FS
11	1		*FRONT BUMPER CARRIER	Dented	795.00 FS	*635.60 FS
12	1		*FRONT BUMPER FOAM FILLER PIECE	Broken	123.00 FS	*98.40 FS
13	1		*FRONT BUMPER COVER	Crushed	126.00 FS	*100.40 FS
14	2		*FRONT BUMPER BRACKET - LH / RH	Not Necessary	450.00 FS	*- FS
15	2		*FRONT BUMPER GUIDE SECTION - LH / RH	Not Necessary	72.00 FS	*- FS
16	1		*CAUTION SIGN STICKER	Necessary	14.00 FS	*10.80 FS
17	1		*AIRCON STICKER	Necessary	8.00 FS	*5.68 FS
18	2		*LOCK CARRIER BRACKET - LH / RH	Broken	136.00 FS	*108.40 FS
19	2		*LOCK CARRIER BRACKET SUPPORT - LH / RH	Cracked	56.00 FS	*44.48 FS
20	1		*HORN - LH HIGH TONE	Not Necessary	124.00 FS	*- FS
21	1		*HORN - RH LOW TONE	Not Necessary	124.00 FS	*- FS
22	2		*SPRING SHACKLE - LH / RH	Not Necessary	58.00 FS	*- FS
23	1		*BONNET	Dented	2,763.00 FS	*2,210.40 FS
24	1		*BONNET ATTACHMENT PARTS	Not Necessary	408.00 FS	*- FS
25	2		*BONNET LID HINGE - LH / RH	Not Necessary	602.00 FS	*- FS
26	1		*BONNET IMPACT PROTECTION - CENTRE	Crushed	27.00 FS	*21.52 FS
27	1		*BONNET IMPACT PROTECTION - LH	Necessary	28.00 FS	*21.84 FS
28	1		*BONNET IMPACT PROTECTION - RH	Necessary	27.00 FS	*21.52 FS
29	2		*BONNET STRIKER - LH / RH	Not Necessary	100.00 FS	*- FS
30	2		*BONNET LID LOCK	Not Necessary	424.00 FS	*- FS
31	1		*BONNET BOWDEN CABLE - CENTRE	Not Necessary	57.00 FS	*- FS
32	1		*BONNET BOWDEN CABLE	Bent	57.00 FS	*45.52 FS
33	1		*BONNET RELEASE LEVER	Not Necessary	13.00 FS	*- FS
34	1		*BONNET LID LOCK CABLE	Not Necessary	73.00 FS	*- FS
35	1		*PLENUM CHAMBER COVER	Not Necessary	96.00 FS	*- FS
36	1		*BONNET SOUND ABSORBER	Not Necessary	339.00 FS	*- FS
37	2		*LED HEADLIGHT - LH / RH	Broken	15,386.00 FS	*12,308.80 FS
38	2		*LIFT CYLINDER - LH / RH	Not Necessary	416.00 FS	*- FS
39	1		*LIFT CYLINDER CORRUGATED PIPE	Not Necessary	92.00 FS	*- FS
40	1		*LOCK CARRIER	Cracked	1,004.00 FS	*803.20 FS
41	2		*COOLANT REGULATOR SUPPORT	Not Necessary	75.00 FS	*- FS
42	1		*AIRCON CONDENSER	Dented	615.00 FS	*492.00 FS
43	1		*REFRIGERANT LINE PRESSURE SENDER	Not Necessary	181.00 FS	*- FS
44	1		*HIGH PRESSURE SWITCH VALVE	Not Necessary	49.00 FS	*- FS
45	1		*REFRIGERANT LINE	Not Necessary	245.00 FS	*- FS
46	1		*TEMPERATURE SENSOR BRACKET	Missing	18.00 FS	*14.40 FS
47	1		*EXTERNAL TEMPERATURE SENSOR	Not Necessary	56.00 FS	*- FS
48	1		*CHARGE AIR COOLER	Not Necessary	580.00 FS	*- FS
49	1		*RADIATOR	Bent	837.00 FS	*669.20 FS
50	1		*READY MIX COOLANT	Necessary	177.00 FS	*72.32 FS
51	1		*RADIATOR FAN RING	Not Necessary	242.00 FS	*- FS
52	1		*RADIATOR FAN	Scratched	1,896.00 FS	*1,516.80 FS
53	2		*RADIATOR AIR GUIDE - LH / RH OUTER	Cracked	56.00 FS	*44.16 FS
54	2		*RADIATOR AIR GUIDE - LH / RH INNER	Cracked	24.00 FS	*18.72 FS
55	1		*RADIATOR AIR GUIDE - UPPER	Not Necessary	16.00 FS	*- FS

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	1		*RADIATOR AIR GUIDE - LOWER	Not Necessary	22.00 FS	*- FS
57	1		*AIR INTAKE AIR DUCT - RH	Not Necessary	22.00 FS	*- FS
58	1		*AIR INTAKE AIR GUIDE	Broken	53.00 FS	*41.92 FS
59	1		*AIR INTAKE HOSE	Not Necessary	94.00 FS	*- FS
60	1		*AIR MASS METER	Not Necessary	551.00 FS	*- FS
61	1		*FRONT DOOR - LH	Repair	2,354.00 FS	*- FS
62	1		*FRONT DOOR OUTER SEAL - LH	Not Necessary	203.00 FS	*- FS
63	1		*BONDING AGENT	Not Necessary	47.00 FS	*- FS
64	1		*CLEANING SOLUTION	Not Necessary	65.00 FS	*- FS
65	1		*FRONT DOOR ATTACHMENT PARTS	Not Necessary	870.00 FS	*- FS
66	1		*FRONT DOOR CATCH	Not Necessary	104.00 FS	*- FS
67	2		*WINDOW SLOT SEAL - LH / RH	Cut	606.00 FS	*484.80 FS
68	2		*WINDOW GUIDE TRIM STRIP - LH / RH	Not Necessary	508.00 FS	*- FS
69	1		*FRONT NO PLATE	Bent	60.00 FS	*60.00 FS
70	1		*SUNDRIES	Necessary	400.00 FS	*2.24 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 40,835.00 22,750.32

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT CONTROL UNITS AND POWER MODULE	New	700.00	500.00
3	TO REMOVE AND RENEW AIRCON CONDENSER, CHARGED AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS	New	1,200.00	1,200.00
4	TO REMOVE AND TRANSFER LHS FRONT DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES	New	280.00	0.00
5	TO DISMANTLE RHS FRONT DOOR PANEL TRIM. TO DISMANTLE AND REINSTALL RHS WING MIRROR ASSY	New	350.00	280.00
6	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND BOTH HEADLIGHTS. TO REPAIR BOTH FRONT FENDERS. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, LHS FRONT DOOR AND BOTH HEADLIGHTS. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	5,600.00	2,500.00
7	TO RESPRAY FRONT BUMPER, BONNET, HINGES, BOTH FRONT FENDERS, BOTH FRONT DOORS AND BOTH UPPER A-PILLARS	New	6,900.00	2,750.00
8	TO CARRY OUT PRE AND POST DIAGNOSTIC CHECK	New	384.00	192.00
9	TO DISMANTLE LHS FRONT DOOR PANEL TRIM. TO DISMANTLE AND REINSTALL LHS WING MIRROR ASSY.	New	350.00	280.00
Gross Labour Cost (\$\$)			16,244.00	8,182.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >