

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS3/AIG20013257/GTF3E2

**Date:** 27/05/2021

### REFERENCE

|                              |                                      |                             |            |           |              |
|------------------------------|--------------------------------------|-----------------------------|------------|-----------|--------------|
| Handling Insurer:            | AIG Asia Pacific Insurance Pte. Ltd. | Policy No:                  | 2070013783 |           |              |
| <b>Claimant Vehicle No :</b> | SGB2B                                | <b>Insured Vehicle No :</b> | GBJ1843B   |           |              |
| Date of Loss:                | 20/11/2020                           | Nature of Claim:            | TP         | Claim No: | 9552386213SG |

### DESCRIPTION & IDENTIFICATION OF VEHICLE

|                             |                                   |             |                   |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No:                     | <b>SGB2B</b>                      | Engine No:  | BWR008613         |
| Make & Model:               | BENTLEY CONTINENTAL, 6.0 FS (A)   | Chassis No: | SCBBE53W67C048279 |
| Reg. Date:                  | 28/06/2007 (Man. Year: 2007)      | Odometer:   | 35795 km          |
| Colour:                     | Black                             |             |                   |
| Engine Capacity:            | 5998 cc                           |             |                   |
| Market Value/New Car Price: | N/A                               |             |                   |
| Sum Insured (S\$):          | <b>Market Value/New Car Price</b> |             |                   |

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

### CONDITION OF TYRES

|                   |              |                  |              |
|-------------------|--------------|------------------|--------------|
| Front Tyre Size:  | 275/35Z R20  | Rear Tyre Size:  | 275/35Z R20  |
| Front Left Side:  | Pirelli 6 mm | Rear Left Side:  | Pirelli 6 mm |
| Front Right Side: | Pirelli 6 mm | Rear Right Side: | Pirelli 6 mm |

*The above values represent the remaining tyre treads depth*

| COST OF CLAIMS           | Repairer's  | Adjuster's  | Difference  | Diff % |
|--------------------------|-------------|-------------|-------------|--------|
| Parts                    | 0.00        | 0.00        | 0.00        |        |
| Miscellaneous Items      | 0.00        | 0.00        | 0.00        |        |
| Labour                   | 0.00        | 0.00        | 0.00        |        |
| Paintwork Labour         | 0.00        | 0.00        | 0.00        |        |
| Towing                   | 0.00        | 0.00        | 0.00        |        |
| <b>Nett Amount (S\$)</b> | <b>0.00</b> | <b>0.00</b> | <b>0.00</b> |        |

### INSPECTION

|                             |                          |                                                                                                     |
|-----------------------------|--------------------------|-----------------------------------------------------------------------------------------------------|
| Date of Assignment:         | 01/12/2020               |                                                                                                     |
| Date Inspected:             | 02/12/2020 Inspected At: | Benz Bodyworkz Pte Ltd (HQ)<br>8 KAKI BUKIT AVE 4 #08-32 PREMIER @KAKI<br>BUKIT<br>Singapore 415875 |
| Estimated Period of Repair: | 20.0 days                |                                                                                                     |

**Adjuster:** XING GUO QIANG

**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

MARKET VALUE: \$131,000.00

# REPAIR DETAILS

## Recommended Parts

| No. | Qty | Part No. | Particulars                             | Condition | Repairer's | Amount |
|-----|-----|----------|-----------------------------------------|-----------|------------|--------|
| 1   | 1   |          | *FRT NUMBER PLATE                       | Missing   | 0.00 F     | *- F   |
| 2   | 1   |          | *FRT NUMBER PLATE BASE                  | Cracked   | 0.00 F     | *- F   |
| 3   | 1   |          | *FRT NUMBER PLATE GARNISH               | Bent      | 0.00 F     | *- F   |
| 4   | 1   |          | *FRT BUMPER                             | Distorted | 0.00 F     | *- F   |
| 5   | 1   |          | *FRT BUMPER CLIPS                       | Necessary | 0.00 F     | *- F   |
| 6   | 2   |          | *FRT BUMPER SIDE RETAINER               | Broken    | 0.00 F     | *- F   |
| 7   | 1   |          | *FRT BUMPER REINFORCEMENT               | Dented    | 0.00 F     | *- F   |
| 8   | 1   |          | *FRT BUMPER SPONGE                      | Torn      | 0.00 F     | *- F   |
| 9   | 1   |          | *FRT BUMPER GRILLE                      | Broken    | 0.00 F     | *- F   |
| 10  | 2   |          | *FRT BUMPER MOULDING                    | Cut       | 0.00 F     | *- F   |
| 11  | 1   |          | *FRT BUMPER SENSOR                      | Cut       | 0.00 F     | *- F   |
| 12  | 1   |          | *FRT LH BUMPER FOG LAMP COVER           | Cracked   | 0.00 F     | *- F   |
| 13  | 1   |          | *FRT GRILLE                             | Cracked   | 0.00 F     | *- F   |
| 14  | 1   |          | *FRONT APRON PANEL                      | Bent      | 0.00 F     | *- F   |
| 15  | 1   |          | *FRT SUPPORT PANEL                      | Broken    | 0.00 F     | *- F   |
| 16  | 1   |          | *FRT SUPPORT PANEL TOP GARNISH COVER    | Distorted | 0.00 F     | *- F   |
| 17  | 1   |          | *FRT LH HEADLAMP ASSY                   | Cracked   | 0.00 F     | *- F   |
| 18  | 1   |          | *FRT RH HEADLAMP ASSY                   | Cracked   | 0.00 F     | *- F   |
| 19  | 1   |          | *BONNET                                 | Buckled   | 0.00 F     | *- F   |
| 20  | 1   |          | *BONNET LOCK                            | * Check   | 0.00 F     | *- F   |
| 21  | 1   |          | *AIR CON CONDENSER                      | Dented    | 0.00 F     | *- F   |
| 22  | 1   |          | *AIR CON FAN ASSY                       | * Check   | 0.00 F     | *- F   |
| 23  | 1   |          | *AIR CON SUCTION PIPE (LOW PRESSURE)    | * Check   | 0.00 F     | *- F   |
| 24  | 1   |          | *AIR CON DISCHARGE PIPE (HIGH PRESSURE) | * Check   | 0.00 F     | *- F   |
| 25  | 1   |          | *AIR CON DISCHARGE HOSE                 | * Check   | 0.00 F     | *- F   |
| 26  | 1   |          | *RADIATOR                               | * Check   | 0.00 F     | *- F   |
| 27  | 1   |          | *RADIATOR FAN COWLING                   | * Check   | 0.00 F     | *- F   |
| 28  | 1   |          | *RADIATOR FAN ASSY                      | * Check   | 0.00 F     | *- F   |
| 29  | 1   |          | *AIR DUCT                               | * Check   | 0.00 F     | *- F   |
| 30  | 1   |          | *ENGINE UNDER COVER                     | Cracked   | 0.00 F     | *- F   |
| 31  | 1   |          | *FRT LH FENDER                          | Buckled   | 0.00 F     | *- F   |
| 32  | 1   |          | *FRT LH FENDER INNER SHIELD             | Cracked   | 0.00 F     | *- F   |
| 33  | 1   |          | *FRT LH WHEEL RIM                       | Cut       | 0.00 F     | *- F   |
| 34  | 1   |          | *FRT LH TYRE (70%)                      | * Check   | 0.00 F     | *- F   |
| 35  | 1   |          | *FRT RH FENDER                          | Buckled   | 0.00 F     | *- F   |
| 36  | 1   |          | *FRT RH FENDER INNER SHIELD             | Cracked   | 0.00 F     | *- F   |
| 37  | 1   |          | *FRT RH WHEEL RIM                       | Cut       | 0.00 F     | *- F   |
| 38  | 1   |          | *FRT RH TYRE (70%)                      | * Check   | 0.00 F     | *- F   |
| 39  | 1   |          | *AIRBAG CONTROL UNIT                    | * Check   | 0.00 F     | *- F   |
| 40  | 2   |          | *HEADLAMP WASHER JET COVER              | Missing   | 0.00 F     | *- F   |
| 41  | 1   |          | *OIL COOLER                             | Dented    | 0.00 F     | *- F   |
| 42  | 1   |          | *FRT PASSENGER SEAT SIDE AIR BAG        | Burst     | 0.00 F     | *- F   |
| 43  | 1   |          | *FRT PASSENGER SEAT BACK REST COVER     | Torn      | 0.00 F     | *- F   |
| 44  | 1   |          | *REAR BUMPER                            | Cracked   | 0.00 F     | *- F   |
| 45  | 1   |          | *REAR BUMPER CLIPS                      | Necessary | 0.00 F     | *- F   |
| 46  | 1   |          | *REAR BUMPER SIDE RETAINER              | Distorted | 0.00 F     | *- F   |
| 47  | 1   |          | *REAR BUMPER REINFORCEMENT              | * Check   | 0.00 F     | *- F   |
| 48  | 1   |          | *REAR BUMPER SPONGE                     | * Check   | 0.00 F     | *- F   |
| 49  | 2   |          | *REAR BUMPER MOULDING                   | Necessary | 0.00 F     | *- F   |
| 50  | 1   |          | *REVERSE SENSOR                         | * Check   | 0.00 F     | *- F   |
| 51  | 1   |          | *REAR END PANEL                         | Repair    | 0.00 F     | *- F   |
| 52  | 1   |          | *REAR LH TAILLAMP                       | Cracked   | 0.00 F     | *- F   |
| 53  | 1   |          | *REAR LH TAILLAMP PANEL                 | * Check   | 0.00 F     | *- F   |
| 54  | 1   |          | *REAR LH FENDER                         | Buckled   | 0.00 F     | *- F   |
| 55  | 1   |          | *REAR LH FENDER INNER PANEL             | Repair    | 0.00 F     | *- F   |

| No. | Qty | Part No. | Particulars                         | Condition | Repairer's | Amount |
|-----|-----|----------|-------------------------------------|-----------|------------|--------|
| 56  | 1   |          | *REAR LH FENDER INNER TRIM          | * Check   | 0.00 F     | *- F   |
| 57  | 1   |          | *REAR LH FENDER INNER SHIELD        | Torn      | 0.00 F     | *- F   |
| 58  | 1   |          | *REAR LH WHEEL RIM                  | Cut       | 0.00 F     | *- F   |
| 59  | 1   |          | *REAR LH TYRE (70%)                 | * Check   | 0.00 F     | *- F   |
| 60  | 1   |          | *REAR RH FENDER                     | Buckled   | 0.00 F     | *- F   |
| 61  | 1   |          | *REAR RH FENDER INNER PANEL         | Repair    | 0.00 F     | *- F   |
| 62  | 1   |          | *REAR RH FENDER INNER TRIM          | * Check   | 0.00 F     | *- F   |
| 63  | 1   |          | *REAR RH FENDER INNER SHIELD        | Torn      | 0.00 F     | *- F   |
| 64  | 1   |          | *REAR RH WHEEL RIM                  | Cut       | 0.00 F     | *- F   |
| 65  | 1   |          | *REAR RH TYRE (70%)                 | * Check   | 0.00 F     | *- F   |
| 66  | 1   |          | *REAR WINDSCREEN GLASS              | * Check   | 0.00 F     | *- F   |
| 67  | 1   |          | *REAR WINDSCREEN MOULDING           | Necessary | 0.00 F     | *- F   |
| 68  | 1   |          | *REAR WINDSCREEN SEALANT            | Necessary | 0.00 F     | *- F   |
| 69  | 1   |          | *REAR FENDER AIR GRILLE LH          | Torn      | 0.00 F     | *- F   |
| 70  | 1   |          | *REAR RH DOOR                       | Buckled   | 0.00 F     | *- F   |
| 71  | 1   |          | *FRT PASSENGER SEAT SIDE AIR BAG    | Burst     | 0.00 F     | *- F   |
| 72  | 1   |          | *REAR LH DOOR                       | Buckled   | 0.00 F     | *- F   |
| 73  | 1   |          | *REAR LH DOOR MOULDING              | Cut       | 0.00 F     | *- F   |
| 74  | 1   |          | *REAR LH DOOR GLASS REGULATOR       | * Check   | 0.00 F     | *- F   |
| 75  | 1   |          | *REAR LH DOOR GLASS REGULATOR MOTOR | * Check   | 0.00 F     | *- F   |
| 76  | 1   |          | *REAR LH DOOR RUBBER                | * Check   | 0.00 F     | *- F   |
| 77  | 1   |          | *REAR LH DOOR LOCK                  | Jammed    | 0.00 F     | *- F   |
| 78  | 1   |          | *REAR LH DOOR INNER TRIM BOARD      | * Check   | 0.00 F     | *- F   |
| 79  | 1   |          | *ROOF TOP LINING                    | Torn      | 0.00 F     | *- F   |
| 80  | 1   |          | *ROOF TOP AIR-BAG LH                | Burst     | 0.00 F     | *- F   |
| 81  | 1   |          | *ROOF TOP AIR-BAG SENSOR LH         | Necessary | 0.00 F     | *- F   |
| 82  | 1   |          | *ROOF TOP AIR-BAG CONTROL UNIT      | * Check   | 0.00 F     | *- F   |

F=Franchise part.

|                          |             |             |
|--------------------------|-------------|-------------|
| <b>Total Parts (S\$)</b> | <b>0.00</b> | <b>0.00</b> |
|--------------------------|-------------|-------------|

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

|                                               |
|-----------------------------------------------|
| Report was unsubmitted during this print-out. |
|-----------------------------------------------|

< END OF ESTIMATES >