

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way #07-16  
Singapore 079120

**Our File No:** CS/AIG20013258/ETF3E2

**Date:** 22/12/2020

### REFERENCE

|                   |                  |                  |            |           |              |
|-------------------|------------------|------------------|------------|-----------|--------------|
| Insured/Claimant: | NUNNA SIVAJI RAO | Policy No:       | 1900261240 |           |              |
| Date of Loss:     | 01/12/2020       | Nature of Claim: | OD         | Claim No: | 9404382578SG |

### DESCRIPTION & IDENTIFICATION OF VEHICLE

|                             |                               |             |             |
|-----------------------------|-------------------------------|-------------|-------------|
| Reg No:                     | SMR4534B                      |             |             |
| Make & Model:               | MITSUBISHI OUTLANDER, 2.0 (A) | Engine No:  | 4J11AG9646  |
| Reg. Date:                  | 07/01/2020 (Man. Year: 2018)  | Chassis No: | GF7W0600952 |
| Colour:                     | Red                           | Odometer:   | 14597 km    |
| Engine Capacity:            | 1998 cc                       |             |             |
| Market Value/New Car Price: | S\$114,000.00                 |             |             |
| Sum Insured (S\$):          | Market Value/New Car Price    |             |             |

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

### CONDITION OF TYRES

|                   |            |                  |            |
|-------------------|------------|------------------|------------|
| Front Tyre Size:  | 225/55 R18 | Rear Tyre Size:  | 225/55 R18 |
| Front Left Side:  | Toyo 4 mm  | Rear Left Side:  | Toyo 4 mm  |
| Front Right Side: | Toyo 4 mm  | Rear Right Side: | Toyo 4 mm  |

*The above values represent the remaining tyre treads depth*

| COST OF CLAIMS                      | Repairer's      | Adjuster's      | Difference      | Diff %       |
|-------------------------------------|-----------------|-----------------|-----------------|--------------|
| Parts                               | 4,810.94        | 4,131.80        | 679.14          | 14.12        |
| Miscellaneous Items                 | 0.00            | 0.00            | 0.00            |              |
| Labour                              | 2,250.00        | 1,000.00        | 1,250.00        | 55.56        |
| Paintwork Labour                    | 0.00            | 0.00            | 0.00            |              |
| Towing                              | 0.00            | 0.00            | 0.00            |              |
| <b>Calculated Gross Total (S\$)</b> | <b>7,060.94</b> | <b>5,131.80</b> | <b>1,929.14</b> | <b>27.32</b> |
| <b>- Excess (S\$)</b>               | <b>300.00</b>   | <b>300.00</b>   | <b>0.00</b>     | <b>0.00</b>  |
| <b>(S\$)</b>                        | <b>6,760.94</b> | <b>4,831.80</b> | <b>1,929.14</b> | <b>28.53</b> |
| <b>+ GST 7.00/7.00% (S\$)</b>       | <b>473.27</b>   | <b>338.23</b>   | <b>135.04</b>   | <b>28.53</b> |
| <b>Nett Amount (S\$)</b>            | <b>7,234.21</b> | <b>5,170.03</b> | <b>2,064.18</b> | <b>28.53</b> |

### INSPECTION

|                             |                          |                                                                                                |
|-----------------------------|--------------------------|------------------------------------------------------------------------------------------------|
| Date of Assignment:         | 02/12/2020               |                                                                                                |
| Date Inspected:             | 07/12/2020 Inspected At: | Cycle & Carriage Automotive Pte Ltd (Pandan Gardens)<br>209 Pandan Gardens<br>Singapore 609339 |
| Estimated Period of Repair: | 3.0 days                 |                                                                                                |

**Adjuster:** CHEN TSUE YEE

**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but*

*any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars                           | Condition     | Repairer's  | Amount       |
|-----|-----|----------|---------------------------------------|---------------|-------------|--------------|
| 1   | 1   |          | *SUNDRIES                             | Necessary     | 20.00 FS    | *20.00 FS    |
| 2   | 1   |          | *FACE, FR BUMPER                      | Broken        | 859.00 FL   | *859.00 FL   |
| 3   | 1   |          | *BRACKET, FR BUMPER SIDE, LH          | Broken        | 18.00 FL    | *18.00 FL    |
| 4   | 1   |          | *BRACKET, FR BUMPER SIDE, RH          | Broken        | 18.00 FL    | *18.00 FL    |
| 5   | 1   |          | *EXTENSION, FR BUMPER, LH             | Cut           | 515.00 FL   | *515.00 FL   |
| 6   | 1   |          | *GARNISH, FR BUMPER, LH               | Not Necessary | 48.00 FL    | *- FL        |
| 7   | 1   |          | *GARNISH, FR BUMPER SIDE              | Not Necessary | 48.00 FL    | *- FL        |
| 8   | 1   |          | *GARNISH, FR BUMPER SIDE              | Cracked       | 220.00 FL   | *220.00 FL   |
| 9   | 1   |          | *GARNISH, FR BUMPER SIDE              | Broken        | 112.00 FL   | *112.00 FL   |
| 10  | 1   |          | *GARNISH, FR BUMPER SIDE              | Not Necessary | 48.00 FL    | *- FL        |
| 11  | 1   |          | *GARNISH, FR BUMPER SIDE              | Not Necessary | 220.00 FL   | *- FL        |
| 12  | 1   |          | *GARNISH, FR BUMPER SIDE              | Not Necessary | 112.00 FL   | *- FL        |
| 13  | 1   |          | *COVER,FR BUMPER                      | Broken        | 359.00 FL   | *359.00 FL   |
| 14  | 1   |          | *REINFORCEMENT, FR BUMPER             | Bent          | 490.00 FL   | *490.00 FL   |
| 15  | 1   |          | *BAR, FR BUMPER GUARD                 | Not Necessary | 130.00 FL   | *- FL        |
| 16  | 1   |          | *REINF, FR BUMPER SIDE, LH            | Bent          | 60.00 FL    | *60.00 FL    |
| 17  | 1   |          | *REINF, FR BUMPER SIDE, RH            | Bent          | 69.00 FL    | *69.00 FL    |
| 18  | 1   |          | *REINFORCEMENT, FR BUMPER             | Bent          | 134.00 FL   | *134.00 FL   |
| 19  | 1   |          | *GRILLE ASSY, RADIATOR                | Broken        | 548.00 FL   | *548.00 FL   |
| 20  | 1   |          | *MOULDING, FR BUMPER, LH              | Not Necessary | 116.00 FL   | *- FL        |
| 21  | 1   |          | *MOULDING, FR WHEEL ARCH, LH          | Not Necessary | 160.00 FL   | *- FL        |
| 22  | 1   |          | *HEADLAMP ASSY, RH<br>(SUPPLEMENTARY) | Broken        | 1,938.00 FL | *1,938.00 FL |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|                                                     |          |          |
|-----------------------------------------------------|----------|----------|
| Sub Total (\$\$)                                    | 6,242.00 | 5,360.00 |
| - List Item Discount on L Items 23.00/23.00% (\$\$) | 1,431.06 | 1,228.20 |
| Total Parts (\$\$)                                  | 4,810.94 | 4,131.80 |

Report was unsubmitted during this print-out.

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

| No                              | Particulars                                                                 | Lab.Type | Repairer's      | Amount          |
|---------------------------------|-----------------------------------------------------------------------------|----------|-----------------|-----------------|
| <b>Labour Items</b>             |                                                                             |          |                 |                 |
| 1                               | RENEW FRT BUMPER. REPAIR LHF FENDER                                         | New      | 1,350.00        | 450.00          |
| 2                               | RESPRAY FRT BUMPER & LHF FENDER                                             | New      | 700.00          | 350.00          |
| 3                               | CHECK WIRING ELECTRICAL SYSTEM                                              | New      | 30.00           | 30.00           |
| 4                               | TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST | New      | 120.00          | 120.00          |
| 5                               | SUPPLY FRT NUMBER PLATE WITH CASING                                         | New      | 50.00           | 50.00           |
| <b>Gross Labour Cost (\$\$)</b> |                                                                             |          | <b>2,250.00</b> | <b>1,000.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >