



AIG - OD CLAIM
SURVEY: 07/12/20
LKK - STEVE

VEHICLE NO : SMR 4534 B

MODEL : MIT/OUTLANDER 2.0

WIP : 60285

Material	:	\$	<u>4,111.80</u>
Labour	:	\$	<u>1,020.00</u>
Sub-Total	:	\$	<u>5,131.80</u>
Less 2% Disc	:	\$	<u>—</u>
Less Excess	:	\$	<u>300.00</u>
Total	:	\$	<u>4,831.80</u>
GST 7%	:	\$	<u>338.23</u>
Grand Total	:	\$	<u>5,170.03</u>
Finalise By/Date : <u>Larry on 16/12/20</u>			

☒ REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

REPAIR TOOK 03 WORKING DAYS

PRO-FORMA INVOICE

Co Reg No : 1977014696

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 07/12/2020	Cust No/Name KCV15177/NUNNA SIVAJI RAO Reg No/Reg Date SMR4534B / 07/01/2020 Date In/Mileage 07/12/2020/ 14454 Chassis/Package GF7W0600952 /DC17P(F) Engine No 4J11AG9646 Make/Model MIT/19MY OUTLANDER 2.0 MODERN(995) Colour/Trim P02 RED METALLIC / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	16/12/2020/ 09:31	BLE	884 / Lauro Songcuan	60285

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW FRONT BUMPER				450.00 ✓
E PNT98000 SPRAY PAINT FRONT BUMPER				350.00 ✓
A 54900099 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM				30.00 ✓
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				120.00 ✓
M SUNDRY Sundries				20.00 ✓
S SPECIALISTJOB				50.00 ✓
K SUPPLY FRONT LICENSE PLATE WITH FRAME (RECTANGULAR & BLACK)				
X EXC EXCESS				-300.00
X FACE,FR BUMPER ✓	1.00	859.00	23.00	661.43 ✓
X BRACKET,FR BUMPER SIDE,LH ✓	1.00	18.00	23.00	13.86 ✓
X BRACKET,FR BUMPER SIDE,RH ✓	1.00	18.00	23.00	13.86 ✓
X EXTENSION,FR BUMPER ✓	(509.00) 1.00	* 515.00	23.00	396.55 ✓
X GARNISH,FR BUMPER SIDE ✓	1.00	220.00	23.00	169.40 ✓
X GARNISH,FR BUMPER SIDE X	1.00	112.00	23.00	86.24 ?
X COVER,FR BUMPER ✓	1.00	359.00	23.00	276.43 ✓
X REINF,FR BUMPER SIDE,LH ?	1.00	60.00	23.00	46.20 ?
X REINF,FR BUMPER SIDE,RH ?	1.00	69.00	23.00	53.13 ?
X REINFORCEMENT,FR BUMPER ?	1.00	134.00	23.00	103.18 ?
X GRILLE ASSY,RADIATOR ✓	1.00	548.00	23.00	421.96 ✓
X HEADLAMP ASSY,RH → <i>supp</i>	1.00	1938.00	23.00	1492.26 X
X REINFORCEMENT,FR BUMPER ?	1.00	490.00	23.00	377.30 ?
Z TEXT OD CLAIM - AIG SURVEY: STEVE (LKK) 07.12.2020 DOA: 01.12.2020 03 DAYS <i>* change price</i>				

Guarantee Your Warranty, Maintain with Cycle & Carriage!

Parts	4,111.80	Nett	4,831.80
Labour	950.00	7% GST on	338.23
Standard Menu	0.00		
Specialist Job	50.00		
Diagnostics Job	0.00	Total Payable	5,170.03
Sundry/Others	-280.00		
Total(w/o GST)	4,831.80		

This is not an official tax invoice.
 This is a computer generated document, no signature is required.



CYCLE & CARRIAGE

INSURANCE CO.: AIG

Supplementary For Registration No.: SMR 4534 B

<u>Materials</u>		<u>Cost \$</u>
1	Headlamp Assy, RH	1,938.00
	23% Discount	445.74
		1,492.26
	7% GST	104.46
	Total	1,596.72

✓ BR

Thank You.

Yours faithfully
CYCLE & CARRIAGE AUTOMOTIVE PTE LTD

Larry Songcuan
Customer Service
Cycle & Carriage
Pandan Gardens

CAR NO: SMR4534BWIP: 60285

(ADDITIONAL PARTS CHANGE)

S/NO	PARTS NAME	? / SUPP	CSA SIGN	PHOTO TAKEN	REMARKS
1	Finish Front Bumper Side LH LWR	? / SUPP	CSA		
2	Reinforcement Front Bumper LWR	? / SUPP	BT		
3	Reinforcement Front Bumper UPR	? / SUPP	BT	Steve 7/12/20	5pm
4	Reinforcement Front Bumper LH	? / SUPP	BT		
5	Reinforcement Front Bumper RH	? / SUPP	BT		
6	Headlamp RH	? / SUPP	BR		
7	Engine Under Cover	? / SUPP	X	(Discovered)	
8		? / SUPP			
9		? / SUPP			
10		? / SUPP			
11		? / SUPP			
12		? / SUPP			
13		? / SUPP			
14		? / SUPP			
15		? / SUPP			
16		? / SUPP			
17		? / SUPP			
18		? / SUPP			
19		? / SUPP			
20		? / SUPP			

PHOTO BEFORE PAINT	DATE	TAKEN BY
PHOTO AFTER PAINT	8/12/20	Steve 12pm
PHOTO OF MOUNT TO CELLETE BENCH		
REMOVE AND INSTALL ENGINE		
REMOVE AND INSTALL DASHBAORD		
REMOVE & INSTALL FUEL TANK		
PHOTO UNDERCARRIAGE PARTS		

MODEL: QUMANDERSURVEYOR: STEVE

All DTCS

Setting	
Item	Information
M.U.T.-3 Version	SEW20011-00
V.C.I. Version	B177
Vehicle Information	DBA-GF7W 2019MY

SMR.45340
 Before use, part 3x use unit to check all the data

ATTRIBUTES LOCAL(0x40)"
 @PJL COMMENT "SpoolDataType=RAW"
 @PJL COMMENT "CV=V0.21F(2012/12/28,16:34:01)"
 @PJL COMMENT "C1=000114000000000040001000100"
 @PJL COMMENT "C2=323232323200000005100000"
 @PJL COMMENT "TI=0203040608"
 @PJL ENTER LANGUAGE = QPDL

All DTCs

System Name	SCC or DVC or Diagnostic database ID	Diagnostic trouble code(s)	Name	Malfunction Condition
MPi/GDI/DIESEL	GAS_0E640000		No DTCs	
Auto Stop & Go (AS&G)	ASG_25080000		No DTCs	
AT/CVT/A-MT/T-C-SST	CVT_14080300		No DTCs	
AUTO CRUISE	GAS_0E640000		Non-target System	
4WS/Electric Power Steering	EPS_45880040		No DTCs	
ABS/ASC/ASTC/WSS	ASC_4208000F		No DTCs	
SRS-AIR BAG	ORC_81047302		No DTCs	
Air Conditioner	AC_80080011		No DTCs	
ETACS	ETACS_83040801	B16A4	Turn signal(RH) bulb outage	Active
Meter	MTR_84084001		No DTCs	
Steering Angle Sensor	GS_SAS_47000100		Non-target System	
AND	AND_8C080002		Non-equipped System or Communication Error	
AUDIO (Display Audio)	AUDIO_8D080002		Non-equipped System or Communication Error	
LIN	ETACS_83040801		Non-target System	
Power Gate	ETG_92080000		Non-equipped System or Communication Error	

All DTCs

System Name	SCC or DVC or Diagnostic database ID	Diagnostic trouble code(s)	Name	Malfunction Condition
KOS/IMMO/Keyless	KOS_8A880020		No DTCs	
OSS	OSS_9688000B		No DTCs	
CORNER SENSOR/SONAR	SONAR_9D080000		Non-equipped System or Communication Error	
ACC/FCM	ACCSFCM_4B080000		Non-equipped System or Communication Error	
Multi Around Monitor	CAMERA_94080100		Non-equipped System or Communication Error	
EPB	EPB_4C080000	C2253	EPB SW malfunction	Stored
Gateway	GW_C1000000		Non-equipped System or Communication Error	
FCM/LDW/AHB	ADAS_4B080003		Non-equipped System or Communication Error	
BSW	BSW_RAD_MASTER_A0080000		Non-equipped System or Communication Error	
BSW(SUB)	BSW_RAD_SLAVE_A0080000		Non-equipped System or Communication Error	

▲

SMR4534B

All DTCs

Setting	
Item	Information
M.U.T.-3 Version	SEW20011-00
V.C.I. Version	B177
Vehicle Information	DBA-GF7W 2019MY

after use MUT-3 VCI unit to check all the found
in and erase all the found
is job Done.

2020.12.09

System Name	SCC or DVC or Diagnostic database ID	Diagnostic trouble code(s)	Name	Malfunction Condition	
MP/IGDI/DIESEL	GAS_0E640000		No DTCS		
Auto Stop & Go (AS&G)	ASG_25080000		No DTCS		
AT/CVT/A-MT/C-SST	CVT_14080300		No DTCS		
AUTO CRUISE	GAS_0E640000		Non-target System		
4WS/Electric Power Steering	EPS_45880040		No DTCS		
ABS/ASC/ASTC/MSS	ASC_4208000F		No DTCS		
SRS-AIR BAG	ORC_81047302		No DTCS		
Air Conditioner	AC_80080011		No DTCS		
ETACS	ETACS_83040801		No DTCS		
Meter	MTR_84084001		No DTCS		
Steering Angle Sensor	GS_SAS_47000100		Non-target System		
AND	AND_8C080002		Non-equipped System or Communication Error		
AUDIO (Display Audio)	AUDIO_8D080002		Non-equipped System or Communication Error		
LIN	ETACS_83040801		Non-target System		
Power Gate	ETG_92080000		Non-equipped System or Communication Error		

All DTCS

System Name	SCC or DVC or Diagnostic database ID	Diagnostic trouble code(s)	Name	Malfunction Condition
KOS/IMMO/keyless	KOS_8A880020		No DTCS	
OSS	OSS_9688000B		No DTCS	
CORNER SENSOR/SONAR	SONAR_9D080000		Non-equipped System or Communication Error	
ACC/FCM	ACCSCFM_4B080000		Non-equipped System or Communication Error	
Multi Around Monitor	CAMERA_94080100		Non-equipped System or Communication Error	
EPB	EPB_4C080000		No DTCS	
Gateway	GW_C1000000		Non-equipped System or Communication Error	
FCM/LDW/AHB	ADAS_4B080003		Non-equipped System or Communication Error	
BSW	BSW_RAD_MASTER_A0080000		Non-equipped System or Communication Error	
BSW(SUB)	BSW_RAD_SLAVE_A0080000		Non-equipped System or Communication Error	