



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 4732P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER COVER	DEFORMED	1,052.20	1,052.20
2	FRONT BUMPER BRACKET SIDE LH/RH	O/S DEFORMED / N/S NOT NECESSARY	71.20	44.80
10	FRONT BUMPER CLIPS @\$2.20	NECESSARY	22.00	22.00
2	FRONT BUMPER BRACKET LH/RH @\$49.20	NOT NECESSARY	98.40	-
1	FRT RH FENDER	BENT	663.00	663.00
1	FRT RH HEAD LAMP ASSY	CUT	1,388.00	1,388.00
1	HEAD LAMP SUPPORT PANEL	NOT NECESSARY	907.40	-
1	WASHER TANK ASSY	NOT NECESSARY	61.90	-
	LESS 20% DISCOUNT		-852.82	-634.00
			3,411.28	2,536.00
LABOUR				
	PANEL BEATING.		500.00	420.00
	SPRAY PAINTING CHARGE.		500.00	400.00
	CHECK LIGHTING.		50.00	30.00
	REMOVE/REFIX CONDENSER & CHARGE GAS.	NOT NECESSARY	90.00	-
	TUFF KOTE.		90.00	30.00
			1,230.00	880.00
GRAND TOTAL			4,641.28	3,416.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				2,400.00

Report Ref No. NS/INC20013265/T1tf3e2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.