Adjuster Report Page 1 of 3

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG20013269/KTD3Q2

Date: 10/03/2021

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: 1001403902

Claimant

SKW913P

Insured Vehicle No: GBC4245U

Vehicle No: Skills 13F Illustred Vehicle No. GBC42430

Date of Loss: 28/11/2020 Nature of Claim: TP Claim No: 250334

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKW913P

 Make & Model:
 HONDA VEZEL, 1.5 X CVT (A)
 Engine No:
 L15B4023168

 Reg. Date:
 16/10/2015 (Man. Year: 2015)
 Chassis No:
 RU11103166

 Colour:
 Metallic Pearl White
 Odometer:
 72080 km

Engine Capacity: 1496 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60R16 Rear Tyre Size: 215/60R16
Front Left Side: Dunlop 8 mm Rear Left Side: Dunlop 8 mm
Front Right Side: Dunlop 8 mm Rear Right Side: Dunlop 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,015.88	1,269.76	2,746.12	68.38
Miscellaneous Items	0.00	0.00	0.00	
Labour	780.00	600.00	180.00	23.08
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,795.88	1,869.76	2,926.12	61.01
+ GST 7.00/7.00% (S\$)	335.71	130.88	204.83	61.01
Nett Amount (S\$)	5,131.59	2,000.64	3,130.95	61.01

INSPECTION

Date of Assignment: 01/12/2020

Date Inspected: 02/12/2020 Inspected At: Chew Goon Motor (AMK)

Blk 10 Ang Mo Kio Industrial Park 2A, #01-15/16 & 17, AMK Autopoint

Singapore 568047

Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 2 of 3

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 04 Mar 2021)

Parts: M1-SUV HONDA VEZEL 1.5 X CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKW913P)

These estimates are valid only if they contain the print code (above) on all estimate pages, running page Validity:

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts No. Qtv Part No. Particulars

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*BONNET	Bent	1,089.00 FL	*892.20 FL
2	2	*BONNET SIDE STOPPERS	Serviceable	26.00 FL	*-FL
3	2	*BONNET RUBBER SEAL	Serviceable	78.00 FL	*-FL
4	8	*BONNET INSULATOR CLIPS	Not Necessary	30.40 FL	*- FL
5	1	*HEADLAMP LH	Serviceable	1,970.00 FL	*-FL
6	1	*GRILLE TOP GARNISH	Serviceable	195.00 FL	*-FL
7	1	*GRILLE EMBLEM	Necessary	32.00 FL	*32.00 FL
8	1	*GRILLE TOP GARNISH MOULDING L	H Scratched	150.00 FL	*150.00 FL
9	1	*FRONT BUMPER	Cracked	963.00 FL	*459.80 FL
10	14	*FRONT BUMPER CLIPS	Necessary	53.20 FL	*53.20 FL
11	1	*FRONT BUMPER REINFORCEMENT	Repair	340.00 FL	*- FL
12	1	*FRONT NUMBER PLATE (DENTED)	Not Consistent With The Impact	45.00 FS	*-FS
13	1	*HEADLAMP LOWER BRACKET LH	Serviceable	37.00 FL	*- FL
F=Fra	anchise	part. S=SpcNett. L=ListItemDisc.			
			Sub Total (S\$)	5,008.60	1,587.20
- List Item Discount on L Items 20.00/20.00% (S\$)					317.44

Total Parts (S\$) 4,015.88 1,269.76

Report was unsubmitted during this print-out.

Adjuster Report Page 3 of 3

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	LABOUR CHARGE-PANEL BEATING,REPAIRING OF BONNET HINGE,BRACE PANEL AND PARTS REPLACEMENT	New	300.00	200.00
2	TO RESPRAY AFFECTED AREAS	New	480.00	400.00
	Gross Labour Cost (S\$)		780.00	600.00
	Report was unsubmitted do	uring this print-out.		

< END OF ESTIMATES >