

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20013270/AVF3Q2

Date: 09/12/2020

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00112292001

Claimant Vehicle No : CB9928T **Insured Vehicle No :** GBK371Y

Date of Loss: 30/11/2020 Nature of Claim: TP Claim No: SNM20D204655/C02/TOHHS

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	CB9928T	Engine No:	2KD1366321
Make & Model:	TOYOTA HIACE, 2.5 (M)	Chassis No:	KDH2000030025
Reg. Date:	31/12/2005 (Man. Year: 2005)	Odometer:	605048 km
Colour:	White		
Engine Capacity:	2494 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195R15C	Rear Tyre Size:	195R15C
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,901.02	5,498.60	2,402.42	30.41
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,410.00	1,800.00	610.00	25.31
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,311.02	7,298.60	3,012.42	29.22
Approved Total (Overridden) (S\$)		5,800.00		
(S\$)	10,311.02	5,800.00	4,511.02	43.75
+ GST 7.00/7.00% (S\$)	721.77	406.00	315.77	43.75
Nett Amount (S\$)	11,032.79	6,206.00	4,826.79	43.75

INSPECTION

Date of Assignment: 03/12/2020

Date Inspected: 03/12/2020 Inspected At: 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB
Repairer: An-51 Automotive (HQ)

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 09 Dec 2020)	
Parts:	N/A	TOYOTA HIACE 2.5 (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for CB9928T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	706.00 FL	*706.00 FL
2	4		*REAR BUMPER LOWER BRACKET	Bent	192.00 FL	*72.00 FL
3	2		*REAR BUMPER SIDE RETAINER L/R	Necessary	94.00 FL	*94.00 FL
4	1		*REAR BUMPER STEP PANEL	Bent	381.90 FL	*381.90 FL
5	1		*REAR END PANEL (INNER)	Repair	820.70 FL	*- FL
6	1		*REAR END PANEL (OUTER)	Dented	743.00 FL	*743.00 FL
7	1		*REAR TAILGATE	Dented	1,950.00 FL	*1,950.00 FL
8	1		*REAR TAILGATE LOGO EMBLEM	Necessary	63.00 FL	*63.00 FL
9	2		*REAR TAILGATE DAMPER L/R	Not Necessary	428.00 FL	*- FL
10	2		*REAR TAILGATE HINGES L/R	Not Necessary	134.00 FL	*- FL
11	1		*REAR TAILGATE INNER AUTO LOCK CONTROL	Damaged	405.00 FL	*289.00 FL
12	2		*REAR TAILGATE INNER RUBBER GUIDE STOPPER L/R	Not Necessary	34.00 FL	*- FL
13	1		*REAR TAILGATE INNER TRIM BOARD	Not Necessary	469.00 FL	*- FL
14	1		*REAR TAILGATE LOCK STRIKER	Not Necessary	53.00 FL	*- FL
15	1		*REAR TAILGATE MECHANISM LOCK	Damaged	264.00 FL	*264.00 FL
16	1		*REAR TAILGATE MECHANISM LOCK COVER	Cut	98.90 FL	*98.90 FL
17	2		*REAR TAILGATE NUMBER PLATE LAMP L/R	Not Necessary	224.20 FL	*- FL
18	1		*REAR TAILGATE OUTER HANDLE	Cracked	93.00 FL	*93.00 FL
19	1		*REAR TAILGATE WINDSCREEN	Shattered	980.00 FL	*980.00 FL
20	1		*REAR TAILGATE WEATHER STRIP	Cut	391.00 FL	*391.00 FL
21	1		*REAR TAILGATE WINDSCREEN SEAL	Necessary	80.00 FL	*80.00 FL
22	1		*REAR TAILLAMP L/R	O/s Cracked	530.00 FL	*265.00 FL
23	2		*REAR TAILLAMP LOWER GARNISH	Deformed	314.00 FL	*314.00 FL
24	2		*REAR TAILLAMP LOWER GARNISH SIDE RETAINER	Not Necessary	106.00 FL	*- FL
25	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
26	1		*REAR TAILGATE 70KM STICKER	Necessary	25.00 FS	*15.00 FS
27	1		*REAR TAILGATE AWC STICKER	Necessary	35.00 FS	*25.00 FS
28	1		*SET REAR TAILGATE INNER TRIM BOARD CLIPS	Not Necessary	50.00 FS	*- FS
29	1		*REAR TAILGATE NUMBER PLATE	Not Necessary	25.00 FS	*- FS
30	1		*REAR TAILGATE NUMBER PLATE HOLDER	Not Necessary	50.00 FS	*- FS
31	1		*SET REAR TAILGATE OUTER HANDLE CLIPS	Necessary	50.00 FS	*10.00 FS
32	1		*SET REAR TAILGATE OUTER HANDLE STICKER	Necessary	100.00 FS	*50.00 FS
33	1		*REAR TAILGATE WINDSCREEN SEALANT	Necessary	80.00 FS	*60.00 FS
34	1		*REAR TAILGATE WINDSCREEN SOLAR FILM	Necessary	200.00 FS	*200.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
35	2		*SET REAR TAILLAMP CLIPS L/R	Necessary	50.00 FS	*10.00 FS
36	1		*SET REAR TAILLAMP LOWER GARNISH CLIPS	Necessary	20.00 FS	*10.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	10,289.70	7,194.80
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,388.68	1,696.20

Total Parts (\$\$)	7,901.02	5,498.60
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE,REINSTALL ELECTRICAL WIRING HARNESS,CHECK LIGHTING AND REWIRE FOR PARKING SENSOR	New	80.00	80.00
2	TO REMOVE,REINSTALL TAILGATE WINDSCREEN	New	150.00	120.00
3	TO REMOVE,REINSTALL ROOF TOP TRIM UPHOLSTERY,CUSHION SEAT,TRIM GARNISH,TRIM LINER CARPET (TO FR)	New	100.00	60.00
4	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS,REPAIR PORTION,AND WHERE CONSISTENT TO THE ACCIDENT	New	900.00	600.00
5	TO PROVIDE LABOUR,WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS,REPAIR,RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE,BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	1,000.00	800.00
6	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	100.00	60.00
7	TO REMOVE/REPLACE TAILGATE FITTINGS	New	80.00	80.00
Gross Labour Cost (\$\$)			2,410.00	1,800.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >