

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20013272/DBA3Q2
Date: 16/02/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No: 1800030385	
Claimant Vehicle No : SMT7951A	Insured Vehicle No : GBH3322K	
Date of Loss: 27/11/2020	Nature of Claim: TP	Claim No: 9138158931SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMT7951A		
Make & Model: MERCEDES-BENZ GLA180, 1.6 (A)	Engine No: 27091031906422	
Reg. Date: 17/07/2020 (Man. Year: 2019)	Chassis No: WDC1569422J656180	
Colour: White	Odometer: 9443 km	
Engine Capacity: 1595 cc		
Market Value/New Car Price: N/A		
Sum Insured (S\$): Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable): Yes	Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes	Engine Modification: No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/45R19	Rear Tyre Size: 235/45R19	
Front Left Side: Bridgestone 5 mm	Rear Left Side: Bridgestone 5 mm	
Front Right Side: Bridgestone 5 mm	Rear Right Side: Bridgestone 5 mm	

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	25,763.70	5,372.96	20,390.74	79.15
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,300.00	1,090.00	3,210.00	74.65
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	30,063.70	6,462.96	23,600.74	78.50
Approved Total (Overridden) (S\$)		5,000.00		
(S\$)	30,063.70	5,000.00	25,063.70	83.37
+ GST 7.00/7.00% (S\$)	2,104.46	350.00	1,754.46	83.37
Nett Amount (S\$)	32,168.16	5,350.00	26,818.16	83.37
+ Car Rental (7.0 x S\$250.00/day) (S\$)		1,750.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		7,107.45		
Global Sum Settlement (S\$)		5,700.00		

INSPECTION

Date of Assignment: 02/12/2020

Date Inspected: 02/12/2020 Inspected At:

JWG International Pte Ltd (HQ)
 Blk 10, Ang Mo Kio Ind Park 2A,, #03-08 AMK
 AutoPoint
 Singapore 568047

2/16/2021

Adjuster Report

Estimated Period of Repair: 3.0 days

Adjuster: BRYAN TANI

Manager: CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Not Necessary	1,987.00 FL	*- FL
2	1		*HEAD LAMP RH	Cut	3,816.00 FL	*3,455.60 FL
3	1		*HEAD LAMP ECU RH	Not Necessary	756.00 FL	*- FL
4	1		*HEAD LAMP PANEL RH	Not Necessary	738.00 FL	*- FL
5	1		*FRONT GRILLE	Not Necessary	417.00 FL	*- FL
6	1		*FRONT GRILLE BASE	Not Necessary	445.00 FL	*- FL
7	1		*FRONT GRILLE LOGO	Not Necessary	152.00 FL	*- FL
8	1		*FRONT BUMPER	Cut / Deformed	2,964.00 FL	*1,381.13 FL
9	2		*FRONT BUMPER SIDE RETAINER LH/RH	Not Necessary	90.00 FL	*- FL
10	1		*FRONT BUMPER LOGO	Not Necessary	171.00 FL	*- FL
11	1		*FRONT BUMPER TOW HOOK COVER	Not Necessary	102.00 FL	*- FL
12	1		*FRONT BUMPER LOWER LID RH	Cut	303.00 FL	*303.00 FL
13	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	303.00 FL	*- FL
14	1		*FRONT BUMPER LOWER LID CENTER	Not Necessary	901.00 FL	*- FL
15	1		*FRONT BUMPER FOG LAMP GARNISH RH	Deformed / Mtg Cracked	164.00 FL	*164.00 FL
16	1		*FRONT BUMPER SENSOR (6 PCS)	O/S Damaged (2 PCS ONLY)	1,932.00 FL	*644.00 FL
17	6		*FRONT BUMPER SENSOR HOLDER	Not Necessary	120.00 FL	*- FL
18	6		*FRONT BUMPER SENSOR O-RING	Not Necessary	60.00 FL	*- FL
19	1		*FRONT BUMPER SENSOR WIRE HARNESS	Not Necessary	1,464.00 FL	*- FL
20	1		*FRONT BUMPER SPONGE	Not Necessary	374.00 FL	*- FL
21	1		*FRONT REINFORCEMENT BAR	Not Necessary	871.00 FL	*- FL
22	1		*FRONT ENGINE UNDER COVER	Not Necessary	411.00 FL	*- FL
23	1		*FRONT SUPPORT PANEL SIDE GARNISH RH	Not Necessary	101.00 FL	*- FL
24	1		*FRONT SUPPORT PANEL SIDE SPONGE RH	Not Necessary	145.00 FL	*- FL
25	1		*FRONT FENDER RH	Not Necessary	1,264.00 FL	*- FL
26	1		*FRONT FENDER ARC GARNISH RH	Not Necessary	338.00 FL	*- FL
27	1		*FRONT FENDER INNER SHIELD RH	Not Necessary	203.00 FL	*- FL
28	1		*FRONT RIM RH	Not Necessary	3,479.00 FL	*- FL
29	1		*FRONT WHEEL BEARING RH	Not Necessary	308.00 FL	*- FL
30	1		*FRONT WHEEL BEARING HUB RH	Not Necessary	308.00 FL	*- FL
31	1		*FRONT LOWER ARM RH	Not Necessary	842.00 FL	*- FL
32	1		*FRONT ABSORBER RH	Not Necessary	1,135.00 FL	*- FL
33	1		*FRONT KNUCKLE ARM RH	Not Necessary	1,129.00 FL	*- FL
34	1		*HEAD LAMP CLIPS	Not Necessary	50.00 FS	*- FS
35	1		*FRONT GRILLE CLIPS	Not Necessary	50.00 FS	*- FS
36	1		*FRONT BUMPER CLIPS	Necessary	50.00 FS	*20.00 FS
37	1		*FRONT BUMPER GRILLE CLIPS	Not Necessary	50.00 FS	*- FS
38	1		*FRONT BUMPER UNDER COVER CLIPS	Not Necessary	50.00 FS	*- FS
39	1		*FRONT FENDER ARC GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
40	1		*FRONT FENDER INNER SHIELD CLIPS	Not Necessary	50.00 FS	*- FS
41	1		*TYRE	Not Necessary	300.00 FS	*- FS
42	1		*FRONT NO PLATE & CASING	Not Necessary	100.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	28,543.00	5,967.73
- List Item Discount on L Items 10.00/10.00% (\$)	2,779.30	594.77
Total Parts (\$)	25,763.70	5,372.96

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	New	1,400.00	500.00
2	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	New	1,400.00	400.00
3	TO TUFF COAT DAMAGED AREAS	New	300.00	0.00
4	TO RNR FRONT BUMPER SENSOR TO FACILITATE REPAIRS	New	150.00	40.00
5	TO RNR FRONT UNDERCARRIAGE TO FACILITATE REPAIRS	New	400.00	0.00
6	TO CONDUCT COMPUTERIZED 4 WHEEL ALIGNMENT	New	150.00	0.00
7	TO CHECK & REFIX ALL ELECTRICAL WIRINGS	New	200.00	0.00
8	TO COMPUTERIZED DIAGNOSE FAULT CODES & CONTROL UNITS ,RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	New	300.00	150.00
Gross Labour Cost (S\$)			4,300.00	1,090.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >