



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKR 2850A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT BUMPER	DEFORMED	495.00	495.00
1	FRONT BUMPER LOWER GRILLE	NOT NECESSARY	147.00	-
1	FRONT BUMPER FOG LAMP RH	CRACKED	320.00	320.00
1	FRONT BUMPER FOG LAMP GARNISH RH	CRACKED	75.00	75.00
2	FRONT BUMPER SIDE RETAINER @\$60.00	O/S NECESSARY	120.00	60.00
1	FRONT BUMPER REINFORCEMENT SPONGE	NOT NECESSARY	123.00	-
1	FRONT CENTER GRILLE	NOT NECESSARY	349.00	-
1	FRONT CENTER GRILLE LOGO	NOT NECESSARY	85.00	-
1	HEADLAMP (LED) RH	CUT	2,849.00	2,223.00
1	HEADLAMP LOWER BRACKET RH	NOT NECESSARY	95.00	-
1	FRONT FENDER RH	NOT NECESSARY	782.00	-
1	FRONT FENDER EMBLEM (VVTI) RH	NOT NECESSARY	55.00	-
1	FRONT FENDER INNER COWLING RH	TORN	210.00	210.00
1	FRONT FENDER UPPER CORNER GARNISH RH	NOT NECESSARY	85.00	-
1	FRONT FENDER SUPPORT BRACKET	NOT NECESSARY	90.00	-
1	FRONT KNUCKLE ARM RH	NOT NECESSARY	585.00	-
1	FRONT LOWER ARM RH	NOT NECESSARY	640.00	-
1	FRONT KNUCKLE ARM BEARING RH	NOT NECESSARY	280.00	-
1	FRONT STABILIZER BAR LINKAGE RH	NOT NECESSARY	195.00	-
1	FRONT SHOCK ABSORBER RH	NOT NECESSARY	405.00	-
1	FRONT ABS SENSOR RH	NOT NECESSARY	460.00	-
1	FRONT WHEEL RIM RH	NOT NECESSARY	1,655.00	-
	LESS 25% DISCOUNT		-2,525.00	-845.75
			7,575.00	2,537.25
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	80.00	30.00
1	SET FRONT BUMPER UNDER COVER GARNISH CLIP (SN)	NOT NECESSARY	50.00	-
1	SET FRONT BUMPER FOG LAMP GARNISH CLIP RH (SN)	NOT NECESSARY	50.00	-
1	SET FRONT CENTER GRILLE CLIP (SN)	NOT NECESSARY	30.00	-
1	SET FRONT FENDER COWLING CLIPS (SN)	NECESSARY	80.00	30.00

Report Ref No. CS/AGI20013273/Avf3q2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET FRONT FENDER UPPER CORNER GARNISH CLIP RH (SN)	NOT NECESSARY	50.00	-
1	BRAKE OIL (SN)	NOT NECESSARY	30.00	-
1	FRONT WHEEL TYRE RH (SN)	NOT NECESSARY	580.00	-
			950.00	60.00
	<b>LABOUR</b>			
	PANEL BEATING,REMOVING AND REPLACING PARTS.		600.00	300.00
	SPRAY PAINTING TO AFFECTED AREA.		600.00	250.00
	TUFF COAT.	NOT NECESSARY	150.00	-
	WIRING CHECK.		80.00	30.00
	REMOVE AND REFIX FRONT UNDERCARRIAGE.	NOT NECESSARY	350.00	-
	FOUR WHEEL ALIGNMENT.	NOT NECESSARY	120.00	-
	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS,RESET MEMORIES TO SPECIFICATION ETC.	NOT NECESSARY	180.00	-
			2,080.00	580.00
<b>GRAND TOTAL</b>			<b>10,605.00</b>	<b>3,177.25</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>2,500.00</b>

Report Ref No. CS/AGI20013273/Avf3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.