

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III20013275/AGS3Q2
Date: 17/08/2021**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant Vehicle No :	SMA6743R	Insured Vehicle No :	SHD6502M
Date of Loss:	01/12/2020	Nature of Claim:	TP
		Claim No:	MCT20120003

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMA6743R	Engine No:	2ZR0B84114
Make & Model:	TOYOTA PRIUS PLUS, 1.8 (A)	Chassis No:	JTDZS3EU90J028095
Reg. Date:	18/06/2018 (Man. Year: 2018)	Odometer:	263851 km
Colour:	Blue		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Habilead 6 mm	Rear Left Side:	Habilead 6 mm
Front Right Side:	Habilead 6 mm	Rear Right Side:	Habilead 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,106.92	2,925.87	1,181.05	28.76
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,680.00	1,280.00	1,400.00	52.24
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,786.92	4,205.87	2,581.05	38.03
Approved Total (Overridden) (S\$)		3,300.00		

(S\$)	6,786.92	3,300.00	3,486.92	51.38
+ GST 7.00/7.00% (S\$)	475.08	231.00	244.08	51.38
Nett Amount (S\$)	7,262.00	3,531.00	3,731.00	51.38
+ Loss of Use (6.0 x S\$57.95/day) (S\$)		347.70		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		3,886.15		

INSPECTION

Date of Assignment: 02/12/2020

Date Inspected: 03/12/2020

Inspected At:

N-51 Automotive Pte Ltd (HQ)
 BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB
 Singapore 417921

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 03 Jun 2021)
Parts:	M1-MPV	TOYOTA PRIUS PLUS 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMA6743R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT RH DOOR	Dented	1,300.90 FL	*1,300.90 FL
2	1		*FRONT RH DOOR FRAME BLACK STICKER	Necessary	48.00 FL	*48.00 FL
3	1		*FRONT RH DOOR GLASS	Cut	546.40 FL	*546.40 FL
4	1		*FRONT RH DOOR GLASS CHANEL	Cut	130.30 FL	*130.30 FL
5	1		*FRONT RH DOOR INNER PLASTIC SEAL COVER	Not Necessary	41.40 FL	*- FL
6	1		*FRONT RH DOOR OUTER MOULDING	Cut	92.00 FL	*92.00 FL
7	1		*FRONT RH DOOR PILLAR	Repair	381.10 FL	*- FL
8	1		*FRONT RH DOOR SIDE MIRROR	Damaged	1,294.40 FL	*992.00 FL
9	1		*FRONT RH DOOR SIDE MIRROR COVER	Cracked	131.40 FL	*131.40 FL
10	1		*FRONT RH DOOR VERTICAL GARNISH	Not Necessary	75.40 FL	*- FL
11	1		*FRONT RH DOOR WEATHERSTRIP	Not Necessary	180.70 FL	*- FL
12	1		*FRONT RH FENDER HYBRID EMBLEM	Necessary	54.60 FL	*54.60 FL
13	1		*FRONT RH QUARTER GLASS ASSY	Cut	390.00 FL	*390.00 FL
14	1		*FRONT WINDSCREEN GLASS MOULDING	Not Necessary	60.40 FL	*- FL
15	1		*FRONT WINDSCREEN GLASS SEAL	Necessary	28.90 FL	*28.90 FL
16	1		*SET FRONT RH DOOR TRIM BOARD CLIP	Not Necessary	50.00 FS	*- FS
17	1		*FRONT RH FENDER MICHELIN STICKER	Necessary	100.00 FS	*40.00 FS
18	1		*FRONT RH QUARTER GLASS ARTWORK STICKER	Necessary	250.00 FS	*70.00 FS
19	1		*FRONT RH QUARTER GLASS SEALANT	Necessary	60.00 FS	*30.00 FS
20	1		*FRONT WINDSCREEN GLASS MOULDY SEALANT	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,295.90	3,854.50
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,188.98	928.63
Total Parts (\$\$)	4,106.92	2,925.87

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO RESET SYSTEM AFTER REPAIR WORKS	New	200.00	0.00
2	TO REMOVE ,REINSTALL WINDSCREEN (TO FR)	New	120.00	0.00
3	TO REMOVE ,REINSTALL FENDER GLASS	New	100.00	60.00
4	TO REMOVE ,REINSTALL ROOF TOP TRIM UPHOLSTERY ,CUSHION SEAT ,TRIM GARNISH ,TRIM LINER CARPET (TO FR)	New	120.00	40.00
5	TO TRANSFER DOOR GLASS ,REGULATOR GEAR ,MOTOR ,RAILING ,CHANNEL ,TRIM BOARD ,MECHANISM LOCK AND HANDLE	New	100.00	80.00
6	TO REMOVE ,REINSTALL DASHBOARD FASCIA ,METER READING AND ETC (TO FR)	New	250.00	0.00
7	TO RE-SPRAY PAINTING ON THE CHARGE BODYPARTS ,REPAIR PORTION ,AND WHERE CONSISTENT TO THE ACCIDENT	New	950.00	600.00
8	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	40.00	0.00
9	TO PROVIDE LABOUR ,WORKMANSHIP TO CHARGE THE ABOVE DAMAGED BODYPARTS ,REPAIR ,RECONSTRUCT AND REALIGN BODY STRUCTURE ,BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	800.00	500.00
Gross Labour Cost (\$\$)			2,680.00	1,280.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >