

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CS/AIG20013283/KVD3E2

Date: 08/01/2021

REFERENCE

Insured/Claimant: DAIMLER FLEET MANAGEMENT SINGAPORE PTE.LTD.

Policy No: 0999993933

Date of Loss: 27/11/2020

Nature of Claim: OD

Claim No: 5177791192SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKP4011C	Engine No:	2ARU158723
Make & Model:	TOYOTA CAMRY, 2.0 (A)	Chassis No:	MR053AK5004008066
Reg. Date:	05/09/2014 (Man. Year: 2014)	Odometer:	60793 km
Colour:	Metallic Green		
Engine Capacity:	2494 cc		
Market Value/New Car Price:	S\$56,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Yokohama 8 mm	Rear Left Side:	Yokohama 8 mm
Front Right Side:	Yokohama 8 mm	Rear Right Side:	Yokohama 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,857.70	2,601.10	1,256.60	32.57
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,330.00	1,070.00	1,260.00	54.08
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,187.70	3,671.10	2,516.60	40.67
- Excess (S\$)	1,500.00	1,500.00	0.00	0.00
(S\$)	4,687.70	2,171.10	2,516.60	53.69
+ GST 7.00/7.00% (S\$)	328.14	151.98	176.16	53.68
Nett Amount (S\$)	5,015.84	2,323.08	2,692.76	53.69

INSPECTION

Date of Assignment: 03/12/2020

Date Inspected: 03/12/2020 Inspected At:

Tong Luck Auto Pte Ltd (HQ)
160 Sin Ming Drive, #07-01 Sin Ming AutoCity
Singapore 575722

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET (WCP)1	Bent	550.00 F	*550.00 F
2	1		*BONNET CHROME (WCP)	Serviceable	115.00 F	*- F
3	2		*BONNET HINGES - LH / RH (WCP)	Repair	110.00 F	*- F
4	1		*BONNET INSULATOR CLIPS (15PCS) (WCP)	Necessary	82.50 FS	*50.00 FS
5	1		*SUPPORT PANEL (WCP)	Repair	320.00 F	*- F
6	1		*SUPPORT PANEL TOP GARNISH (WCP)	Cracked	155.00 F	*155.00 F
7	8		*SUPPORT PANEL TOP GARNISH CLIPS (WCP)	Necessary	44.00 FS	*20.00 FS
8	1		*HEADLAMP ASSY - LH (WCP)	Cracked	550.00 F	*550.00 F
9	1		*HEADLAMP BRACKET - LH (WCP)	Repair	58.00 F	*- F
10	1		*FRONT FENDER - LH (WCP)	Repair	300.00 F	*- F
11	1		*FRONT BUMPER (WCP)	Bent	320.00 F	*320.00 F
12	1		*FRONT BUMPER REINFORCEMENT (WCP)	Bent	170.00 F	*170.00 F
13	1		*FRONT BUMPER BRACKET - LH (WCP)	Repair	68.00 F	*- F
14	1		*FRONT BUMPER SIDE RETAINER - LH (WCP)	Distorted	48.00 F	*48.00 F
15	1		*FRONT BUMPER FOG LAMP - LH (WCP)	Broken	135.00 F	*135.00 F
16	1		*FRONT BUMPER FOG LAMP CHROME - LH (WCP)	Missing	65.00 F	*65.00 F
17	1		*FRONT BUMPER CENTRE GRILLE (WCP)	Serviceable	120.00 F	*- F
18	1		*FRONT BUMPER SENSOR (WCP)	Shorted	200.00 F	*200.00 F
19	1		*FRONT BUMPER SENSOR COVER (WCP)	Necessary	28.00 F	*28.00 F
20	1		*FRONT BUMPER SPONGE (WCP)	Cracked	80.00 F	*80.00 F

F=Franchise part. S=SpcNett.

Sub Total (\$\$)	3,518.50	2,371.00
+ Margin on L,N Items 10.00/10.00% (\$\$)	339.20	230.10
Total Parts (\$\$)	3,857.70	2,601.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REFIT AIR-CON CONDENSER, RADIATOR AND REFILL AIR-CON GAS	New	150.00	0.00
2	TO CHECK AND RECTIFY WIRING SYSTEM	New	80.00	20.00
3	TO PANEL BEAT AND STRAIGHTEN LH FRONT FENDER, INCLUDING REPLACEMENT OF PARTS AND ALIGN WHERE NECESSARY, TO REFIT AND ADJUST THE SAME	New	1,000.00	400.00
4	TO PUTTY AND SPRAY PAINT ON AFFECTED AREAS	New	1,000.00	600.00
5	TO REMOVE AND REFIT FRONT BUMPER SENSOR	New	100.00	50.00
Gross Labour Cost (\$\$)			2,330.00	1,070.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >