



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2203532

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 09/06/2022
Reference CC6/CTI20013290/Dea3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SHC 3693U
Insured Veh. SJP 6468S
Claim No. SNM20D204830/C02
Policy No. DMPCSNW00158412000
Accident Date 01/12/2020
Inspection Date 16/12/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC6/CTI20013290/Dea3q2 Date: 09/06/2022 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJP 6468S	Veh. Inspected	SHC 3693U	
Policy No.	DMPCSNW00158412000	Coverage (\$)	0.00	
Claim No.	SNM20D204830/C02	Excess (\$)	0.00	
Assign From		Assign Date	16/12/2020	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI IONIQ	c.c	1580	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	KMHC851CVJU103533	Colour	BLUE	
Odometer	393424 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	DURATURN	5 mm	
L/H Front Tyre	195/65 R15	DURATURN	5 mm	
R/H Rear Tyre	195/65 R15	DURATURN	5 mm	
L/H Rear Tyre	195/65 R15	DURATURN	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	01/12/2020	Inspection Date	16/12/2020	
Survey held at	BIFROST AUTO PTE LTD 8 KAKI BUKIT AVENUE 4 #01-49 PREMIER @ KAKI BUKIT SINGAPORE 415875			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			8 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 3693U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BONNET	BENT	2,253.80	2,253.80
1	BONNET LOCK	NOT NECESSARY	127.30	-
1	RADIATOR GRILLE	MTG CRACKED	1,409.10	1,409.10
2	FLAP ASSY ACTIVE AIR UPPER (LH/RH) @\$824.60	NOT NECESSARY	1,649.20	-
1	FRONT NUMBER PLATE GARNISH	NOT NECESSARY	188.00	-
1	FRONT BUMPER COVER	TORN	418.30	418.30
1	FRONT BUMPER TOP COVER	NOT NECESSARY	476.30	-
1	FRONT BUMPER SPONGE	NOT NECESSARY	186.90	-
1	FRONT BUMPER SPONGE /ABSORBER	NOT NECESSARY	96.90	-
1	FRONT BUMPER REINFORCEMENT	BENT / CRACKED	1,075.10	1,075.10
2	FRONT BUMPER REINFORCEMENT ABSORBER (LH/RH) @\$186.50	NOT NECESSARY	373.00	-
1	FRONT BUMPER TOWING COVER	SERVICEABLE	29.00	-
1	FRONT BUMPER MOULDING CENTRE UPPER	SCRATCHED	368.50	368.50
1	FRONT BUMPER MOULDING	NOT NECESSARY	93.60	-
1	FRONT BUMPER LOWER STIFFNER	BENT / CRACKED	285.10	285.10
1	FRONT BUMPER LOWER GRILLE	DEFORMED	365.30	365.30
1	FRONT BUMPER LOWER GRILLE MOULDING	BENT	127.60	127.60
1	FRONT BUMPER LIP	NOT NECESSARY	35.10	-
2	FRONT BUMPER BRACKET TOP (LH/RH) @\$35.00	NOT NECESSARY	70.00	-
2	FRONT BUMPER BRACKET (LH/RH) @\$28.00	NOT NECESSARY	56.00	-
2	FRONT BUMPER SIDE BRACKET SUPPORT @\$12.00	NOT NECESSARY	24.00	-
2	FRONT BUMPER RETAINER MOUNTING (LH/RH) @\$65.30	NOT NECESSARY	130.60	-
10	FRONT BUMPER CLIPS	NECESSARY	25.00	25.00
2	FRONT BUMPER GRILLE (LH/RH) @\$186.90	O/S CRACKED / N/S NOT NECESSARY	373.80	186.90
2	FRONT BUMPER AIR DUCT (LH/RH) @\$153.80	NOT NECESSARY	307.60	-
1	DAY LIGHT ,RH	MTG BROKEN	642.50	642.50
1	DAY LIGHT WIRE ,RH	NOT NECESSARY	585.50	-
1	HEADLAMP SUPPORT PANEL ASSY	BROKEN	949.30	949.30
1	HEADLAMP (RH)	CRACKED	3,987.30	1,198.80

Report Ref No. CC6/CTI20013290/Dea3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	RADIATOR INVERTER	BENT	884.80	884.80
1	RADIATOR	BENT	710.50	710.50
1	RADIATOR FAN BLOWER MOTOR ASSY	BROKEN	1,226.60	1,226.60
2	RADIATOR AIR GUARD (LH/RH) @\$76.40	O/S DEFORMED / N/S NOT NECESSARY	152.80	76.40
2	RADIATOR AIR GUARD,UPR (LH/RH) @\$127.50	NOT NECESSARY	255.00	-
1	RADIATOR HOSE LOWER	NOT NECESSARY	156.20	-
1	FRONT FENDER (RH)	DENTED	490.70	490.70
1	FRONT FENDER SHIELD (RH)	TORN	164.70	164.70
1	AIRCON CONDENSER	BENT	663.60	663.60
1	WIPER CONTAINER ASSY	CRACKED	385.40	385.40
1	ENGINE UNDER COVER	DEFORMED / TORN	469.40	469.40
1	ENGINE CROSSMEMBER	BENT	1,803.90	1,803.90
1	AUTO GEAR OIL	NOT NECESSARY	163.70	-
1	ELECTRONIC CLUTCH PUMP	MOUNTING BROKEN	4,386.50	4,386.50
1	WIRING-ENGINE	NOT NECESSARY	3,474.00	-
1	UNIT ASSY-SMART CRU (RADAR SENSOR)(ADDITIONAL)	MOUNTING BROKEN	2,910.90	2,910.90
1	FRONT SUSPENSION LOWER ARM RH (ADDITIONAL)	BENT	596.80	596.80
1	CENTER UNDER COVER SIDE RH (ADDITIONAL)	TORN	638.90	638.90
1	SPEAKER ASSY-VESS (ADDITIONAL)	CRACKED	354.40	354.40
1	HORN RH (ADDITIONAL)	SERVICEABLE	72.80	-
	LESS 20% DISCOUNT		-7,334.26	-5,013.76
			29,337.04	20,055.04
1	EMBLEM-BLUE DRIVE (RH)	NECESSARY	26.60	26.60
			26.60	26.60
	LESS 20% DISCOUNT		-	-5.32
			-	-5.32

Report Ref No. CC6/CTI20013290/Dea3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT NUMBER PLATE (SN)	CRACKED	25.00	25.00
1	FRONT NO PLATE TRIM COVER (SN)	NOT NECESSARY	30.00	-
1	COOLANT (SN)	NOT NECESSARY	45.00	-
			100.00	25.00
	<u>LABOUR</u>			
	PANEL BEATING.		1,400.00	800.00
	SPRAY PAINTING CHARGE.		1,000.00	700.00
	WIRING CHARGE.		120.00	30.00
	TUFF KOTE.		120.00	40.00
	TOWING CHARGE.	NOT NECESSARY	80.00	-
	FOUR WHEEL ALIGNMENT.		120.00	60.00
	REMOVE/REFIX RADIATOR.		90.00	50.00
	REMOVE/REFIX AIRCON & REFILL GAS.		130.00	80.00
	REMOVE/REFIX FUSE BOX.	NOT NECESSARY	120.00	-
	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE.		550.00	180.00
	REMOVE & REFIX FRONT SUSPENSION & CROSS MEMBER (ADDITIONAL).		600.00	120.00
			4,330.00	2,060.00
GRAND TOTAL			33,793.64	22,161.32

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			18,800.00
---	--	--	------------------

Report Ref No. CC6/CTI20013290/Dea3q2

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHC 3693U

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd


51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHC 3693U

RE-INSPECTION








LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHC 3693U

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

