

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315





ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SH 6349M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	TO REPAIR SEE LABOUR	459.40	-
1	REAR BUMPER CENTRE MOULDING	DEFORMED	451.25	451.25
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	394.80	-
2	REAR BUMPER STAY LH / RH @\$138.10	NOT NECESSARY	276.20	-
10	REAR BUMPER CLIPS @\$2.20	NECESSARY	22.00	22.00
1	REAR BUMPER FOG LAMP	NOT NECESSARY	201.50	-
2	REAR NUMBER PLATE LAMP LH / RH @\$85.30	NOT NECESSARY	170.60	-
2	REAR BUMPER BRACKET LH / RH @\$55.80	NOT NECESSARY	111.60	-
	LESS 20% DISCOUNT		-417.47	-94.65
			1,669.88	378.60
	NETT ITEMS			
1	REAR NUMBER PLATE W/HOLDER (N)	CRACKED	55.00	55.00
1	REAR REVERSE SENSOR (N)	NOT WORKING	180.00	180.00
	LESS 10% DISCOUNT		-23.50	-23.50
			211.50	211.50
	<u>LABOUR</u>			
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF REAR BUMPER.		640.00	320.00
	SPRAY PAINTING CHARGE.		500.00	200.00
	TUFF KOTE.	NOT NECESSARY	60.00	-
	REMOVE / REFIX REVERSE SENSOR.		60.00	30.00
			1,260.00	550.00
	GRAND TOTAL		3,141.38	1,140.10

RECOMMENDED COST OF REPAIRS (CONFIRMED)		1,140.10
---	--	----------

Report Ref No. NS/INC20013291/T1vd3e2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.