

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 1297D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	IONIQVC COVER-RR BUMPER	DEFORMED	459.40	459.40
10	HYUNDAI BUMPER COVER CLIP	NECESSARY	22.00	22.00
1	MOULDING ASSY-RR BUMPER C	DEFORMED	451.25	451.25
1	IONIQVC EMBLEM-HYBRID	NECESSARY	24.30	24.30
1	IONIQVC EMBLEM-IONIQ	NECESSARY	31.30	31.30
	LESS 20% DISCOUNT		-197.65	-197.65
			790.60	790.60
	NETT ITEMS			
1	HYUNDAI REVERSE SENSOR AS (N)	NOT WORKING	180.00	180.00
1	NO PLATE (S) WITH TRIM COV (N)	CRACKED	55.00	55.00
1	(I40) REAR BOOT LOGO CTPL (N)	NECESSARY	30.00	30.00
1	(I40) REAR BOOT TEL NUMBER (N)	NECESSARY	30.00	30.00
	LESS 10% DISCOUNT		-29.50	-29.50
			265.50	265.50
	<u>LABOUR</u>			
	TOWING FEE.		60.00	-
	PANEL BEATING.		500.00	320.00
	SPRAYPAINT ON AFFECTED AREA.		450.00	400.00
	REMOVE/REFIX REVERSE SENSOR.		120.00	30.00
			1,130.00	750.00
	GRAND TOTAL		2,186.10	1,806.10

RECOMMENDED COST OF REPAIRS (CONFIRMED			1,806.10
--	--	--	----------

Report Ref No. NS/INC20013292/T1qd3q2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.