

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SH 7806D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	CRACKED	459.40	459.40
1	REAR BUMPER CENTRE MOULDING	NOT NECESSARY	451.25	-
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	394.80	-
2	REAR BUMPER STAY LH / RH @\$138.10	NOT NECESSARY	276.20	-
10	REAR BUMPER CLIPS @\$2.20	NECESSARY	22.00	20.00
1	REAR BUMPER FOG LAMP	NOT NECESSARY	201.50	-
1	REAR RH BLIND SPOT RADAR	NOT NECESSARY	1,625.00	-
2	REAR NUMBER PLATE LAMP LH / RH @\$85.30	NOT NECESSARY	170.60	-
2	REAR BUMPER BRACKET LH / RH @\$55.80	N/S NOT NECESSARY / O/S NECESSARY	111.60	55.80
	LESS 20% DISCOUNT		-742.47	-107.04
			2,969.88	428.16
	NETT ITEMS			
1	REAR NUMBER PLATE W/HOLDER (N)	NOT NECESSARY	55.00	-
1	REAR REVERSE SENSOR (N)	NOT NECESSARY	180.00	-
	LESS 10% DISCOUNT		-23.50	-
			211.50	-
	SPECIAL NETT ITEMS			
1	REAR BUMPER MAT (SN)	NECESSARY	50.00	50.00
			50.00	50.00
	<u>LABOUR</u>			
	PANEL BEATING.		640.00	320.00
	SPRAY PAINTING CHARGE.		500.00	200.00
	TUFF KOTE.	NOT NECESSARY	60.00	-
	DIAGNOSE / RESET ERROR CODE.	NOT NECESSARY	300.00	-
	REMOVE / REFIX REVERSE SENSOR.		60.00	30.00
			1,560.00	550.00
	GRAND TOTAL		4,791.38	1,028.16

Report Ref No. NS/INC20013294/T1qf3e2





Page No.:2 of 2

RECOMMENDED COST OF REPAIRS (CONFIRMED)		1,028.16
---	--	----------

Report Ref No. NS/INC20013294/T1qf3e2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser