

REPAIR ESTIMATE*

VEHICLE NO SH 7806D

02/12/20

MAKE :

MODEL IONIQ G2

CHIANG/NTUC

| Qty | Parts Description/ Labour | Type | Unit Price | Amount |
|-----|------------------------------|--------|------------|-------------------|
| 1 | REAR BUMPER | | | \$459.40 |
| 1 | REAR BUMPER CENTRE MOULDING | | | \$451.25 |
| 1 | REAR BUMPER REINFORCEMENT | | | \$394.80 |
| 1 | REAR BUMPER STAY LH /RH | | \$138.10 | \$276.20 |
| 10 | REAR BUMPER CLIPS | | \$2.00 | 20 \$22.00 |
| 1 | REAR BUMPER FOG LAMP | | | \$201.50 |
| 1 | REAR RH BLIND SPOT RADAR | | | \$1,625.00 |
| 1 | REAR NUMBER PLATE LAMP LH/RH | | \$85.30 | \$170.60 |
| 1 | REAR BUMPER BRACKET RH/ LH | | \$55.80 | \$111.60 |
| | | | | \$3,712.35 |
| | | 20.00% | 535.20 | \$742.47 |
| | DISCOUNTED TOTAL | | 428.76 | \$2,969.88 |
| 1 | REAR BUMPER MAT | | | \$50.00 |
| 1 | REAR NUMBER PLATE W/HOLDER | | | \$55.00 |
| 1 | REAR REVERSE SENSOR | | | \$180.00 |
| | | 10.00% | 50 | \$261.50 |
| | Labour Charge | | | |
| | Panel Beating | | | \$640.00 |
| | Spray Painting Charge | | | \$500.00 |
| | Tuff Kote | | | \$60.00 |
| | Diagnose/ reset error code | | | \$300.00 |
| | Remove/Refix reverse sensor | | | \$60.00 |
| | TOTAL LABOUR | | 550 | \$1,560.00 |
| | ESTIMATE TOTAL | | \$1028.16 | \$4,791.38 |
| | | | 2 days | |

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tanphir 97495749 Davanti
 WP 2/12/20 C/pu
 2 days
 p/p Resurvey before paint
 tanphir@lkkauto.com

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: