

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG20013297/AGVF3E2**Date:** 03/01/2022REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	80481738QMX
Claimant Vehicle No :	SLZ6278Y	Insured Vehicle No :	SKW3604L
Date of Loss:	28/11/2020	Nature of Claim:	TP
		Claim No:	631594

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLZ6278Y	Engine No:	1ZZ3107147
Make & Model:	TOYOTA WISH, 1.8 X (A)	Chassis No:	ZNE100410590
Reg. Date:	26/06/2008 (Man. Year: 2008)	Odometer:	365112 km
Colour:	Silver		
Engine Capacity:	1794 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,210.47	3,022.25	11,188.22	78.73
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,500.00	1,860.00	2,640.00	58.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	18,710.47	4,882.25	13,828.22	73.91
Approved Total (Overridden) (S\$)		3,700.00		
Nett Amount (S\$)	18,710.47	3,700.00	15,010.47	80.22

INSPECTION

Date of Assignment:	03/12/2020	1st Auto Pro Pte Ltd - 8 Kaki Bukit (HQ) 8 Kaki Bukit Avenue 4, #01-51/52 PREMIER @ KAKI BUKIT Singapore 415875
Date Inspected:	03/12/2020 Inspected At:	
Estimated Period of Repair:	6.0 days	

Adjuster: XING GUO QIANG**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 03 Jan 2022)
Parts:	M1-MPV	TOYOTA WISH 1.8 X (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLZ6278Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAIL GATE	Dented	1,846.00 FL	*1,217.00 FL
2	1		*REAR TAILGATE LOCK	Damaged	220.00 FL	*220.00 FL
3	1		*REAR TAILGATE KEY CATCH	Not Necessary	154.00 FL	*- FL
4	1		*REAR TAILGATE LOGO	Necessary	194.00 FL	*65.00 FL
5	1		*REAR TAILGATE WISH CHROME PANEL	Not Necessary	356.00 FL	*- FL
6	1		*REAR TAILGATE GARNISH	Not Necessary	178.00 FL	*- FL
7	1		*REAR TAILGATE INNER GARNISH	Cracked	194.00 FL	*194.00 FL
8	2		*REAR TAILGATE HINGE LH / RH	Not Necessary	724.00 FL	*- FL
9	1		*REAR TAILGATE WEATHERSTRIP	Cut	439.10 FL	*288.00 FL
10	1		*REAR TAILGATE GLASS MOULDING	Necessary	355.30 FL	*140.00 FL
11	1		*REAR NUMBER PLATE LAMPS	Not Necessary	184.00 FL	*- FL
12	1		*REAR WIPER MOTOR	Not Necessary	450.00 FL	*- FL
13	1		*REAR WIPER	Not Necessary	164.00 FL	*- FL
14	2		*REAR TAILLAMPS LH / RH	Not Necessary	2,648.00 FL	*- FL
15	2		*REAR TAILLAMPS PANELS LH / RH	Repair	388.00 FL	*- FL
16	1		*REAR END PANEL	Dented	903.00 FL	*590.00 FL
17	1		*REAR END PANEL INNER GARNISH	Cracked	310.00 FL	*213.00 FL
18	1		*REAR BUMPER	Deformed	998.00 FL	*495.00 FL
19	1		*REAR BUMPER INNER SPONGE	Not Necessary	241.00 FL	*- FL
20	1		*REAR BUMPER REFLECTORS LH / RH	N/S Cracked	480.00 FL	*83.00 FL
21	2		*REAR BUMPER SIDE RETAINERS LH / RH	Necessary	368.00 FL	*110.00 FL
22	1		*REAR BUMPER BRACKET LH / RH	N/S Dented	480.40 FL	*68.00 FL
23	1		*REAR BUMPER TOP HOLDERS	Not Necessary	230.00 FL	*- FL
24	1		*REAR SPARE TYRE TOP BOARD	Not Necessary	396.20 FL	*- FL
25	1		*REAR FLOOR PANEL	Repair	689.30 FL	*- FL
26	1		*REAR EXHAUST SILENCER	Repair	1,096.00 FL	*- FL
27	1		*REAR EXHAUST SILENCER MOUNTINGS	Not Necessary	184.00 FL	*- FL
28	2		*REAR FENDERS LH / RH	Not Necessary	1,587.00 FL	*- FL
29	2		*REAR FENDER INNER SHIELD	Not Necessary	290.00 FL	*- FL
30	2		*REAR FENDER INNER TRIMS	Not Necessary	680.00 FL	*- FL
31	2		*SET REAR FENDER INNER TRIM CLIPS	Not Necessary	100.00 FS	*- FS
32	1		*SET REAR REVERSE CAMERA	Not Necessary	490.00 FS	*- FS
33	1		*REAR NUMBER PLATE WITH HOLDER	Not Necessary	100.00 FS	*- FS
34	1		*SET REVERSE SENSORS	Damaged	350.00 FS	*200.00 FS
35	1		*REAR WINDSCREEN SEALANT	Necessary	100.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	18,567.30	3,943.00
- List Item Discount on L Items 25.00/25.00% (\$\$)	4,356.83	920.75
Total Parts (\$\$)	14,210.47	3,022.25

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REFIT ELECTRICAL WIRING, REPLACE DAMAGED LAMPS AND TEST FOR PROPER FUNCTIONING REAR	New	150.00	30.00
2	TO REMOVE AND REFIT SPARE TYRE PANEL TO FACILITATE THE REPAIR	New	150.00	0.00
3	TO TRANSFER WINDSCREEN FROM OLD TAILGATE TO NEW	New	200.00	120.00
4	TO REMOVE, REFIT AND TEST REVERSE SENSOR	New	200.00	50.00
5	TO REMOVE, STRAIGHTEN AND REFIT EXHAUST	New	150.00	0.00
6	PANEL BEATING ON AFFECTED AREA	New	2,000.00	800.00
7	SPRAY PAINTING	New	1,500.00	800.00
8	APPLY ANTI RUST ON AFFECTED AREA	New	150.00	60.00
Gross Labour Cost (\$\$)			4,500.00	1,860.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >